

**Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities**

Letting: 03250410 Call Order: 006 Proposal: E3Y62-R0 District:03
 Counties: HOLMES, WALTON, WASHINGTON
 Road Name: PONCE DE LEON OPS MAINT - GUARDRAIL MAINTENANCE
 Limits: Midpoint
 Project(s): 42214337257(*) Federal Aid No: N/A
 Total Roadway Length: 0.000 Miles Contract Days: THRU 6/30/26
 Total Bridge Length: 0.000 Miles Letting Date: 04/10/25
 Total Proposal Length: 0.000 Miles Contract Execution Days: 10
 Special Start Date: N/A
 Aquis/Flexible Start Time: 15 DAYS

Proposal Budget Estimate: \$250,000.00

Please read the full advertisement

Description:

The Improvements under this Work Document-Driven Contract consist of the repair and/or replacement of damaged guardrail and crash cushions along state-maintained roadways in Holmes, Walton, and a portion of Washington Counties. Removal and disposal of all debris from installation of damaged guardrail will be the responsibility of the Contractor. Mobilization and Maintenance of Traffic are incidental to the pay items listed in the contract. This contract has a budgetary estimate of \$250,000.00.

Needs The quantities shown on the Bid Price Proposal are approximate and only represent estimated planned requirements based on historical or specific project needs. The Department does not guarantee any maximum or minimum quantity, any range of quantities, or the exact quantities shown for each bid item. The Department estimated quantities and the Contractors bid price will be used to calculate a total bid amount. This total bid amount will then be used to determine the low bidder, however, actual payment under the awarded contract will be based on actual quantities completed. For this Contract in which specific sites are not identified at the time of letting, the Engineer will issue a Work Document. Work Documents will identify the location, description, amount of work to be accomplished, and the number of calendar days to complete the work.

Call Order: 006 Proposal: E3Y62-R0

ALT	Item	Description	Unit	Quantity
Section 0001 ASPHALT REPAIR (MANUAL) (TN)				
	0120- 2- 2	BORROW EXCAVATION, TRUCK MEASURE	CY	10.000
	0339- 1-	MISCELLANEOUS ASPHALT PAVEMENT	TN	50.000
	0515- 1- 1	PIPE HANDRAIL - GUIDERAIL, STEEL	LF	42.000
	0515- 1- 2	PIPE HANDRAIL - GUIDERAIL, ALUMINUM	LF	42.000
	0515- 1- 41	PIPE HANDRAIL - GUIDERAIL, RELOCATE, STEEL	LF	42.000
	0515- 1- 42	PIPE HANDRAIL - GUIDERAIL, RELOCATE, ALUMINUM	LF	42.000
	0515- 2-211	PEDESTRIAN / BICYCLE RAILING, STEEL, 42" TYPE 1	LF	42.000
	0515- 2-311	PEDESTRIAN/ BICYCLE RAILING, ALUMINUM ONLY,42" TYPE 1	LF	42.000
	0515- 2-500	PEDESTRIAN / BICYCLE RAILING, RELOCATE	LF	42.000
	0515- 3- 1	PIPE HANDRAIL- RETROFIT TO EXISTING RAILING, STEEL	LF	42.000
	0515- 3- 2	PIPE HANDRAIL- RETROFIT TO EXISTING RAILING, ALUMINUM	LF	42.000
	0536- 1- 1	GUARDRAIL -ROADWAY, GENERAL TL-3	LF	3,000.000
	0536- 1- 3	GUARDRAIL- ROADWAY, DOUBLE FACE	LF	500.000
	0536- 5- 1	RUB RAIL FOR GUARDRAIL, SINGLE SIDED RUB RAIL	LF	100.000
	0536- 6-	PIPE RAIL FOR GUARDRAIL	LF	50.000
	0536- 7- 1	SPECIAL GUARDRAIL POST- DEEP POST FOR SLOPE BREAK CONDITION- TIMBER OR STEEL	EA	2.000

Call Order: 006 Proposal: E3Y62-R0

ALT	Item	Description	Unit	Quantity
	0536- 7- 2	SPECIAL GUARDRAIL POST- SPECIAL STEEL POST FOR CONCRETE STRUCTURE MOUNT	EA	2.000
	0536- 7- 3	SPECIAL GUARDRAIL POST- ENCASED POST FOR SHALLOW MOUNT	EA	2.000
	0536- 7- 4	SPECIAL GUARDRAIL POST- FRANGIBLE LEAVE-OUT FOR MOUNTING THROUGH CONCRETE SURFACE	EA	2.000
	0536- 73-	GUARDRAIL REMOVAL	LF	100.000
	0536- 85- 24	GUARDRAIL END TREATMENT- PARALLEL APPROACH TERMINAL	EA	1.000
	0536- 85- 26	GUARDRAIL END TREATMENT- TYPE CRT	EA	1.000
	0536- 85- 27	GUARDRAIL END TREATMENT- DOUBLE FACE APPROACH TERMINAL	EA	1.000
	0538- 1-	GUARDRAIL RESET	LF	100.000
	0544- 2- 1	CRASH CUSHION, TL-2, NARROW	EA	1.000
	0544- 3- 1	CRASH CUSHION, TL-3, NARROW	EA	1.000
	0705- 11- 6	DELINEATOR, REPLACE DELINEATOR ON EXISTING BARRIER	EA	100.000
	E101- 72-	MOBILIZATION (EMERGENCY RESPONSE)	EA	10.000
	E536- 3-141	GUARDRAIL STANDARD PANEL (REPLACE) (SHOP BENT)	LF	50.000
	E536- 3-242	GUARDRAIL THRIE BEAM (REPLACE) (0' - 50')	LF	1.000
	E536- 5- 1	THRIE BEAM (TERMINAL CONNECTOR)	EA	1.000
	E536- 5- 2	THRIE BEAM (RAIL SPLICE)	EA	1.000
	E536- 5- 3	THRIE BEAM (TRANSITION SECTION)	EA	1.000
	E536- 5- 4	THRIE BEAM (MODIFIED OFFSET BLOCK)	EA	1.000
	E536- 6- 45	END ANCHORAGE ASSEM (REPLACE) (TYPE ET 2000)	EA	1.000
	E536- 6- 46	END ANCHORAGE ASSEM (REPLACE) (BRIDGE)	EA	1.000
	E536- 6- 47	END ANCHORAGE ASSEM (REPLACE) (BARRIER WALL)	EA	1.000
	E536- 6- 48	END ANCHORAGE ASSEM (REPLACE) (TYPE SRT-350)	EA	1.000
	E536- 6-412	END ANCHORAGE ASSEM (REPLACE) (TYPE MELT)	EA	1.000
	E536- 6-414	END ANCHORAGE ASSEM (REPLACE) (TYPE SRT-350/8)	EA	1.000
	E536- 6-423	GUARDRAIL END TREATMENT-FLARED APPROACH TERMINAL, REPLACE, NCHRP 350	EA	1.000
	E536- 6-424	END ANCHORAGE ASSEM (REPLACE) (PARALLEL)	EA	1.000
	E536- 6-425	GUARDRAIL END TREATMENT-FLARED APPROACH TERMINAL, REPLACE, MASH	EA	1.000
	E536- 12-604	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN CONC.)	EA	2.000
	E536- 12-605	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN ASPH.)	EA	10.000
	E536- 12-606	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN SOIL)	EA	2.000
	E536- 12-608	GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN ASPH.)	EA	10.000
	E536- 12-609	GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN SOIL)	EA	2.000
	E536- 12-615	GUARDRAIL REPAIRS (REPLACE) (FILLER BLOCKS)	EA	5.000
	E536- 12-616	GUARDRAIL REPAIRS(REPLACE)(OFFSET BLOCK)	EA	10.000
	E536- 12-619	GUARDRAIL REPAIRS (REPLACE) (THRIE-BEAM PANEL, 12-1/2')	EA	5.000
	E536- 12-620	GUARDRAIL REPAIRS (REPLACE) (THRIE-BEAM PANEL, 25')	EA	2.000
	E536- 15-	MISCELLANEOUS GUARDRAIL MAINTENANCE	LF	100.000
	E536- 65-	END ANCHORAGE ASSEM (REMOVE)	EA	1.000
	E536-301-501	END ANCHOR ASSEM TYPE II (REPL FLARED END SECT)	EA	1.000
	E536-301-502	END ANCHOR ASSEM TYPE II (REPL ROUND END SECT)	EA	1.000
	E536-301-503	END ANCHOR ASSEM TYPE II (REPL BUFFER END SECT)	EA	1.000

Call Order: 006 Proposal: E3Y62-R0

ALT	Item	Description	Unit	Quantity
	E536-301-506	END ANCHOR ASSEM TYPE II (REPL GUARDRAIL BEAM)	EA	1.000
	E536-301-508	END ANCHOR ASSEM TYPE II (REPL TIMBER BREAK POST)	EA	1.000
	E536-303-503	END ANCHOR ASSEM CRT (REPL BUFFER END SECTION)	EA	1.000
	E536-303-508	END ANCHOR ASSEM CRT (REPL TIMBER BREAK POST)	EA	1.000
	E536-306-501	END ANCHOR ASSEM BRIDGE (REPL SPECIAL END SHOE)	EA	1.000
	E536-306-503	END ANCHOR ASSEM BRIDGE (REPL TIMBER FILL BLOCK)	EA	1.000
	E536-306-504	END ANCHOR ASSEM BRIDGE (REPL GUARDRAIL BEAM)	EA	1.000
	E536-306-506	END ANCHOR ASSEM BRIDGE (REPL CONC ANCHOR BLOCK)	EA	1.000
	E536-306-509	END ANCHOR ASSEM BRIDGE (REPL ANCHOR PANEL SECT)	EA	1.000
	E536-307-503	END ANCHOR ASSEM BARRIER (REPL TIMBER FILL BLOCK)	EA	1.000
	E536-309-506	END ANCH ASSEM BEST (REPL GUARDRAIL BEAM)	EA	1.000
	E536-322-501	END ANCHOR ASSEM FLARED (REPL FLARED END SECT)	EA	1.000
	E536-322-502	END ANCHOR ASSEM FLARED (REPL ROUND END SECT)	EA	1.000
	E536-322-503	END ANCHOR ASSEM FLARED (REPL BUFFER END SECT)	EA	1.000
	E536-322-506	END ANCHOR ASSEM FLARED (REPL GUARDRAIL BEAM)	EA	1.000
	E536-322-508	END ANCHOR ASSEM FLARED (REPL TIMBER BREAK POST)	EA	1.000
	E536-322-511	END ANCHOR ASSEM FLARED (REPL SPECIAL END SHOE)	EA	1.000
	E536-322-515	END ANCHOR ASSEM FLARED (REPL AMBER REFLECT SHEET)	EA	1.000
	E536-322-517	END ANCHOR ASSEM FLARED (REPL SHORT TIMBR BREAK POST)	EA	1.000
	E536-324-506	END ANCHOR ASSEM PARALLEL (REPL GUARDRAIL BEAM)	EA	1.000
	E536-324-511	END ANCHOR ASSEM PARALLEL (REPL SPECIAL END SHOE)	EA	1.000
	E536-324-515	END ANCHOR ASSEM PARALLEL (REPL AMBER REFLECT SHEET)	EA	1.000
	E536-324-517	END ANCHOR ASSEM PARALLEL (REPL SHORT TIMBR BREAK POST)	EA	1.000
	E544- 8- 5	CRASH CUSHION DAMAGE RESTORATION	EA	1.000
	E544- 75-500	05 TRACC CRASH CUSHION	EA	1.000
	E544- 75-501	05 TRACC NOSEPIECE / REFLECTIVE SHEETING	EA	1.000
	E544-054-000	ATTENUATOR (GREAT) (REMOVE)	EA	1.000
	E544-061-019	ATTENUATOR (HEX FOAM) F&I (DIAPHRAM 6-8 BAY)	EA	1.000
	E544-091-001	ATTENUATOR (TAU II) F&I (FENDER PANEL)	EA	1.000