

Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities

Letting:	04211203	Call Order: 011	Proposal: E4V64-R0	District:04
Counties:	DIST/ST-WIDE			
Road Name:	D/W STRUCTURES REPAIRS PUSHBUTTON - ANCILLARIES			
Limits:	Midpoint			
Project(s):	44476837201(*)	Federal Aid No: N/A		
Total Roadway Length:	0.000 Miles	Contract Days:	730	
Total Bridge Length:	0.000 Miles	Letting Date:	12/03/21	
Total Proposal Length:	0.000 Miles	Contract Execution Days:	10	
		Special Start Date:	N/A	
		Aquis/Flexible Start Time:	13	
Proposal Budget Estimate:	\$700,000.00			

Please read the full advertisement

Description:

The work under this Contract consists of a Work Document driven contract to perform routine and priority repairs on ancillary structures including but not limited to, traffic signal mast arms and sign structure repairs, coating of existing structural steel, bolt replacement, bolt tightening, grout pad replacement, and other miscellaneous concrete and steel repairs at various locations throughout District 4.

• **WORK DRIVEN CONTRACT:** The award amount and contract performance bond shall be based on the budgeted amount of \$700,000.00 and not the contractors bid total over the 730 calendar days term of the contract.

o The quantities shown on the Bid Price Proposal are approximate and only represent estimated planned requirements based on historical or specific project needs. The Department does not guarantee any maximum or minimum quantity, any range of quantities, or the exact quantities shown for each bid item. The Department's estimated quantities and the Contractor's bid price will be used to calculate a total bid amount. This total bid amount will then be used to determine the low bidder; however, actual payment under the awarded contract will be based on actual quantities completed.

o For this Contract in which specific sites are not identified at the time of letting, the Engineer will issue a Work Document. Work Documents will identify the location, description, amount of work to be accomplished, and the number of calendar days to complete the work.

• **MAXIMUM LIMITING FUNDING TERM 7:** This contract has a budgetary ceiling of \$700,000.00

Currently only \$10,000 of the \$ 700,000.00 is available. Additional funds will be brought on by Letters of Authorization/Task Work Order (Funding Term 7). The total of all work documents is limited to the budgetary ceiling over the 730 contract calendar days unless amended by Supplemental Agreement.

• **PERFORMANCE BOND:** A Contract / Performance bond is required for this project.

• **REQUIRED SUBMITTAL WITH BID:** Experience in Traffic Signal Repair experience form 850-070-07 must be submitted with the bid.

• **GENERAL LIABILITY:** The limits of coverage shall not be less than \$1,000,000 for each occurrence and not less than a \$5,000,000 annual general aggregate, inclusive of amounts provided by an umbrella or excess policy. The limits of coverage described herein shall apply fully to the work or operations performed under the Contract, and may not be shared with or diminished by claims unrelated to the contract. The policy/ies and coverage described herein may be subject to a deductible. Pay all deductibles as required by the policy. No policy/ies or coverage described herein may contain or be subject to a Retention or a Self-Insured Retention.

**Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities**

Call Order: 011 Proposal: E4V64-R0

ALT	Item	Description	Unit	Quantity
Section 0001 TRAFFIC CONTROL DEVICES CONTROL (MH)				
	0102- 14-	TRAFFIC CONTROL OFFICER	HR	32.000
	0400-145-	CLEANING CONCRETE SURFACE	SF	50.000
	0400-153-	NON SHRINK GROUT, F&I, MISCELLANEOUS- STRUCTURES REHAB	CF	7.000
	0401- 70- 1	RESTORE SPALLED AREAS, EPOXY	CF	7.000
	0401- 70- 3	RESTORE SPALLED AREAS, LATEX MODIFIED MORTAR- ACRYLIC	CF	7.000
	0411- 1-	EPOXY MATERIAL FOR CRACK INJECTION- STRUCTURES REHAB	GA	4.000
	0411- 2-	CRACKS INJECT & SEAL- STRUCTURES REHAB	LF	20.000
	0460- 1- 13	STRUCTURAL STEEL REHAB- BOLTS, NUTS, WASHERS & PLATES	LB	1,900.000
	0460- 94-	STRUCTURAL STEEL REPAIR- WELDS	LF	7.000
	0561- 2-	COATING EXISTING STRUCTURAL STEEL	SF	1,135.000
	0649- 26- 1	STEEL MAST ARM ASSEMBLY, REMOVE, POLE ONLY- ENTIRE FOUNDATION REMAINS	EA	1.000
	0649- 26- 3	STEEL MAST ARM ASSEMBLY, REMOVE, SHALLOW FOUNDATION- BOLT ON ATTACHMENT	EA	1.000
	0649- 26- 7	STEEL MAST ARM ASSEMBLY, REMOVE, REMOVE ARM AND ATTACHMENTS; POLE REMAINS	EA	1.000
	0649- 40- 1	STEEL MAST ARM ASSEMBLY- REPLACE SCREEN ON EXISTING POLE	EA	79.000
	0649- 40- 2	STEEL MAST ARM ASSEMBLY- REPLACE HAND HOLE COVER ON EXISTING POLE	EA	4.000
	0649- 40- 3	STEEL MAST ARM ASSEMBLY- REPLACE POLE CAP ON EXISTING POLE	EA	57.000
	0649- 40- 4	STEEL MAST ARM ASSEMBLY- REPLACE STRUCTURAL GROUT PAD ON EXISTING POLE	EA	111.000
	0649- 40- 5	STEEL MAST ARM ASSEMBLY- REPAIR/REPLACE BROKEN WELD ON EXISTING POLE	EA	4.000
	0649- 40- 8	STEEL MAST ARM ASSEMBLY- FURNISH & INSTALL BIRD SCREEN ON EXISTING POLE	EA	142.000
	0700- 4-610	OVERHEAD STATIC SIGN STRUCTURE, REMOVE CANTILEVER	EA	1.000
	0700- 4-620	OVERHEAD STATIC SIGN STRUCTURE, REMOVE SPAN	EA	1.000
	0715- 19- 60	HIGH MAST LIGHT POLE, REMOVE POLE AND FOUNDATION	EA	1.000
	0715- 19- 61	HIGH MAST LIGHT POLE, REMOVE POLE- FOUNDATION REMAINS	EA	1.000
	E101- 72-	MOBILIZATION (EMERGENCY RESPONSE)	EA	1.000
	E460- 82-	BOLT TIGHTENING	EA	284.000