



**Florida Department of Transportation  
Bid Solicitation Notice and Approximate Quantities**

**Call Order: 003 Proposal: E6P45-R0**

ALT	Item	Description	Unit	Quantity
<b>Section 0001 BRIDGE DAMAGE REPAIR (MH)</b>				
	0102- 14-	TRAFFIC CONTROL OFFICER	HR	10.000
	0121- 70- 2	FLOWABLE FILL, MAINTENANCE CONTRACTS ONLY	CY	2.000
	0400- 4- 4	CONCRETE CLASS IV, SUPERSTRUCTURE	CY	1.000
	0400- 4- 5	CONCRETE CLASS IV, BRIDGE SUBSTRUCTURE	CY	1.000
	0400-145-	CLEANING CONCRETE SURFACE	SF	3.000
	0401- 70- 2	RESTORE SPALLED AREAS, LATEX MODIFIED MORTAR- STYRENE BUTADIENE	CF	50.000
	0411- 1-	EPOXY MATERIAL FOR CRACK INJECTION- STRUCTURES REHAB	GA	5.000
	0411- 2-	CRACKS INJECT & SEAL- STRUCTURES REHAB	LF	1,400.000
	0413-149-	PENETRANT SEALER	GA	5.000
	0413-154-	CLEANING & SEALING CONCRETE SURFACES - PENETRANT SEALER OR METHACRYLATES	SF	1.000
	0415- 1- 4	REINFORCING STEEL - BRIDGE SUPERSTRUCTURE	LB	1.000
	0450- 83- 1	BEAM REPAIR, STRAND SPLICES	EA	10.000
	0458- 1- 21	BRIDGE DECK EXPANSION JOINT, REHABILITATION, POURED JOINT WITH BACKER ROD	LF	2,000.000
	0458- 2-	POLYMER NOSING FOR BRIDGE DECK EXPANSION JOINT	CF	100.000
	0530- 1-100	RIPRAP, SAND-CEMENT BAGS	CY	20.000
	0530- 3- 3	RIPRAP- RUBBLE, BANK AND SHORE	TN	1.000
	0561- 2-	COATING EXISTING STRUCTURAL STEEL	SF	100.000
	0649- 40- 4	STEEL MAST ARM ASSEMBLY- REPLACE STRUCTURAL GROUT PAD ON EXISTING POLE	EA	45.000
	0649- 40- 5	STEEL MAST ARM ASSEMBLY- REPAIR/REPLACE BROKEN WELD ON EXISTING POLE	EA	1.000
	E561- 1- 1	COATING EXISTING STRUCTURAL STEEL, BEARING	EA	40.000
	E700- 46- 33	REPAIR EXISTING SIGN (OVHD TRUSS)	AS	30.000
	E700- 96- 1	SIGN SUPPORT REPAIRS (ALUMINUM)	LB	1.000