STE OF FLORID	Bid Questions and Ar	Bid Questions and Answers Report Date & Tim		3/28/2018 9:39:57 AM	
	District Address:	District 5 Construction Office, FL 32720	located at 719 South V	Voodland Blvd, Deland,	
OF TRAILS	District Phone:	(386) 943-5350			
Proposal:	T5609				
Project:	434412-1-52-01				
Letting Date:	3/28/2018				
Localtion:	CENTRAL OFFICE				
Description:	SR 436				
Question:	relates to the median drainage work under nightly lane closur protection during non-work pe similar drainage work (without	evaluate the Traffic Control Plan a work? It is unrealistic to perfore (8 hours) without temporary b riods. On other FDOT projects TBW protection) the Departme uous weekend closures. Please k.	rm this arrier wall s with nt/Engineer	2/9/2018 3:17:33 PM	
Answer:	See Amendment 1.		Status: Posted:	ANSWER PUBLISHED 2/23/2018 9:37:06 AM	
Answer:	See upcoming Revision 2.		Status: Posted:	ANSWER VOIDED 2/16/2018 2:04:14 PM	
Question:		neer did not provide any quantity d resurfacing operations through of Estimates. Please advise.		2/12/2018 6:40:49 AM	
Answer:	See Amendment 1.		Status: Posted:	ANSWER PUBLISHED 2/23/2018 9:38:05 AM	
Answer:	See upcoming Revision 2.		Status: Posted:	ANSWER VOIDED 2/16/2018 2:03:46 PM	

Question:	21104: There are several drainage structures in the median and outside lanes that require an extensive amount of work. Connecting to existing	Posted:	2/12/2018 4:21:13 PM
	drainage pipe usually requires a concrete collar. Setting a precast structure, grouting in the pipes, building concrete collars, allowing concrete to set up before backfilling, and compaction efforts take a lot more time than what is allowed in the contract for lane closures. Can extended lane closures be allowed for these drainage structures?		
Answer:	See Amendment 1.	Status:	ANSWER PUBLISHED
		Posted:	2/23/2018 9:38:48 AM
Answer:	See upcoming Revision 2.	Status:	ANSWER VOIDED
		Posted:	2/16/2018 2:03:24 PM
Question:	21106: Is there survey control data for this project?	Posted:	2/13/2018 10:45:57 AM
Answer:	No.	Status:	ANSWER PUBLISHED
		Posted:	2/15/2018 5:03:46 PM
Question:	21111: The Department did not provide any information regarding how they want the Contractor to pave the intersection shown on Sheet 40. Variable depth milling? Overbuild? Quantities and details were not provided for either. Please advise.	Posted:	2/13/2018 4:00:12 PM
Answer:	Please refer to Sheet 10 of the Roadway Construction plans.	Status:	ANSWER PUBLISHED
		Posted:	2/15/2018 5:03:27 PM
Question:	21117: Can the Department verify their quantities for the traffic separators? The lengths calculated per station range are wrong.	Posted:	2/14/2018 7:23:21 AM
Answer:	See Amendment 1.	Status:	ANSWER PUBLISHED
		Posted:	2/23/2018 9:39:53 AM
Answer:	See upcoming Revision 2.	Status:	ANSWER VOIDED
			2/16/2018 2:02:36 PM

Question:	21134: Water table information has not been provided. Please provide water table data so that Contractor can determine dewatering requirements, if required, for drainage structure excavations.	Posted:	2/14/2018 4:15:01 PM
Answer:	Roadway borings were not performed for this contract. Please see attached geotechnical report for available geotechnical information.	Status:	ANSWER PUBLISHED 2/16/2018 2:55:35 PM
		r Usteu.	2/10/2010 2.33.33 FW
Docum	ent: 6978951: 434412-1 SR 436 Geo Report for Drainage.pdf		
	434412-1-52-01 - Geotechnical Report		
Question:	21163: Referencing the Department's response to question 21111, the detail referenced on sheet 10 is applicable from station 8+15 to 9+01.28, beyond that range the intersection detail governs. Sheet 40, does not specify variable depth milling and/or overbuild above 9+01.28 and on the mainline SR436. The Typical Section for SR436 or Maitland Ave does not provide elevation change information for this area. Please provide further detail regarding the intersection grading plan, especially as it relates to the mainline of SR436 as shown.	Posted:	2/16/2018 4:52:53 PM
Answer:	Sheet 10 shows two details for the construction of Maitland Avenue. A	Status:	ANSWER PUBLISHED
	variable depth milling detail from Sta. 8+15.00 to Sta. 9+01.28 and a reconstruction detail from 9+01.28 to 9+60.00. The mainline of SR 436 is to match the existing elevation and cross slope as shown on the intersection detail sheet. Sheet 40 refers to the edge of pavement profile for the southeast quadrant elevation changes on Roadway Profile Sheet (12). The intersection detail, Maitland Avenue profile, Maitland avenue cross sections, and typical section show all the necessary details for construction.	Posted:	2/21/2018 5:10:12 PM
Question:	21201: When will Revision 2 be available, as referenced in the current Q&A? Revision 1 was released today (2/21/18) in Addendum 2, and today is the question cutoff. Please advise.	Posted:	2/21/2018 12:01:15 PM
Answer:	Please see Amendment 1 for plans revisions.	Status:	ANSWER PUBLISHED
		Posted:	2/21/2018 5:10:46 PM
Question:	21210: Referencing the Department's response to question 21201, Revision 1 released in Addendum 2 did not address multiple Contractors' concerns regarding median drainage work (questions 21096 & 21104). Both responses stated "See upcoming Revision 2." Revision 1 only revised traffic separator quantities, added trooper quantity, and removed totals from Summary of Quantities. Please advise when Revision 2 will be released with TCP modifications.	Posted:	2/21/2018 6:12:31 PM

Answer:	There is no Revision 2. Please refer to Amendment 1. All previous responses referencing Revision 2 have been modified to direct bidders to	Status:	ANSWER PUBLISHED
	Amendment 1. Amendment 1 expanded the lane closure restrictions to include weekend closures to facilitate the median construction work.	Posted:	2/23/2018 9:41:16 AM
Question:	21215: The plans do not address several vital issues with the drainage structures from approximate 1451+00 to 1455+00 (LT). Utility conflicts/protections with drainage structures, pipe, and/or sheet pile; insufficient space behind barrier wall without encroaching onto private property; additional roadway reconstruction required into SR436 (beyond TBW/proposed reconstruction limits). The current plans are not possible. Please advise.	Posted:	2/22/2018 2:47:36 PM
Answer:	Utility conflicts have been identified and addressed in the utility work schedules. The Department has provided extended lane closures to	Status:	ANSWER PUBLISHED
	facilitate construction through this area. Refer to sheets 151 and 152 for construction during non-lane closure hours and sheet 150 for phasing notes. Amendment 1 expanded the lane closure restrictions to include weekend closures to facilitate westbound drainage construction work.	Posted:	2/23/2018 9:42:12 AM
Question:	21225: This project is a LS bid project. A Summary of Quantities for the required and intended work has been provided to be used for the basis of the Contractors estimate. There is additional work REQUIRED for some areas in the plans where no work is shown to performed and no quantities have been included. At Structures S-112, S-116, S-303, and S-304 additional roadway base, asphalt, and concrete curbs will be required to be removed and replaced. This work is not shown in the plans. How will this work be paid if required?	Posted:	2/23/2018 11:34:42 AM
Answer:	Please note that the Letting for this project has been moved to 3/28/2018.	Status:	ANSWER PUBLISHED
	Please see forthcoming Amendment.	Posted:	2/28/2018 3:46:26 PM
Answer:	Questions posted to this site before 5:00 P.M. (EST) on the seventh calendar day prior to the bid opening, or tenth day prior to the December	Status:	ANSWER VOIDED
	bid opening will be responded to by the Department. For Questions posted after these times, an answer cannot be assured.	Posted:	2/26/2018 3:25:04 AM
Question:	21226: This project is a LS bid project. A Summary of Quantities for the required and intended work has been provided to be used for the basis of the Contractors estimate. There is additional work REQUIRED for some areas in the plans where no work is shown to be performed and no quantities have been included. In regards to the installation of several storm drain structures in the median/center areas of SR436 no MOT plans address these installations. No lane closures or devices or barrier walls (if required) have been shown to be required to create the required	Posted:	2/23/2018 11:38:15 AM

Answer:	Please note that the Letting for this project has been moved to 3/28/2018. Please see forthcoming Amendment.	Status:	ANSWER PUBLISHED
		Posted:	2/28/2018 3:47:13 PM
Answer:	Questions posted to this site before 5:00 P.M. (EST) on the seventh calendar day prior to the bid opening, or tenth day prior to the December	Status:	ANSWER VOIDED
	bid opening will be responded to by the Department. For Questions posted after these times, an answer cannot be assured.	Posted:	2/26/2018 3:25:04 AM
Question:	21227: Work required to install pipe and structures S-123,124,126, and 128 will require work outside of the FDOT ROW limits on private properties, Restoration work for these areas is not included in the Summary of Quantities for the project. How will this work be compensated? Is it incidental or will payment for additional quantities be made for all work required to restore the areas outside of the ROW?	Posted:	2/23/2018 11:41:33 AM
Answer:	Please note that the Letting for this project has been moved to 3/28/2018. Please see forthcoming Amendment.	Status:	ANSWER PUBLISHED
		Posted:	2/28/2018 3:48:19 PM
Answer:	Questions posted to this site before 5:00 P.M. (EST) on the seventh calendar day prior to the bid opening, or tenth day prior to the December	Status:	ANSWER VOIDED
	bid opening will be responded to by the Department. For Questions posted after these times, an answer cannot be assured.	Posted:	2/26/2018 3:25:04 AM
Question:	21228: The project MOT plans do not include MOT for the work areas for the storm drain structure work for structures S-303 and S-304 specifically. Is the contractor to include costs for engineering and MOT plans for the required work in these areas? If the contractors MOT plans submitted for this work are rejected/denied will a change order and possibly additional project time be granted for modifications to the contractors MOT plan? Will the department issue MOT plans at a later date addressing this work for pricing via change order? Please clarify this issue.	Posted:	2/23/2018 11:47:44 AM
Answer:	Please note that the Letting for this project has been moved to 3/28/2018. Please see forthcoming Amendment.	Status:	ANSWER PUBLISHED
		Posted:	2/28/2018 3:49:03 PM
Answer:	Questions posted to this site before 5:00 P.M. (EST) on the seventh calendar day prior to the bid opening, or tenth day prior to the December	Status:	ANSWER VOIDED
	bid opening will be responded to by the Department. For Questions posted after these times, an answer cannot be assured.	Posted <sup>.</sup>	2/26/2018 3:25:04 AM

Question:	21232: There are outstanding questions regarding scope that may or ma not be addressed via change order. Either way, we request additional time to evaluate the Department's responses to those outstanding questions. We need the time to plan and coordinate with vendors/subcontractors. Based on feedback from subcontractors, the Department caused confusion by answering many questions with "See upcoming Revision 2." It is apparent at this point there is no plan "Revision 2," only plan Revision 1 (Released 2/20 in "Addendum" No. 2) The Department later changed the responses to "See Amendment 1" on 2/23. This prompted an influx of questions that we all thought were goin to be addressed in a future "Revision 2". Please grant additional time fo Contractors to evaluate the Department's responses to questions regarding scope that is REQUIRED but not included in this Lumpsum Contract.		2/24/2018 11:18:10 AM
Answer:	Please note that the Letting for this project has been moved to 3/28/2018. Please see forthcoming Amendment.	Status:	ANSWER PUBLISHED
		Posted:	2/28/2018 3:49:41 PM
Answer:	Questions posted to this site before 5:00 P.M. (EST) on the seventh calendar day prior to the bid opening, or tenth day prior to the December bid opening will be responded to by the Department. For Questions posted after these times, an answer cannot be assured.		ANSWER VOIDED
			2/26/2018 3:25:04 AM