



Bid Questions and Answers Report

Date & Time:

3/25/2020 8:07:52 AM

District Address: District 6 Construction Office, located at 1000 NW 111 Ave, Miami, FL 33172

District Phone: (305) 640-7448

Proposal: T6475

Project: 436355-2-52-01

Letting Date: 3/25/2020

Localtion: CENTRAL OFFICE

Description: SR 976 (SW 40 ST) (BIRD RD)

---

Question: 29054: What type of sod will be implemented on this project? Posted: 3/4/2020 7:33:08 AM

---

Answer: It is the Contractor's choice. Status: ANSWER PUBLISHED

Posted: 3/4/2020 4:29:10 PM

---

Question: 29055: Pay item no. 0639 8 27 Electrical Power Service, identifies a \$4500 contribution in aid of construction (CIAC) DO NOT BID. Is the contractor suppose to do the work for \$4500, or do we enter our cost? Posted: 3/4/2020 7:44:25 AM

---

Answer: Pay Item No. 639-8-27 - is to reimburse FP&L for the cost of the transformers. The Department will reimburse the Contractor for the actual invoice amount. Any additional costs associated with coordination, processing the invoice transmittal and payment shall be included in Pay Item 639-1-122 - Electrical Power Service, per assembly. Status: ANSWER PUBLISHED

Posted: 3/4/2020 5:55:06 PM

---

Question: 29098: The roadway soils survey GR-1, states that the material in Stratum no. 3 is unsuitable and shall be removed to a depth of 27", under what pay item does the contractor get paid. Posted: 3/6/2020 3:35:57 PM

---

Answer: Should unsuitable material (topsoil or silty sand) be encountered, it shall be removed and replaced with suitable soil. Cost of excavation is included in 120-71 - Regular Excavation, LS. Cost of the fill is included in in pay item 120-2-2 - Borrow Excavation, CY. Status: ANSWER PUBLISHED

Posted: 3/10/2020 1:59:37 PM

---

Question: 29099: Could you provide the boring details? Need to know the depth of each of the stratum shown on sheet GR-1. Posted: 3/6/2020 3:38:23 PM

---

Answer: The Roadway Soil Survey and the Signal Core Boring Sheets are attached. Status: ANSWER PUBLISHED  
Posted: 3/9/2020 5:44:15 PM

---

Document: 9811014: 436355-2 - SW 40 St - Roadway Soils Survey.pdf

Roadway Soil Survey

---

Document: 9811019: 436355-2- SIGNALIZATION-COREBORINGS.pdf

Signal Core Borings

---

Question: 29142: Fin No. 436355-2-52-01, sheet no. SQ-16 identifies a truck measure quantity for pay item no. 120 71. Yet, Fin No. 436355-3-52-0, does not provide any quantities for this pay item nor as stated in the pay item, show any cross sections to calculate the quantity in order to provide a price on the second regular excavation (3R Projects Only) pay item on the bid sheet. Posted: 3/12/2020 3:04:03 PM  
  
Could you please provide the CY's for Fin No. 436355-3-52-0, pay item no. 10 71?

---

Answer: 436355-3-52-01 does not require Pay Item 120-71 - Regular Excavation (3-R Projects Only). Status: ANSWER PUBLISHED  
Posted: 3/16/2020 11:11:57 AM  
  
Unless otherwise specified in the contract plans, minor earthwork is incidental to related bid item. For example, cost of excavation for sidewalk replacement (6" sidewalk where 4" sidewalk existed previously) is included in pay item for 6" sidewalk.

---

Question: 29172: Where is the Optional Base group 09 going to be placed? Posted: 3/16/2020 8:17:51 AM

---

Answer: All bases shall be OBG 11. The quantities for OBG 09 will be revised to OBG 11. Plans will be changed accordingly in the upcoming Amendment. Status: ANSWER PUBLISHED  
Posted: 3/17/2020 10:52:29 AM