
Index 524-001 Ditch Pavement and Sodding

ORIGINATION

Date: 4-19-22

Name: Tim Holley

Phone: 850 414-4117

Email: tim.holley@dot.state.fl.us

COMMENTARY

Redeveloped and reorganized the Index for clarity and to reduce clutter.

Moving joint language to Specifications should help clarify construction of joints for slope pavement and ditch pavement.

COMMENTS AND RESPONSES

BLACK = Industry Review Comments **BLUE** = Standard Plans Response **GREEN** = Change Made to Index

Name: Paul Foley

Date: 8-30-22

COMMENT: On Sheet 1, the 4' standard ditch bottom width may conflict with Section 2.4.4 of the Drainage Manual indicating "The minimum channel bottom width is five feet to accommodate mitered end sections and maintenance mowers."

RESPONSE: The five feet in the Drainage Manual is referring to grassed channels for maintenance mowers. The detail in the Index is for paved ditches. There will always be a transition in the ditch bottom when a MES is used.

No Change to Index

Response Date: 8/31/22