State of Florida Department of Transportation PAVEMENT EVALUATION AND CONDITION DATA SHEET															_			SHE	ЕТ		
Proje	ect No.:		24020	Cored	By:		Arda	aman					Date: 12/13/2016							Page No.: 1 of 1	
County:			Seminole		Highway Sect. No: 77030									From: Center Road							To: W. of SR 400 (I-4)
Road No.:			SR 46		Begin MP: 3.257								End MP: 5.090							Length: 1.833	
Road	110		510		Degin	.,	Doromo	Pavement Layers (in.) Base					Crack				T		ſ	Length. 1.833	
Core No.	MP	Distance from left edge of lane (ft.)	Lane	Wheel Path	FC-5	FC-2	FC-12.5	Type SP	Type S	Type I	Core Length (in)	Type	Thickness (in)	Depth (in)	Type	Class	Extent	Pavt Cond.	Rut Depth (in)	Cross Slope (%)	Comments
1	3.863	7.0	RRTL		1.1			2.7			3.8	LR	10.5					F			To Atria Park of Lake Forest
2	3.863	1.5	OR		1.1			2.8			3.9	LR	7.3					F			Grass covering pavement To International Parkway
3	4.311	5.5	RRTL		0.9				4.8		5.7	LR	10.1					G			Cavitation (pitting) on shoulder To Wayside Drive
4	4.751	5.0	RRTL				2.0		1.6		13.8	ABC	10.2					G G			1 inch of limerock under ABC
5	4.810	5.5	LRTL				1.6		1.2		13.7	ABC	10.9								To Oregon Street
6	4.651	5.5	LRTL				1.3		1.3		13.1	ABC	10.5					G			To Hawkstone Drive
7	4.582	6.0	LRTL				1.3		1.5		12.4	ABC	9.6					G			To Hawkstone Drive To Dunwoody Plaza
8	4.478	5.0	LRTL		0.8				2.8		12.5	ABC	8.9					F			Light raveling present Grass covering pavement Air voids noted in structural course
-	4.478	1.5	OL		0.6				3.0		10.1	ABC	6.5					G			To Terracina Drive Very thick OGFC
10	4.380	6.0	LRTL		1.5				2.5		4.0	LR	13.8					G			To Bernini Way / 5th Third Bank
11	4.301	6.0	LRTL		0.8				2.9		3.7	LR	13.9					G			To Lake Forest Blvd. (Extension)
12	4.207	6.0	LRTL		0.9		1.7		4.2	1.0	5.1	LR	9.0					G			To Lake Forest Boulevard
13	4.155	5.5	LRTL		0.5		1.7		3.6	1.9	5.0	LR LR	10.6					G			To Publix / Shoppes Plaza
		6.0	LRTL		0.5						4.1							G			
15	4.034	1.5	OL		0.6				2.7		3.3	LR	5.8					G			To Bell Lake Forest Apartments
16	3.905	6.5	LRTL		1.4			3.6			5.0	LR	11.0					G			
17	3.905	3.0	OL		0.6			2.9			3.5	LR	11.6					G			To Henderson Lane
18	3.800	7.5	LRTL		0.6				4.2		4.8	LR	10.5					G			
19	3.800	2.0	OL		1.1				2.9		4.0	LR	10.4					G			To Elite Fitness / Dry Cleaners
20	3.677	7.5	LRTL		0.6			3.7			4.3	LR	11.9					F			
21	3.677	9.0	OL LRTL	 X	0.5			3.1	2.9		3.6	LR LR	12.8					F			To Kangaroo / Shell Gas Station
23	3.550	1.0	OL		0.5				3.8		4.3	LR	11.0					G			
24	3.405	10.0	LRTL	Х		1.5			4.3		5.8	LR	8.6	OGFC	SL	I	L	F			To Moreno Landscape Nurseries Light raveling present
25	3.405	1.5	OL			1.4			1.2		2.6	LR	14.0					F			
26	3.538	2.0	RRTL		0.7				4.2		4.9	LR	10.2					F			To 7-11 / Mobil Gas Station
27	3.538	8.5	OR	х	0.9				5.1		6.0	LR	10.3					F			Light raveling present
28	4.232	9.5	R2	X	1.0				6.0		7.0	LR	7.2					F			
29	4.651	10.0	R2	х			1.1		5.0		6.1	LR	9.0					F			
30	4.743	6.0	R3				1.3		3.8		5.1	LR	7.6					G			
31	4.553	8.5	L2	Х	0.5				4.9		5.4	LR	9.8					F			
32	4.087	4.0	L2		1.0				3.4		4.4	LR	10.2					F			Light raveling present
33	3.627	8.0	L2	Х	0.7				4.4		5.1	LR	10.9					F			
34	3.384	4.0	1.2			1.1			1.9		3.0	LR	11.3	1.1	SL	I	L	F			Light raveling present Lane eventually merges to L1
35	3.380	6.0	R1		0.7				3.9		4.6	LR	9.5					F			
36	3.452	4.5	RLTL		0.6				2.7		3.3	LR	15.3					F			RLTL to Orange Boulevard
37	3.673	6.0	R1		0.7				4.8		5.5	LR	11.1					F			Light raveling present
38	3.743	2.5	RLTL	X	0.7				3.7		4.4	LR	13.4					F			To Henderson Lane Cavitation (pitting) present
39	3.950	8.0	R1	X	0.4				3.9		4.3	LR	8.4					F			and a Street
40	4.122	5.0	RLTL		0.9				2.8		3.7	LR	11.4					F			To Lake Forest Boulevard
41	4.537	7.5	RLTL	Х	0.6				2.5		14.4	ABC	11.3					G			To Hawkstone Drive
42	4.562	6.0	R1		0.7				6.3		7.0	LR	7.7					G			
43	4.742	6.0	RLTL				1.4		2.9		4.3	LR	11.7					G			To Oregon Street
44	4.611	10.0	LI	X			1.3		5.4		6.7	LR	8.6					G			
45	4.443	6.0	LLTL		0.5				4.5		5.0	LR	9.5					G			To International Parkway
46	4.179	5.5	LI	X	0.7				4.6		5.3	LR	10.6					G			
47	3.808	5.0	LLTL		0.6				3.5		4.1	LR	10.0					F			To Henderson Lane Cavitation (pitting) present. Grass covering pavement.
48	3.755	1.5	LI	X	0.6				3.7		4.3	LR	11.0					G			
49	3.627	7.5	LLTL	X	0.4			4.1	5.1		4.5	LR	9.5					G			To U-Turn / Future Development
50	3.562	8.0	LI	X	0.9				3.1		4.0	LR	9.9					F			
51	3.502	5.5	LLTL		0.7	0.7			2.5		3.2	LR	11.6	OGFC	SL	I	L	F			To Orange Boulevard Many small SL cracks present
52	3.431	7.0	R2		0.5	0.7			2.6		3.1	LR	11.1					F			many sman on clacks present
53	3.769	3.0	R2	X	0.6						5.2	LR						F			Light raveling present
54	4.299	5.5	R2 R1	X	0.6				5.3		6.1	LR	8.3					G			
																		G			To Terracina Drive
55	4.343	4.5	RLTL		0.5	1	1	1	4.4		4.9	LR	9.8	1	<u> </u>	<u> </u>	<u> </u>	<u> </u>		<u> </u>	1