

# FLORIDA DEPARTMENT OF TRANSPORTATION

## ALL SYSTEM PAVEMENT CONDITION FORECAST

**PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2024 - 2029, EXTRACTED ON 02/06/2024**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = BRADFORD -----																						
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR											FUTURE		
SR US	G_BMP	G_EMP	LN	#T	AADT	RATINGS	=====	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011		
INTERSECT AT (MP SIDE)	W_BMP	W_EMP	RW	FY-P	WKM-M	P	ASTYPE	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2029	
CONTRACTOR (AGE_ONE YEAR)	W_BMP	W_EMP	RW	FY-F	WKM-M	F															(REG)	
28010000	0.000	5.291	R	1	1	65	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5		
200 301				2	19.9	29249	RIDE	7.9		8.8	8.9	8.9	8.5	8.4	8.4	8.6	8.6	8.5	8.4	8.4		
CR 221 WYE ( 0.8R)																						
2080131	0.055	8.075	C	1999		0221	CRACKING	7.0	7.0	7.0	7.0	7.0	7.0	7.0	6.5	6.5	5.5*	5.5*	5.5*	5.5*	4.0	
APAC-FLORIDA INC (2001) SPRIDE																						
4472041	0.004	6.921	R	2024		0012																
28010000	6.038	6.923	R	1	1	55	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5		
200 301				2	23.0	10700	RIDE	7.9		8.8	8.9	8.9	8.5	8.4	8.4	8.6	8.6	8.5	8.4	8.4		
COMMERCIAL DR L ( 6.1R)																						
2080131	0.055	8.075	C	1999		0221	CRACKING	7.0	7.0	7.0	7.0	7.0	7.0	7.0	6.5	6.5	5.5*	5.5*	5.5*	5.5*	4.0	
APAC-FLORIDA INC (2001) SPRIDE																						
4472041	0.004	6.921	R	2024		0012																
28010000	6.923	8.044	R	1	1	35	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5		
200 301				2	23.0	10700	RIDE	7.9		8.8	8.9	8.9	8.0	7.9	7.8	8.1	8.0	7.7	7.7	7.8		
ALEXANDER ST( 7.0R)																						
4342981	6.923	8.044	C	2017		0012	CRACKING	8.0	8.0	7.0	7.0	7.0	6.5	6.5		10.0	10.0	10.0	10.0	10.0	10.0	
ANDERSON COLUMBIA CO., INC(2020) SPRIDE																						
28010000	8.044	8.954	R	1	1	30	CRACKING	10.0	10.0	10.0	9.5	9.5	9.5	9.5	8.0	10.0	10.0	10.0	10.0	10.0	9.5	
200 301				2	24.8	15400	RIDE	7.9	7.7	7.4	7.2	7.2	7.1	6.7	6.5	8.2	8.1	7.9	7.8	7.6		
MADISON ST( 8.1C)																						
4361561	8.044	8.954	C	2017		0012	CRACKING	8.0	8.0	7.0	6.5	6.5	6.5	6.5		10.0	10.0	10.0	10.0	10.0	10.0	
ANDERSON COLUMBIA CO., INC(2020) SPRIDE																						
28010000	8.954	9.875	R	1	1	45	CRACKING	2.0*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	7.0	7.0		
200 301				2	24.8	4700	RIDE	7.7		7.9	8.2	8.1	7.9	7.9	7.8	8.1	8.0	7.8	7.8	7.6		
ANDREWS ST( 9.0C)																						
4323091	8.954	14.320	C	2017		0012	CRACKING	6.0*	6.0*	6.0*	6.0*	6.0*	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	
ANDERSON COLUMBIA CO., INC(2020) SPRIDE																						
28010000	9.875	11.362	R	1	1	55	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5		
200 301				2	24.8	4700	RIDE	7.8		8.7	8.9	8.8	8.3	8.3	8.3	8.5	8.5	8.4	8.3	8.3		
UNSIGNED(10.1R)																						
4323091	8.954	14.320	C	2017		0012	CRACKING	7.0	7.0	7.0	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	
ANDERSON COLUMBIA CO., INC(2021) SPRIDE																						
28010000	11.916	14.330	R	1	1	65	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5		
200 301				2	24.8	23500	RIDE	7.8		8.7	8.9	8.8	8.3	8.3	8.3	8.5	8.5	8.4	8.3	8.3		
NE 196 TER(12.3R)																						
4323091	8.954	14.320	C	2017		0012	CRACKING	7.0	7.0	7.0	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	
ANDERSON COLUMBIA CO., INC(2021) SPRIDE																						
28010000	14.330	15.052	R	1	1	55	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	7.0	7.0		
200 301				2	24.8	23500	RIDE	7.8		8.7	8.2	8.3	7.8	7.8	7.6	7.8	7.6	7.0	6.9	6.3*		
CR-225/LAKE ST(15.4R)																						
4286921	14.320	15.857	C	2014		0012	CRACKING	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	9.5	7.5	7.5	6.5	6.5	4.4	
ANDERSON COLUMBIA CO., INC(2015) SPRIDE																						
4286922	14.330	15.857	C	2026		0012		6.2*	5.9*	7.7	8.3	8.4	8.4	8.4	8.2	8.3	8.2	8.1	8.5	8.4	8.3	
28010000	15.052	15.857	R	1	1	45	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	7.0	7.0		
200 301				2	24.8	23500	RIDE	6.8		8.1	8.2	8.3	7.8	7.8	7.6	7.8	7.6	7.0	6.9	6.3		
CR-225/LAKE ST(15.4R)																						
4286921	14.320	15.857	C	2014		0012	CRACKING	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	9.5	7.5	4.5*	4.5*	4.5*	0.9	
ANDERSON COLUMBIA CO., INC(2015) SPRIDE																						
4286922	14.330	15.857	C	2026		0012		6.2	5.9	7.7	8.3	8.4	8.4	8.4	8.2	8.3	8.2	7.6	7.8	7.9	7.4	
28010000	15.857	20.227	R	1	1	65	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	7.0		
200 301				2	29.7	21000	RIDE	8.2		8.9	8.9	8.9	8.4	8.4	8.3	8.5	8.5	8.4	8.3	8.3		
CR 125(16.3C)																						
4323151	15.857	20.078	C	2017		0012	CRACKING	7.0	7.0	7.0	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	
ANDERSON COLUMBIA CO., INC(2019) SPRIDE																						
28010000	15.857	20.227	L	1	1	65	CRACKING	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	7.0		
200 301				2	29.7	21000	RIDE	8.2		8.9	8.9	8.8	8.4	8.3	8.4	8.5	8.5	8.4	8.3	8.3		
CR 125(16.3C)																						
4323151	15.857	20.078	C	2017		0012	CRACKING	7.0	7.0	7.0	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	
ANDERSON COLUMBIA CO., INC(2019) SPRIDE																						

\*\*\* INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.  
 \*\*\* INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.  
 "@@ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.  
 2029 FORECASTED BY SIMPLE LINEAR REGRESSION (REG).





# FLORIDA DEPARTMENT OF TRANSPORTATION

## ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2024 - 2029, EXTRACTED ON 02/06/2024

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = BRADFORD -----																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE	
SR	US	G_BMP	G_EMP	LN	*T	ADT	RATINGS	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	
INTERSECT AT (MP SIDE)								=====													
ITMSEG-P W_BMP W_EMP RW FY-P WKMX-P																					
CONTRACTOR (AGE_ONE YEAR) ASTYPE																					
ITMSEG-F W_BMP W_EMP RW FY-F WKMX-F																					
28030001	7.250	7.790	C	1	1	40	CRACKING	6.0*	4.5*	1.5*	1.5*	1.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5
16			2	3.4		4500	RIDE	8.5	8.3	8.2	8.0	7.7	8.3	8.2	8.3	7.4	8.3	8.2	8.0	8.1	
NW 177TH ST( 7.3R)								FC125M													
							CRACKING	7.5	7.0	7.0	7.0	7.0	7.0	7.0	6.5	10.0	10.0	9.0	9.0	9.0	7.3
							RIDE	8.1	7.9	7.8	7.8	7.8	7.7	7.7	7.6	7.6	7.5	7.5	7.5	7.4	7.2
2080205	0.000	9.163	C	2025		0012															
28030001	7.790	9.184	C	1	1	40	CRACKING	7.0	7.0	7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	
16			2	3.4		6100	RIDE	8.0	8.0	7.7	7.6	7.4	8.1	8.0	7.8	7.2	8.0	7.8	7.7	7.9	
HARLEY CIR( 7.9R)								FC125													
2080202	0.000	9.184	C	2002		0012	CRACKING	9.5	9.5	9.5	7.0	7.0	7.0	7.0	6.0*	6.0*	6.0*	5.5*	5.5*	3.5*	3.4
ANDERSON COLUMBIA CO., INC(2004)								SPRIDE													
2080205	0.000	9.163	C	2025		0012		7.8	7.7	7.7	7.7	7.4	7.4	7.5	7.3	7.3	7.2	7.2	7.1	7.1	6.9
28040000	0.000	5.708	C	1	1	60	CRACKING	7.0	7.0	7.0	6.5	6.5	6.5	6.5	6.5	6.5	6.5	3.5*	10.0	10.0	10.0
18			2	7.0		900	RIDE	8.6	8.7	8.2	8.2	7.8	7.6	7.8	7.6	7.7	7.8	8.6	8.2	8.3	
SW 206 AVE( 1.8L)								FC125													
2079732	0.000	5.509	C	2007		0221	CRACKING	10.0	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	7.0	7.0	5.7
ANDERSON COLUMBIA CO., INC(2009)								SPRIDE													
							RIDE	8.0	7.7	7.1	7.2	7.5	7.4	7.0	7.0	7.1	7.0	6.6	6.8	6.6	5.9
28050000	0.000	0.379	C	1	7	25	CRACKING	9.5	9.5	9.5	9.5	9.5	9.0	9.0	9.0	9.0	6.5	6.5	6.5	6.5	
230			2	2.3		4000	RIDE	5.6*	5.8*	5.9*	5.4*	7.2	6.4	6.5	6.5	7.0	6.6	6.4	6.4	6.3	
SR 200( 0.0C)								FC125													
							CRACKING	6.5	6.5	6.5	6.5	5.5*	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	10.0	
							RIDE	6.3	6.2	5.0*	4.7*	4.4*	4.4*	4.5*	4.3*	4.4*					
28050000	0.379	3.843	C	1	1	55	CRACKING	10.0	10.0	10.0	9.5	9.5	8.0	8.0	8.0	7.0	6.5	6.5	6.5	6.5	
230			2	6.2		2100	RIDE	8.8	8.8	8.2	8.7	8.7	8.2	8.1	8.0	8.1	7.9	7.8	7.3	7.4	
REDGRAVE ST( 0.4R)								FC125R													
4244821	0.694	3.843	C	2013		0012	CRACKING	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	6.0*	6.0*	3.8
V. E. WHITEHURST & SONS, I(2014)								SPRIDE													
4244823	0.379	3.843	C	2027		0012		7.1	6.8	8.5	8.3	8.2	7.9	7.6	7.0	6.9	6.5	6.0*	5.8*	5.5*	3.9
28060000	0.000	0.657	C	1	1	55	CRACKING	9.5	9.5	9.5	8.0	8.0	7.0	8.0	8.0	6.5	4.5*	10.0	10.0	10.0	
231			2	5.6		3900	RIDE	7.7	7.9	8.0	8.3	8.2	7.7	7.6	7.3	7.7	7.5	8.2	7.8	8.1	
SW 114 ST( 0.3L)								FC125													
2079783	0.000	0.671	C	2007		0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	7.5	7.0	6.0*	6.0*	5.5*	4.6
ANDERSON COLUMBIA CO., INC(2009)								SPRIDE													
							RIDE	7.8	7.4	7.3	7.2	7.3	7.3	7.3	7.1	7.3	7.3	7.3	7.3	7.3	6.8
28090000	0.000	3.560	C	1	1	55	CRACKING	6.5	6.5	4.5*	3.5*	2.5*	2.5*	2.5*		10.0	10.0	10.0	10.0	10.0	
21			2	7.3		9500	RIDE	7.9	7.6	7.5	7.3	5.8*	6.2*	6.1*		8.4	8.3	8.4	8.3	8.2	
SE 16TH ST( 0.8L)								FC125M													
							CRACKING	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	6.0*	5.5*	10.0	10.0	10.0	
							RIDE	8.1	8.1	8.1	8.0	7.9	7.8	7.8	7.7	7.7	7.7	8.3	8.3	8.3	8.3
28125000	0.000	7.166	R	1	1	70	CRACKING									10.0	10.0	10.0	10.0	10.0	
223	A301		2	24.9		21500	RIDE									8.8	8.7	8.6	8.6	8.2	
N END BR #280061( 0.0C)								FC5M													
							CRACKING														
							RIDE														
28125000	0.000	7.166	L	1	1	70	CRACKING									10.0	10.0	10.0	10.0	10.0	
223	A301		2	24.9		21500	RIDE									8.9	8.7	8.6	8.6	8.1	
N END BR #280061( 0.0C)								FC5M													
							CRACKING														
							RIDE														

\*\*\* INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.  
 \*\*\* INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.  
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.  
 2029 FORECASTED BY SIMPLE LINEAR REGRESSION (REG).