

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = COLUMBIA																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR													
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS		2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	FUTURE
INTERSECT AT (MP SIDE)							=====														
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKMX-P																
CONTRACTOR (AGE_ONE YEAR)					ASTYPE																
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKMX-F																(PMRS)
29001000	0.000	0.363	C	1	1	45	CRACKING														
100A 441				2	3.6	7200	RIDE														
SR 25(0.0C)						FC125M															
4432821	0.026	0.354	C	2022	0012	CRACKING															
ANDERSON COLUMBIA CO., INC(2023)						SPRIDE							3.0*	3.0*	3.0*	3.0*	3.0*	10.0	10.0	9.1	8.0
													6.3	6.2	6.8	7.3	6.4	8.0	7.1	7.0	6.6
29002000	0.000	3.471	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.0	7.0	7.0	
10A				2	3.6	16800	RIDE	8.5	8.3	8.5	8.5	8.0	7.9	7.7	7.3	7.6	7.7	7.1	7.0	7.0	
DUVAL ST(0.0C)						FC125M															
4305561	0.959	3.471	R	2016	0012	CRACKING		7.0	7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.4	5.5*
ANDERSON COLUMBIA CO., INC(2017)						SPRIDE		6.9	7.4	6.6	7.0	8.0	7.8	7.5	7.6	7.6	7.4	7.4	7.1	7.1	6.7
29002000	0.000	3.471	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	
10A				2	3.6	16800	RIDE	8.3	8.5	8.4	8.4	7.8	7.5	7.1	6.8	7.2	7.2	7.1	7.0	7.0	
DUVAL ST(0.0C)						FC125M															
4305561	0.959	3.471	L	2016	0012	CRACKING		7.0	7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.5	5.5*
ANDERSON COLUMBIA CO., INC(2017)						SPRIDE		6.9	7.4	6.6	7.0	8.0	7.8	7.5	7.6	7.6	6.9	6.8	6.6	6.6	6.2
29010000	0.000	4.490	C	1	1	60	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	6.0*	6.0*	
10 90				2	6.1	7321	RIDE	8.7	9.0	8.9	8.8	8.5	8.6	8.3	8.4	8.6	8.4	8.4	8.3	8.2	
BELL LAKE CT(0.5L)						FC125W															
4244931	0.687	4.493	C	2013	0012	CRACKING		6.0*	4.0*	10.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.0	7.0	6.5	4.5*
ANDERSON COLUMBIA CO., INC(2015)						SPRIDE		8.1	8.1	8.5	8.4	8.5	8.4	8.3	8.4	8.4	8.4	8.2	8.4	8.3	7.9
29010000	4.490	5.957	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	6.0*	6.0*	
10 90				2	6.1	22500	RIDE	8.7	9.0	8.9	8.8	8.5	8.6	8.3	8.4	8.1	8.1	7.9	7.8	7.9	
SW EXECUTIVE DR(4.8R)						FC125W															
						CRACKING		6.0*	6.0*	6.0*			10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	6.5
(2018)						RIDE		7.6	7.7	7.7			7.9	7.6	7.7	7.6	7.7	7.5	7.6	7.5	7.1
29010000	5.957	6.900	R	1	1	45	CRACKING	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.0	
10 90				2	6.1	30000	RIDE	7.1	7.4	6.4*	8.6	8.1	8.3	8.0	8.1	8.1	8.1	7.9	7.9	7.9	
CR 252B(6.2R)						FC125M															
4433131	5.908	6.775	R	2022	0012	CRACKING		8.0	7.0	7.0	5.5*		6.0*	3.5*	3.5*	3.5*	3.5*		10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC(2024)						SPRIDE		7.8	7.8	7.8	7.7		7.5	7.8	8.5	8.5	8.4		8.1	8.1	7.7
29010000	6.900	9.137	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	
10 90				3	6.1	30000	RIDE	8.6	8.6	8.4	8.4	8.0	8.1	8.0	7.8	8.2	8.2	7.7	7.6	7.7	
REAL RD(7.3C)						FC125M															
4433131	6.775	9.065	R	2022	0012	CRACKING		8.5	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.6	7.0	7.0		10.0	9.0
ANDERSON COLUMBIA CO., INC(2024)						SPRIDE		7.8	7.7	7.8	7.6	7.7	7.5	7.6	7.6	7.6	7.6	7.5		8.7	8.2
29010000	9.137	9.208	R	1	6	45	CRACKING	3.5*	3.5*	3.5*	1.0*	1.0*	1.0*	1.0*	10.0	10.0	10.0	10.0	10.0	8.5	
10 90				2	6.1	19600	RIDE	7.4	7.6	7.4	7.2	6.4*	6.3*	5.8	8.1	7.7	7.3	7.3	7.1	7.3	
BAYA AVE(9.2R)						FC125M															
4433131	9.065	9.208	R	2022	0012	CRACKING		8.5	8.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	10.0		10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC(2024)						SPRIDE		7.2	7.8	7.7	7.7	7.6	7.6	7.7	7.5	7.5	8.2				
29010000	9.208	11.191	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	
10 90				2	6.1	14200	RIDE	7.4	8.5	8.4	8.4	7.7	7.9	7.5	7.7	7.4	7.8	7.6	7.7	7.5	
MCFARLANE AVE R(9.4R)						FC125M															
4412581	9.208	11.997	C	2020	0012	CRACKING		8.5	8.5	7.5	7.0	5.5*	5.5*	5.5*	5.5*	4.0*	10.0	10.0	10.0	9.6	8.5
ANDERSON COLUMBIA CO., INC(2022)						SPRIDE		7.2	7.3	6.9	7.1	6.9	7.1	7.3	7.3	7.3	8.2	8.1	8.1	8.1	7.7
29010000	11.191	12.000	C	1	1	45	CRACKING	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	
10 90				4	6.1	9300	RIDE	7.6	7.7	7.4	7.5	6.8	6.9	6.5	8.2	8.1	8.3	8.2	8.2	7.7	
MONROSE AVE NE(11.2C)						FC125M															
4412581	9.208	11.997	C	2020	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	10.0	10.0	10.0	9.4	8.0
ANDERSON COLUMBIA CO., INC(2022)						SPRIDE		7.7	7.8	7.6	7.7	7.6	7.3	7.4	7.2	7.4	8.2	8.1	8.1	8.0	7.6
29010000	12.000	14.664	R	1	1	55	CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	6.5	6.5	4.5*	10.0	
10 90				2	12.1	10500	RIDE	8.7	8.5	8.2	8.7	8.0	8.0	8.1	7.7	8.1	8.0	7.9	7.9	7.8	
LLEWELLYN AVE SE(12.0R)						FC5															
2083663	12.069	14.321	R	2011	0226	CRACKING		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	6.5	6.5	6.5	4.5*	4.1*	0.0*
ANDERSON COLUMBIA CO., INC(2012)						SPRIDE		7.9	8.1	7.9	8.2	8.1	8.1	8.2	8.1	8.3	8.2	8.1	8.1	8.0	7.8
2083665	12.008	14.663	C	2027	0012																

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = COLUMBIA

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS	=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
INTERSECT AT (MP SIDE)																						
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKM-F	ASTYPE		2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030	
CONTRACTOR (AGE ONE YEAR)																					(PMRS)	
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKM-F																	
29010000	14.664	20.891	C	1	1 60	CRACKING	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0			
10 90			2	12.1	7200	RIDE	8.6	8.7	8.5	8.6	7.7	7.7	7.3	7.3	8.6	8.5	8.4	8.4	8.1			
BILLY CRAIG CT NE(14.7L)																						
2083662	14.920	17.791	C	2007	0012	CRACKING	10.0	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	5.5*	5.5*	5.5*	3.5*	3.5*	0.5*		
ANDERSON	COLUMBIA	CO., INC(2008)				RIDE	8.0	8.1	7.8	7.8	7.9	7.7	7.6	7.9	7.8	7.8	7.8	7.6	7.5	7.1		
2083664	14.663	20.891	C	2027	0012																	

29010000	12.000	14.664	L	1	1 55	CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	6.5	6.5	6.0*	10.0			
10 90			2	12.1	10500	RIDE	8.8	8.8	8.5	8.5	8.2	8.2	8.0	8.2	8.2	8.1	8.0	7.9	8.2			
CR 100(12.1L)																						
2083663	12.069	14.321	L	2011	0026	CRACKING	10.0	10.0	10.0	9.0	9.0	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	3.6*	0.0*		
ANDERSON	COLUMBIA	CO., INC(2012)				SPRIDE	8.1	8.3	8.1	8.3	8.3	8.2	8.3	8.3	8.3	8.3	8.1	8.1	8.1	7.9		
2083665	12.008	14.663	C	2027	0012																	

29010000	9.208	11.191	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5			
10 90			2	6.1	14200	RIDE	8.4	8.6	8.0	8.4	7.8	8.0	7.7	7.7	7.8	7.9	7.9	7.7	7.5			
DUVAL ST W(9.3L)																						
4412581	9.208	11.997	C	2020	0012	CRACKING	8.5	8.5	7.5	7.0	5.5*	5.5*	5.5*	5.5*	4.0*	10.0	10.0	10.0	9.7	8.5		
ANDERSON	COLUMBIA	CO., INC(2022)				SPRIDE	7.4	7.3	6.9	7.1	6.9	7.1	7.3	7.3	7.5	8.2	8.1	7.9	8.0	7.6		

29010000	9.137	9.208	L	1	6 45	CRACKING	6.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*	10.0	10.0	10.0	9.0	8.5	8.5			
10 90			2	6.1	19600	RIDE	7.2	7.3	7.1	7.0	6.0*	6.0*	5.3*	8.1	7.8	7.8	7.7	7.9	7.9			
EDISON WAY(9.2L)																						
4433131	9.065	9.208	L	2022	0012	CRACKING	8.5	8.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	10.0		10.0	10.0	9.0		
ANDERSON	COLUMBIA	CO., INC(2024)				SPRIDE	7.7	7.8	7.7	7.7	7.6	7.6	7.7	7.5	7.3	8.2						

29010000	6.884	9.137	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5			
10 90			3	6.1	30000	RIDE	8.7	8.7	8.5	8.5	7.9	7.9	7.8	7.7	8.0	8.0	9.0	7.8	7.5	7.6		
BROOKSIDE AVE L(7.0L)																						
4433131	6.775	9.065	L	2022	0012	CRACKING	8.5	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.0	7.0		10.0	10.0	9.0		
ANDERSON	COLUMBIA	CO., INC(2024)				SPRIDE	7.5	7.7	7.8	7.6	7.7	7.5	7.6	7.6	7.8	7.9		8.6	8.4	8.0		

29010000	5.957	6.884	L	1	1 45	CRACKING	7.0	7.0	7.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0		
10 90			2	6.1	30000	RIDE	7.8	8.0	7.7	8.7	8.2	8.4	7.9	8.0	8.3	8.2	7.7	7.7	7.8			
NW HARVEY WAY(6.2L)																						
4433131	5.908	6.775	L	2022	0012	CRACKING	8.5	7.0	7.0	5.5*		6.0*	3.5*	3.5*	3.5*	3.5*		10.0	10.0	9.0		
ANDERSON	COLUMBIA	CO., INC(2024)				SPRIDE	7.6	7.8	7.8	7.7		7.5	7.8	8.5	8.4	8.4		8.5	8.2	7.8		

29010000	4.490	5.957	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.5	7.0	6.0*	6.0*			
10 90			2	6.1	22500	RIDE	8.7	9.0	8.9	8.8	8.5	8.6	8.3	8.4	8.2	8.1	7.9	7.8	7.9			
BROWN RD(4.8L)																						
						CRACKING	6.0*	6.0*	6.0*													
						RIDE	7.6	7.7	7.7			10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0		

29020000	0.000	4.326	C	1	2 60	CRACKING	10.0	10.0	10.0	8.5	7.0	7.0	6.0*	5.5*	4.0*	4.0*	10.0	10.0	10.0			
47			2	7.3	2689	RIDE	8.9	8.7	8.8	8.7	7.9	8.0	7.8	7.4	7.1	7.0	8.6	8.6	8.5			
C-138(0.3R)																						
2084171	0.000	4.312	C	2009	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	7.5	7.5	7.5	7.5	6.7	4.0*		
ANDERSON	COLUMBIA	CO., INC(2010)				SPRIDE	8.5	8.2	8.3	8.1	8.1	8.0	8.1	7.9	8.0	7.9	7.9	7.8	7.8	7.4		

29020000	4.326	4.963	C	1	1 35	CRACKING	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	8.5	8.5			
47			2	5.9	5000	RIDE	7.5	8.3	8.5	8.6	7.9	8.3	8.1	8.1	8.3	7.9	8.0	7.9	7.8			
SW WELL ST(4.4C)																						
						CRACKING	8.5	7.0	7.0	7.0	6.5	6.0*	5.5*	10.0	10.0	10.0	10.0	9.0	9.1	7.5		
						RIDE	7.7	7.7	7.6	7.6	7.6	7.5	7.6	8.3	8.2	8.1	7.9	7.7	7.7	7.3		
4454021	4.325	18.676	C	2023	0012																	
29020000	4.963	18.000	C	1	7 60	CRACKING	7.5	7.5	5.5*	5.0*	5.0*	10.0	10.0	9.5	9.5	9.5	9.5	8.5	8.5			
47			2	5.9	5900	RIDE	8.0	7.8	7.6	7.5	6.0*	8.3	8.1	8.1	8.1	7.9	8.0	7.9	7.8			
DEESE LN(5.1L)																						
						CRACKING	8.5	7.0	7.0	7.0	6.5	6.0*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	10.0	9.0		
						RIDE	7.7	7.7	7.6	7.6	7.6	7.5	7.6	7.4	7.5	7.4	7.3	7.3	8.4	8.0		

29020000	18.000	18.989	R	1	7 45	CRACKING	10.0	10.0	8.5	7.5	7.5	10.0	10.0	9.5	10.0	10.0	10.0	10.0	9.0			
47			2	5.9	13500	RIDE	8.5	8.4	8.3	8.1	7.4	8.3	8.1	8.1	8.0	7.8	7.8	7.9	7.7			
ARUID DR SW(18.2R)																						
						CRACKING	9.0	9.0	9.0	8.0	8.0	8.0	6.5	6.5	6.5	6.5	6.5	5.5*	10.0	9.0		
						RIDE	7.5	7.7	7.5	7.1	7.0	7.3	7.3	7.3	7.4	7.2	7.4	7.3	8.0	7.6		

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

ALL SYSTEM PAVEMENT CONDITION FORECAST

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

```

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

```

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = COLUMBIA

RDWYID	SR	US	BMP	G_BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	RATINGS	SURVEYED YEAR										FUTURE			
INTERSECT AT (MP SIDE)												2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	W_KMX-P							2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030
CONTRACTOR (AGE ONE YEAR)					ASTYPE																			(PMRS)	
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	W_KMX-F																				
29030000	20.509	20.835	L	1	8 45	CRACKING	8.5	8.5	8.5	8.5	10.0	6.5	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
25 41			2	7.6	9900	RIDE	8.2	7.4	7.1	7.3	8.0	7.0	6.6	6.7	8.5	8.3	8.1	7.9	7.7						
					FC125M																				
2083522	20.509	20.713	C	2007	0012	CRACKING	10.0	8.5	8.5	7.5	7.5	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	4.0*		
ANDERSON	COLUMBIA CO.,	INC(2008)			SPRIDE		7.7	7.7	7.6	7.5	7.6														
2083523	10.344	20.832	C	2022	0012																				
29030000	9.664	10.377	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0		8.5	8.5	8.5	9.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.5	
25 41			2	9.0	5000	RIDE	8.2	8.1	7.6	8.3		7.5	7.2	7.4	7.6	7.2	7.1	7.1	7.1	7.1	7.1	7.1	7.1	7.0	
HOWELL ST SW(9.9L)					FC125M																				
						CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.5	7.5	7.5	7.5	6.0*	5.5*	3.0*
					(2013)	RIDE	8.0	8.1	8.0	7.8	7.8	7.7	7.6	7.7	7.6	7.5	7.4	7.2	7.2	7.2	7.2	7.2	7.1	7.1	6.7
29040000	0.000	0.720	R	1	1 45	CRACKING	7.0	7.0	5.5*	3.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
25 41			2	13.0	10000	RIDE	7.5	7.3	7.1	7.0		7.8	7.9	7.5	7.7	7.9	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8	
DUVAL ST(0.0C)					FC125																				
4361781	0.031	1.261	R	2021	0012	CRACKING	9.0	8.5	8.5	7.5	5.5*	5.5*	4.0*	4.0*	4.0*	4.0*	4.0*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	10.0	9.0
ANDERSON	COLUMBIA CO.,	INC(2023)			SPRIDE		7.7	7.6	7.7	7.5	7.5	7.5	7.4	7.6	7.6	7.3	8.1	7.2	7.3	7.3	7.3	7.3	7.3	6.9	
29040000	0.720	1.934	R	1	1 45	CRACKING	8.5	8.5	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
25 41			1	13.0	10000	RIDE	8.6	7.8	7.8	7.7		8.5	8.2	8.1	8.3	8.3	8.2	8.2	8.2	8.2	8.2	8.2	8.2	8.0	
LONG ST NW(0.7C)					FC125M																				
						CRACKING	8.5	7.5	7.5	7.0	5.5*	5.5*	4.0*	4.0*	4.0*	4.0*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	10.0	9.0	
					(2023)	RIDE	7.9	7.8	7.3	7.8	7.7	7.6	7.6	7.9	7.8	7.8	8.1	8.1	8.1	8.1	8.1	8.1	8.0	8.0	7.6
29040000	1.934	4.149	C	1	1 60	CRACKING	8.5	7.5	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	7.5	
25 41			2	13.0	8800	RIDE	8.6	8.5	8.3	8.2		8.4	8.3	8.4	8.5	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.3	8.3	
MOORE RD NW(3.0C)					FC125M																				
						CRACKING	7.5	7.0	7.0	7.0	5.5*	6.5	4.5*	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	9.0	
					(2023)	RIDE	8.1	8.0	8.0	7.9	7.8	7.9	7.8	7.9	7.9	7.9	7.8	8.6	8.4	8.4	8.4	8.4	8.4	8.0	
29040000	4.149	4.788	R	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
25 41			2	13.0	8800	RIDE	8.9	8.9	8.8	8.9	8.4	8.5	8.2	8.1	8.1	8.0	7.9	7.9	7.9	7.9	7.9	7.9	7.9	7.9	
CR 25A NW(4.3R)					FC125M																				
						CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.5	6.5	5.5*	5.5*	3.0*	
					(2013)	RIDE	8.2	8.3	8.2	8.0	7.9	7.9	7.7	7.7	7.6	7.7	7.5	7.4	7.4	7.4	7.4	7.4	7.4	7.4	7.0
29040000	4.788	11.480	C	1	1 60	CRACKING	7.5	7.5	7.5	7.0	5.0*	3.0*	3.0*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
25 41			2	13.0	5700	RIDE	8.4	8.4	8.1	8.0	7.2	7.0	6.6	6.4*	8.6	8.5	8.4	8.5	8.5	8.5	8.5	8.5	8.5	8.4	
FLAMINGO	GLEN NW(5.0L)				FC95M																				
2083893	4.788	11.480	C	2007	0012	CRACKING	10.0	8.5	8.5	8.5	8.5	7.0	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.1*	2.0*	
ANDERSON	COLUMBIA CO.,	INC(2008)			RIDE		8.3	8.3	8.2	8.1	8.1	8.1	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0	7.9	7.8	7.8	7.4
2083895	4.837	11.480	C	2027	0012																				
29040000	4.149	4.788	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
25 41			2	13.0	8800	RIDE	8.1	8.5	8.3	8.3	7.6	7.8	7.7	7.7	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.7	7.8	
					FC125M																				
						CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	7.0	7.0	6.5	5.5*	5.5*	5.5*	3.0*			
					(2013)	RIDE	8.1	8.2	8.1	7.9	7.8	7.8	7.6	7.8	7.6	7.6	7.4	7.3	7.3	7.3	7.3	7.3	7.3	6.9	
29040000	0.000	1.934	L	1	1 45	CRACKING	7.0	7.0	7.0	3.0*		10.0	10.0	10.0	10.0	8.3	7.8	8.1	8.0	8.5	8.5	8.5	8.5	8.5	
25 41			2	13.0	10000	RIDE	6.7	6.2*	7.0	7.0		8.3	7.8	8.1	8.0	8.4	7.7	8.1	7.7	8.1	7.7	7.6			
DUVAL ST(0.0C)					FC125M																				
4361781	0.031	1.261	L	2021	0012	CRACKING	8.5	8.5	8.5	8.5	7.5	6.0*	6.0*	6.0*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	
ANDERSON	COLUMBIA CO.,	INC(2023)			SPRIDE		7.9	7.6	7.8	7.6	7.9	7.7	7.7	7.8	7.8	7.7	8.0	7.7	7.7	7.7	7.7	7.6	7.6	7.2	
29050000	0.000	7.219	C	1	8 60	CRACKING	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	
20 27			2	7.3	7300	RIDE	8.6	8.5	8.8	8.8	8.4	8.6	8.4	8.4	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.4	8.4	
RIVER RISE STATE PK(0.3R)					FC125																				
2084181	0.000	12.590	C	2001	0012	CRACKING	9.0	8.5	8.5	8.5	8.0	7.0	7.0	7.0	6.0*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	3.5*		
ANDERSON	COLUMBIA CO.,	INC(2002)			SPRIDE		8.4	8.4	8.3	8.0	8.0	8.1	8.1	8.0	8.1	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0		
2084183	0.000	12.590	C	2022	0012																				
29050000	7.219	7.968	C	1	8 30	CRACKING	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	
20 27																									

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = COLUMBIA																										
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR														FUTURE				
SR	US	G BMP	G EMP	LN	%T	AADT	RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013-2025				2030 (PMRS)	
INTERSECT AT (MP SIDE)	W BMP	W EMP	RW	FY-P	WKMX-P	ASTYPE	=====																			
ITMSEG-P	CONTRACTOR (AGE ONE YEAR)							2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025						
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKMX-F																					
29050000	7.968	12.590	C	1	8 60	CRACKING		5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5					
20 27			2	7.3	6500	RIDE		8.7	8.6	8.8	8.8	8.5	8.6	8.4	8.5	8.6	8.5	8.6	8.5	8.4	8.4					
CENTERVILLE AVE SW(8.5R)					FC125																					
2084181	0.000	12.590	C	2001	0012	CRACKING		9.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	6.0*	6.0*	6.0*							
ANDERSON COLUMBIA CO., INC(2002)					SPRIDE			8.4	8.5	8.3	8.0	8.0	8.0	8.0	7.9	7.9	8.0	7.9	7.8							
2084183	0.000	12.590	C	2022	0012																					
29060000	0.000	7.350	C	1	1 60	CRACKING		3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	8.5	8.5						
100			2	11.9	4400	RIDE		7.3	7.9	7.4	8.9	8.4	8.7	8.6	8.6	8.7	8.7	8.7	8.6	8.4						
CR 242 SE(1.2C)					FC125M																					
4342971	0.000	7.350	C	2019	0012	CRACKING		7.0	7.0	5.5*	5.5*	3.5*	3.5*	3.0*		10.0	10.0	10.0	10.0	9.7	8.5					
PREFERRED MATERIALS, INC. (2021)					SPRIDE			8.4	8.4	8.2	8.2	8.1	8.1	8.0		8.8	8.9	8.9	8.9	8.8	8.4					
29060000	7.350	9.989	C	1	1 60	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5						
100			2	11.9	4400	RIDE		8.6	8.7	8.7	8.7	7.9	8.0	8.1	8.0	8.1	8.2	8.2	8.1	8.0						
ACADEMIC AVE SE(7.5R)					FC125A																					
4286941	7.354	9.915	C	2015	0012	CRACKING		7.5	7.5	7.5	7.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.9	7.0					
ANDERSON COLUMBIA COMPANY (2017)					SPRIDE			8.0	8.0	7.9	7.8	8.5	8.5	8.3	8.4	8.4	8.3	8.4	8.4	8.3	7.9					
29070000	0.061	2.652	C	1	1 45	CRACKING		8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.0	7.5	10.0	10.0	10.0						
25A 441			2	3.6	6400	RIDE		7.8	7.9	7.9	7.7	7.4	7.2	7.3	7.2	6.6	7.2	8.0	8.3	7.8						
SR 25(0.1C)					FC125																					
2084024	1.086	2.653	L	2009	0012	CRACKING		10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.2*	3.5*					
(2010)					RIDE			7.9	7.7	7.3	7.7	7.7	7.6	7.5	7.5	7.3	7.3	7.3	7.2	7.2	6.8					
29070000	2.652	3.000	C	1	4 30	CRACKING		5.8*	1.4*	3.2*	3.0*	2.3*	0.9*	0.5*	1.0*	0.0*	2.4*	2.0*	2.2*	1.2*						
25A 441			2	3.6	5200	RIDE		6.8	7.2	6.9	7.1	5.8	5.7	5.2*	5.6	5.6	5.9	6.3	6.1	5.7						
SE CAMP ST(2.7R)					LGD																					
2083861	2.524	3.005	C	1992	0217	CRACKING		0.8*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.1*	0.6*	0.0*					
ANDERSON COLUMBIA CO., INC(1997)					RIDE			6.0	6.1	5.6	6.5	6.4	6.4	6.6	6.2	6.0	5.9	6.0	5.9	5.9	5.7					
29070000	3.000	3.031	C	1	6 30	CRACKING		8.5	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	10.0	10.0	10.0						
25A 441			2	3.6	5200	RIDE		4.7*	5.0*	5.6	4.9*	4.9*	4.5*	4.0*	4.2*	4.0*	4.2*	5.4*	5.0*	4.9*						
DUVAL ST(3.0C)					LGD																					
(2025)					CRACKING			10.0	10.0	10.0	10.0	10.0		8.5	8.5	8.5	8.5	8.5	7.0	8.5	8.0					
					RIDE			5.2*	5.1*	5.0*	4.7*	4.6*														
29070000	4.000	6.513	R	1	1 45	CRACKING		9.0	9.0	9.0	9.0	9.0	9.0	7.0	10.0	9.0	9.0	9.0	9.0	9.0						
47 441			2	3.6	6600	RIDE		6.7	6.7	6.7	7.6	6.8	6.9	6.4	8.1	8.2	8.1	8.1	8.1	7.9						
BASCOM NORRIS DR(4.0R)					FC125																					
2084022	4.011	6.513	C	2005	0012	CRACKING		9.0	8.0	6.5	6.5	6.5	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	3.5*	0.5*					
ANDERSON COLUMBIA CO., INC(2007)					RIDE			7.6	7.6	7.2	7.6	7.5	7.4	7.7	7.6	7.5	7.3	7.1	7.0	6.9	6.5					
4454341	3.971	6.490	C	2024	0012																					
29070000	6.513	6.819	R	1	1 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0						
47 441			1	9.1	3400	RIDE		8.4	8.3	8.3	8.3	7.7	7.7	7.6	7.6	7.6	7.5	7.6	7.5	7.4						
(2013)					FC125M																					
					CRACKING			10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.5	7.5	7.5	7.5	7.5	6.5	4.0*					
					RIDE			8.4	8.4	8.2	7.7	7.7	7.6	7.5	7.5	7.6	7.5	7.5	7.4	7.4	7.0					
29070000	6.819	8.284	C	1	1 60	CRACKING		7.0	7.0	7.0	7.0	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0						
47 441			2	9.1	3400	RIDE		8.6	8.5	8.5	8.2	7.5	7.6		8.4	8.5	8.4	8.3	8.3	8.2						
FRASER GREEN RD(7.0R)					FC125																					
2084022	6.819	8.284	C	2005	0012	CRACKING		10.0	8.5	8.5	7.5	7.5	7.0	6.0*	6.0*	5.5*	5.5*	3.5*	3.5*	3.5*	0.5*					
ANDERSON COLUMBIA CO., INC(2007)					RIDE			8.1	8.0	7.8	7.8	7.8	7.8	7.8	7.8	7.6	7.6	7.6	7.4	7.4	7.0					
2084026	6.881	15.971	C	2023	0012																					
29070000	8.284	15.991	C	1	1 60	CRACKING		10.0	10.0	10.0	7.0	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0						
47 441			2	9.1	750	RIDE		8.8	8.6	8.5	8.5	7.7	7.8	7.5	7.4	7.4	8.5	8.4	8.4	8.2						
NW ZACK JONES GLN(8.5L)					FC125																					
2084023	8.277	15.968	C	2008	0012	CRACKING		10.0	7.0	7.0	7.0	7.0	6.5	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	0.5*					
HUBBARD CONSTRUCTION COMPA(2009)					SPRIDE			8.0	8.0	7.6	7.8	7.7	7.8	7.8	7.6	7.5	7.5	7.4	7.2	7.2	6.8					
2084026	6.881	15.971	C	2023	0012																					
29070000	15.991	32.016	C	1	1 60	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.0						
47 441			2	9.1	750	RIDE			8.7	8.7	8.7	8.2	8.2	8.0	7.9	8.0	7.8	7.8	7.7	7.5						
NE REGISTER LN(16.2R)					FC125M																					
4244921	15.991	32.016	C	2013	0012	CRACKING		7.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.5	6.0*	5.5*	3.5*					
ANDERSON COLUMBIA CO., INC(2014)					SPRIDE			7.4	8.9	8.3	8.3	8.2	8.1	8.1	8.0	7.8	7.9	8.0	7.9	7.8	7.4					
2083897	15.990	32.016	C	2029	0012																					

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = COLUMBIA																							
RDWYID	SR	US	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR											FUTURE	
INTERSECT	AT	(MP)	(SIDE)						=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	
ITMSEG-P	W BMP	W_EMP	W_RW	FY-P	W_KMX-P																		
CONTRACTOR	(AGE ONE YEAR)				ASTYPE					2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030 (PMRS)
ITMSEG-F	W_BMP	W_EMP	W_RW	FY-F	W_KMX-F																		
29070000	6.513	6.819	L	1	1 45	CRACKING				10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	
47 441			1	9.1	3400	RIDE				8.2	8.1	8.2	8.0	7.6	7.8	7.7	7.6	7.6	7.7	7.6	7.5	7.4	
					FC125M																		
				(2013)		CRACKING				10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.5	7.5	7.0	7.0	7.0	6.5	4.0*
						RIDE				8.4	8.4	8.2	7.7	7.7	7.6	7.5	7.5	7.6	6.9	7.1	6.9	6.8	6.4
29070000	4.000	6.513	L	1	1 45	CRACKING				9.0	9.0	9.0	9.0	9.0	7.5	6.5	10.0	10.0	10.0	9.0	9.0	9.0	
47 441			2	3.6	6600	RIDE				7.7	7.8	7.7	7.6	7.1	7.0	6.8	8.3	8.4	8.4	8.1	8.1	7.9	
US-441/SR-100A(4.0L)					FC125																		
2084022	4.011	6.513	C	2005	0012	CRACKING				9.0	8.0	6.5	6.5	6.5	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	3.5*	0.5*
ANDERSON COLUMBIA CO., INC(2007)						RIDE				7.6	7.6	7.2	7.6	7.5	7.4	7.7	7.6	7.5	7.6	7.6	7.4	7.5	7.1
4454341	3.971	6.490	C	2024	0012																		
29080000	0.000	1.473	C	1	1 55	CRACKING				10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	10.0	10.0	
238			2	8.8	4400	RIDE				8.4	8.5	8.2	8.5	7.8	7.6	7.6	7.4	7.5	7.6	7.0	8.7	8.5	
SR 25 US 41 US 441(0.0C)					FC125M																		
2083932	0.000	1.472	C	2010	0226	CRACKING				10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.0	4.5*
ANDERSON COLUMBIA CO., INC(2011)						RIDE				8.3	8.4	8.2	8.2	8.1	8.1	7.9	8.1	8.1	8.0	7.9	7.8	7.8	7.4
29090000	0.000	10.245	C	1	1 60	CRACKING				9.0	9.0	7.0	7.0	7.0	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	
247			2	14.6	5200	RIDE				8.2	8.1	8.1	8.4	7.8	7.4	7.4	6.6	8.3	8.3	8.0	8.0	7.7	
RAMP FROM MARKET RD(0.2L)					FC125M																		
2084115	0.000	5.580	C	2007	0012	CRACKING				9.0	8.5	8.5	8.5	8.5	7.5	7.0	7.0	3.5*	3.5*	3.5*	3.5*	0.5*	
ANDERSON COLUMBIA CO., INC(2008)						RIDE				7.7	7.9	7.7	7.5	7.3	7.4	7.4	7.4	7.3	7.4	7.4	7.2	7.2	6.8
2084119	0.000	10.074	C	2027	0012																		
29090000	10.245	11.348	R	1	1 45	CRACKING				9.0	9.0		10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.0	
247			1	3.7	13000	RIDE				8.2	8.4		8.2	7.7	7.8	7.6	7.5	7.5	7.5	6.9	7.2	7.3	
LEISURE DR SW(10.4R)					FC4																		
				(2003)		CRACKING				8.0	8.0	8.0	8.0	8.0	7.0	6.5	6.5	6.5	6.5	6.5	6.5	5.5*	2.0*
4454351	10.074	11.348	C	2027	0012	RIDE				7.5	7.5	7.3	7.0	6.9	6.8	6.9	6.8	6.8	6.7	6.6	6.6	6.5	6.1
29090000	10.245	11.348	L	1	1 45	CRACKING				9.0	9.0		10.0	10.0	10.0	10.0	8.5	9.0	8.5	8.5	8.5	8.0	
247			1	3.7	13000	RIDE				8.2	8.4		8.2	7.7	7.8	7.6	7.5	7.5	7.7	6.9	7.2	7.3	
REAL TERR SW(10.4L)					FC4																		
				(2003)		CRACKING				8.0	8.0	8.0	8.0	8.0	7.0	6.5	6.5	6.5	6.5	6.5	6.5	5.5*	2.0*
4454351	10.074	11.348	C	2027	0012	RIDE				7.5	7.5	7.3	7.0	6.9	6.8	6.9	6.8	6.8	6.7	6.5	6.5	6.4	6.0
29110000	0.000	0.837	C	1	1 60	CRACKING				10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	7.5	7.5	
2			2	28.7	450	RIDE				8.7	8.4	8.6	8.5	7.7	8.1	7.9	7.5	8.0	7.8	7.9	8.0	7.9	
					FC125A																		
4244841	0.000	0.837	C	2015	0012	CRACKING				7.5	7.0	7.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.4	7.5	7.1	5.0*
ANDERSON COLUMBIA CO., INC(2016)						RIDE				7.9	7.9	7.8	8.4	8.4	8.4	8.3	8.1	7.9	7.7	7.4	7.1	7.1	6.7
29160000	0.000	2.243	C	1	1 55	CRACKING				6.0*	6.0*	3.5*	0.0*	0.0*	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	10.0	
136			2	7.2	2600	RIDE				8.1	8.0	7.9	7.8	6.2*	6.1*	6.1*	8.4	8.4	8.4	8.4	8.4	8.4	
NULL DR NW(0.9L)					FC125																		
2083712	0.000	2.243	C	2006	0012	CRACKING				10.0	9.0	9.0	9.0	7.5	7.5	7.0	7.0	6.0*	6.0*	5.5*	3.5*	3.5*	0.5*
ANDERSON COLUMBIA CO., INC(2007)						RIDE				8.2	8.2	8.0	8.0	8.0	8.0	7.8	7.8	7.7	7.6	7.6	7.6	7.4	7.0
29170000	0.000	6.455	R	4	1 70	CRACKING				10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.0	6.5	6.0*	6.0*	
8 I10	293.8	300.2	2 29.4		24000	RIDE				9.0	9.1	9.0	9.0	8.4	8.5	8.2	8.3	8.1	8.0	7.9	7.7	7.4	
					FC5M																		
2130743	0.000	9.522	C	2011	0012	CRACKING				10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.3	6.0*
ANDERSON COLUMBIA CO., INC(2013)						SPRIDE				8.4	8.5	8.4	8.7	8.7	8.6	8.7	8.7	8.9	8.9	8.9	8.8	8.7	8.6
29170000	6.455	16.297	R	4	1 70	CRACKING				10.0	10.0	9.0	6.5	4.5*	4.5*	3.5*	8.0		10.0	10.0	10.0	10.0	
8 I10	300.2	310.1	2 29.2		23924	RIDE				9.1	9.1	8.9	8.6	7.5	6.7	6.5	7.4		8.1	8.2	8.2	8.0	
					FC5M																		
4326411	5.125	16.154	C	2013	0012	CRACKING				10.0	10.0		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.3	6.0*
(2016)						RIDE				8.0	8.1		8.7	8.7	8.7	8.7	8.7	8.9	8.9	8.8	8.7	8.5	8.4
29170000	16.297	20.690	R	4	7 70	CRACKING				10.0	10.0	9.0	6.5	4.5*	4.5*	3.5*	8.0		10.0	10.0	10.0	10.0	
8 I10	310.1	314.4	2 29.2		23924	RIDE				9.1	9.1	8.9	8.6	7.5	6.7	6.5	7.4		8.1	8.2	8.2	8.0	
					FC5M																		
4434211	16.323	20.690	C	2022	0012	CRACKING				10.0	10.0	9.0	7.5	7.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	9.0
ANDERSON COLUMBIA CO., INC(2025)						SPRIDE				8.0	8.1	7.7	8.3	8.3	8.2	8.3	8.4	8.5	8.4	8.2	8.0	8.7	8.6

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

												DISTRICT = 2 COUNTY = COLUMBIA																					
RDWYID	SR	US	BMP	G BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	AADT	RATINGS	SURVEYED		YEAR										FUTURE								
INTERSECT	AT	(MP)	(SIDE)							=====			2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012								
ITMSEG-P	W BMP	W_EMP	RW	FY-P	WKM-X	P																											
CONTRACTOR	(AGE ONE YEAR)				ASTYPE								2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030							
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKM-X	F																			(PMRS)								
29170000	16.297	20.690	L	4	7	70	CRACKING						10.0	10.0	10.0	9.0	6.5	6.5	4.5*	3.5*		10.0	10.0	10.0	10.0								
8	I10	310.1	314.4	2	29.2	23924	RIDE						8.9	8.9	8.7	8.7	8.0	7.4	7.1	6.9		8.1	8.2	8.2	8.2								
						FC5M																											
4434211	16.323	20.690	C	2022	0012	CRACKING							10.0	10.0	10.0	9.0	9.0	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	9.0							
ANDERSON	COLUMBIA	CO., INC	(2025)			SPRIDE							8.1	8.2	8.0	8.5	8.4	8.4	8.5	8.5	8.6	8.5	8.4	8.2	8.9	8.8							
29170000	6.455	16.297	L	4	1	70	CRACKING						10.0	10.0	10.0	9.0	6.5	6.5	4.5*	3.5*		10.0	10.0	10.0	10.0								
8	I10	300.2	310.1	2	29.2	23924	RIDE						8.9	8.9	8.7	8.7	8.0	7.4	7.1	6.9		8.1	8.2	8.2	8.2								
						FC5M																											
4326411	5.125	16.154	C	2013	0012	CRACKING							10.0	10.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.6	5.5*							
				(2016)		RIDE							8.1	8.2		8.8	8.7	8.7	8.8	8.8	8.9	8.9	8.9	8.8	8.8	8.7							
29170000	0.323	6.455	L	4	1	70	CRACKING						10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	6.5	6.5								
8	I10	294.1	300.2	2	29.4	24000	RIDE						9.0	9.2	9.2	9.1	8.6	8.5	8.4	8.3	8.2	8.2	8.1	7.8	7.7								
						FC5M																											
2130743	0.000	9.522	C	2011	0012	CRACKING							10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.0	7.5	5.0*							
ANDERSON	COLUMBIA	CO., INC	(2013)			SPRIDE							8.4	8.5	8.4	8.7	8.7	8.7	8.8	8.8	8.9	8.9	8.8	8.8	8.8	8.7							
29170000	0.000	0.323	L	4	8	70	CRACKING						10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	6.5	6.5								
8	I10	293.8	294.1	2	27.1	29000	RIDE						9.0	9.2	9.2	9.1	8.6	8.5	8.4	8.3	8.2	8.2	8.1	7.8	7.7								
						FC5M																											
2130743	0.000	9.522	C	2011	0012	CRACKING							10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.0	7.5								
ANDERSON	COLUMBIA	CO., INC	(2013)			SPRIDE							8.4	8.5	8.4	8.7	8.7	8.7	8.8	8.8	8.9	8.9	8.8	8.8	8.8	8.7							
29180000	0.000	9.790	R	4	1	70	CRACKING						10.0	10.0	10.0	9.0	9.0	9.0	8.0	8.0	7.5	6.5	6.0*	6.0*									
93	I75	407.9	417.7	3	29.5	58000	RIDE						9.0	9.0	9.0	9.0	8.4	7.9	7.6	8.1	7.9	7.7	7.4	6.8									
						FC5M																											
2130713	0.000	9.802	C	2011	0012	CRACKING							10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	6.9	4.5*							
V. E. WHITEHURST & SONS,				I(2013)		SPRIDE							8.2	8.3	8.2	8.6	8.6	8.6	8.7	8.8	8.9	8.9	8.8	8.8	8.7	8.6							
29180000	9.790	15.304	R	4	7	70	CRACKING						10.0	10.0	10.0	9.0	9.0	9.0	7.0	7.0	7.0	10.0	10.0	10.0	10.0								
93	I75	417.7	423.2	3	29.5	65000	RIDE						8.9	8.9	8.9	8.8	8.2	8.0	7.9	7.9	7.9	8.3	8.3	8.2	8.1								
						FC2																											
4455471	9.802	15.318	C	2023	0012	CRACKING							10.0	10.0	10.0	10.0	10.0	9.0	7.5	7.5	7.5	6.5	6.5	6.5	10.0	9.0							
ANDERSON	COLUMBIA	CO., INC	(2025)			SPRIDE							7.9	8.1	7.9	8.4	8.4	8.3	8.4	8.5	8.6	8.6	8.5	8.5	9.0	8.9							
29180000	15.304	19.008	R	4	1	70	CRACKING						10.0	10.0	10.0	9.0	9.0	9.0	7.0	7.0	10.0	10.0	10.0	10.0	10.0								
93	I75	423.2	426.9	3	29.5	61500	RIDE						8.9	8.9	8.9	8.8	8.2	8.0	7.9	7.9	8.1	8.2	8.2	8.1	8.1								
						FC5M																											
4425811	15.318	19.002	C	2021	0012	CRACKING							10.0	10.0	10.0	9.0	9.0	7.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.7	8.5							
ANDERSON	COLUMBIA	CO., INC	(2023)			SPRIDE							7.8	7.9	7.7	8.1	8.1	8.1	8.3	8.3	8.4	8.2	9.1	9.1	9.0	8.9							
29180000	19.008	27.456	R	4	1	70	CRACKING						10.0	10.0	8.5	7.0	6.0*		10.0	10.0	10.0	9.0	9.0	8.5	8.5								
93	I75	426.9	435.3	3	30.7	48054	RIDE						9.0	9.0	8.7	8.5	8.3		8.3	8.3	8.2	8.1	7.9	7.8	7.8								
						FC5M																											
4327331	19.008	27.379	C	2016	0012	CRACKING							8.5	7.0	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.0							
ANDERSON	COLUMBIA	CO., INC	(2018)			SPRIDE							7.4	7.2	6.8	7.5		8.9	8.9	8.8	8.9	8.9	8.9	8.9	8.8	8.7							
29180000	27.456	30.447	R	4	7	70	CRACKING						10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	10.0	10.0								
93	I75	435.3	438.3	3	29.5	45000	RIDE						9.0	8.9	9.0	8.9	8.5	8.3	8.2	8.2	8.0	7.9	7.8	8.3	8.4								
						FC5M																											
4460451	27.379	30.447	C	2023	0012	CRACKING							10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.5	6.5	6.5	6.5	10.0	9.0	9.0							
ANDERSON	COLUMBIA	CO., INC	(2025)			SPRIDE							8.4	8.4	8.2	8.5	8.5	8.4	8.6	8.6	8.7	8.6	8.5	8.5	9.0	8.9							
29180000	27.456	30.447	L	4	7	70	CRACKING						10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	6.5	10.0	10.0								
93	I75	435.3	438.3	3	29.5	45000	RIDE						9.0	9.0	9.0	8.9	8.4	8.2	8.2	8.1	7.9	7.7	7.1	8.2	8.3								
						FC5M																											
4460451	27.379	30.447	C	2023	0012	CRACKING							10.0	10.0	10.0	1																	

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

							DISTRICT = 2 COUNTY = COLUMBIA																
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE			
SR	US	G BMP	G EMP	LN	%T	AADT	RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012			
INTERSECT	AT	(MP SIDE)					=====																
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKMX-P																		
CONTRACTOR	(AGE ONE YEAR)				ASTYPE			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030		
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKMX-F																(PMRS)		
29180000	15.315	19.008	L	4	1 70	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	6.5	10.0	10.0	10.0	10.0			
93 I75	423.2	426.9	3	29.5	61500	RIDE		8.8	9.0	8.5	8.8	8.2	8.1	7.9	7.8	8.2	8.1	8.1	8.1	8.1			
					FC5M																		
4425811	15.318	19.002	C	2021	0012	CRACKING		10.0	9.0	9.0	9.0	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	9.0		
ANDERSON	COLUMBIA CO., INC			(2023)	SPRIDE			7.9	7.8	7.5	8.1	8.1	8.0	8.3	8.3	8.3	8.1	9.1	9.1	9.1	9.0		
29180000	9.790	15.315	L	4	7 70	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	10.0	10.0	10.0	10.0			
93 I75	417.7	423.2	3	29.5	65000	RIDE		8.8	9.0	8.5	8.8	8.2	8.1	7.9	7.8	7.8	8.2	8.3	8.2	7.9			
					FC5M																		
4455471	9.802	15.318	C	2023	0012	CRACKING		10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.5	6.5	4.5*	4.5*	10.0	9.0		
ANDERSON	COLUMBIA CO., INC			(2025)	SPRIDE			7.8	7.9	7.7	8.3	8.3	8.3	8.3	8.3	8.6	8.5	8.4	8.4	9.1	9.0		
29180000	0.000	9.790	L	4	1 70	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5	6.0*	6.0*	6.0*				
93 I75	407.9	417.7	3	29.5	58000	RIDE		9.1	9.1	9.0	8.9	8.4	8.2	8.2	7.8	7.8	7.5	7.0	7.1				
					FC5M																		
2130713	0.000	9.802	C	2011	0012	CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	7.8	5.5*		
V. E. WHITEHURST & SONS, I				(2013)	SPRIDE			8.3	8.3	8.2	8.5	8.5	8.5	8.6	8.6	8.6	8.7	8.6	8.6	8.5	8.4		

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 "*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 "@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).