

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = DIXIE -----																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE	
SR	US	G_BMP	G_EMP	LN	#T	AADT	RATINGS	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2031
INTERSECT AT (MP SIDE)	W_BMP	W_EMP	RW	FY-P	WKM-X-P	ASTYPE	=====	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031
CONTRACTOR (AGE_ONE YEAR)	W_BMP	W_EMP	RW	FY-F	WKM-X-F																(PMRS)
30010000	0.000	15.492	R	1	1	65	CRACKING	3.5*	1.0*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	
55 19				2	13.6	6300	RIDE	8.2	8.2	7.9		8.1	8.4	8.5	8.4	8.4	8.3	8.2	8.0	7.8	
SW 37 AVE(1.0R)						FC5M															
4361721	0.000	14.990	C	2018		0012	CRACKING	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5
ANDERSON COLUMBIA CO., INC(2020)							SPRIDE	7.6	7.4	7.9	7.7	7.8	7.6	8.8	8.6	8.6	8.6	8.6	8.6	8.6	8.6
30010000	15.492	17.679	R	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5	
55 19				2	13.6	6300	RIDE	8.8	8.7	8.2	8.2	8.2	7.6	7.8	7.5	7.7	7.8	7.6	7.5	7.6	
CR 351A(15.7R)						FC125M															
4393571	15.485	17.084	R	2022		0012	CRACKING	7.5	7.5	7.5	7.5	7.5	7.0	5.5*	5.5*	5.5*		10.0	10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC(2024)							SPRIDE	7.5	7.2	7.2	7.1	6.5	7.0	6.8	6.8	6.6		8.3	8.2	8.0	7.6
30010000	17.679	18.256	R	1	1	45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5	7.0	
55 19				2	13.6	11000	RIDE	8.8	8.7	8.2	8.2	8.5	8.5	8.5	8.4	8.3	8.3	8.3	8.3	8.2	
SE BEAR LN(18.0R)						FC125M															
4376191	17.671	25.343	C	2019		0012	CRACKING	7.0	5.5*	5.5*	5.5*	5.5*	5.5*		10.0	10.0	10.0	10.0	9.7	10.0	8.5
ANDERSON COLUMBIA CO., INC(2021)							SPRIDE	8.1	8.0	8.0	7.9	7.9	8.0		8.6	8.5	8.5	8.5	8.3	8.2	7.8
30010000	18.256	25.344	R	1	1	65	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5	7.0	
55 19				2	13.6	15700	RIDE	8.8	8.7	8.2	8.2	8.5	8.5	8.5	8.4	8.3	8.3	8.3	8.3	8.2	
HOLLIS CHEWNING RD(18.4R)						FC5M															
4376191	17.671	25.343	C	2019		0012	CRACKING	7.0	5.5*	5.5*	5.5*	5.5*	5.5*		10.0	10.0	10.0	10.0	9.7	9.6	7.5
ANDERSON COLUMBIA CO., INC(2021)							SPRIDE	8.1	8.0	8.0	7.9	7.9	8.0		8.6	8.5	8.5	8.5	8.5	8.5	8.3
30010000	25.344	25.832	R	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	
55 19				2	13.6	15700	RIDE	8.8	8.6	8.4	8.4	8.4	7.9	8.3	8.0	8.4	8.3	8.1	8.1	8.0	
MADISON ST(25.7R)						FC125M															
2084641	25.450	29.216	C	1999		0221	CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.2	8.0	4.0*
ANDERSON COLUMBIA CO., INC(2002)							SPRIDE	8.4	8.3	8.3	8.3	8.3	8.3	8.3	8.1	8.2	8.1	8.1	8.1	8.2	7.8
30010000	25.832	29.216	R	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	7.0	7.0	6.5	6.5	6.5	6.5		
55 19				2	13.6	15700	RIDE	8.8	8.8	8.6	8.4	8.4	8.5	8.5	8.5	8.3	8.2	8.1	7.8		
CR-349/SE 349 HWY(25.8R)						FC5M															
4244831	25.832	29.216	C	2012		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.4	7.9	3.5*
ANDERSON COLUMBIA CO., INC(2014)							RIDE	8.2	8.2	8.4	8.4	8.4	8.3	8.3	8.3	8.3	8.3	8.3	8.3	8.3	8.1
30010000	25.832	29.216	L	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.0	6.5	6.5	6.5	6.5	6.5		
55 19				2	13.6	15700	RIDE	8.7	8.7	8.7	8.4	8.4	8.6	8.6	8.5	8.5	8.3	8.2	8.1		
CR 349(25.8L)						FC5M															
4244831	25.832	29.216	C	2012		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.3	7.8	3.5*
ANDERSON COLUMBIA CO., INC(2014)							RIDE	8.2	8.2	8.5	8.5	8.4	8.5	8.5	8.4	8.4	8.3	8.4	8.3	8.3	8.1
30010000	25.344	25.832	L	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.5	
55 19				2	13.6	15700	RIDE	8.7	8.7	8.4	8.4	8.0	8.0	9.0	9.0	9.0	8.1	7.7	7.7	7.9	
HATCH ST(25.5L)						FC125M															
2084641	25.450	29.216	C	1999		0221	CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	8.0	7.7	7.5	3.5*
ANDERSON COLUMBIA CO., INC(2002)							SPRIDE	8.2	8.3	8.0	8.0	8.1	7.9	8.1	7.9	7.7	7.8	7.8	7.7	7.7	7.3
30010000	18.256	25.344	L	1	1	65	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	
55 19				2	13.6	15700	RIDE	8.7	8.6	8.2	8.2	8.5	8.6	8.5	8.5	8.4	8.4	8.4	8.2	8.2	
GEORGIA PACIFIC PLANT EN(18.8L)						FC5M															
4376191	17.671	25.343	C	2019		0012	CRACKING	9.0	6.5	5.5*	5.5*	5.5*	3.5*		10.0	10.0	10.0	10.0	10.0	9.7	7.5
ANDERSON COLUMBIA CO., INC(2021)							SPRIDE	8.1	8.0	8.2	8.1	8.0	8.1		8.7	8.6	8.6	8.6	8.6	8.6	8.4
30010000	17.679	18.256	L	1	1	45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	
55 19				2	13.6	11000	RIDE	8.7	8.6	8.2	8.2	8.5	8.6	8.5	8.5	8.4	8.4	8.4	8.2	8.2	
BEAR LN SE(18.0L)						FC125M															
4376191	17.671	25.343	C	2019		0012	CRACKING	9.0	6.5	5.5*	5.5*	5.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	8.5
ANDERSON COLUMBIA CO., INC(2021)							SPRIDE	8.1	8.0	8.2	8.1	8.0	8.1		8.7	8.6	8.6	8.6	8.1	8.1	7.7
30010000	15.492	17.679	L	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5	
55 19				2	13.6	6300	RIDE	8.7	8.6	8.2	8.2	7.3	7.2	7.2	7.7	7.8	7.6	7.5	7.6		
CR-351A/NE 223 AVE(15.7L)						FC125M															
4393571	15.485	17.084	L	2022		0012	CRACKING	7.5	7.5	7.5	7.5	7.5	7.0	5.5*	5.5*	5.5*		10.0	10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC(2024)							SPRIDE	7.5	7.2	7.2	7.1	6.5	7.0	6.8	6.4	6.3		8.3	8.2	8.0	7.6

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @* INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = DIXIE -----																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE	
SR	US	G_BMP	G_EMP	LN	*T	AADT	RATINGS	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2031
INTERSECT AT (MP SIDE)	W_BMP	W_EMP	RW	FY-P	WKM	ASTYPE	*****														
ITMSEG-P	W_BMP	W_EMP	RW	FY-F	WKM	ASTYPE	*****														
CONTRACTOR (AGE_ONE YEAR)	W_BMP	W_EMP	RW	FY-F	WKM	ASTYPE	*****	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKM	ASTYPE	*****														
30010000	0.000	15.492	L	1	1	65	CRACKING	3.5*	1.0*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5	
55 19				2	13.6	6300	RIDE	8.3	8.2	8.0		8.0	8.3	8.5	8.4	8.4	8.3	8.1	7.9	7.7	
JONES RD(0.1L) FC5M																					
4361721	0.000	14.990	C	2018	0012		CRACKING	6.5	4.5*	4.5*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	9.8	9.8	7.5
ANDERSON	COLUMBIA CO., INC(2020)						SPRIDE	7.2	7.0	7.7	7.6	7.6	7.6	8.9	8.6	8.7	8.6	8.7	8.7	8.7	8.5

30030000	23.492	23.640	C	1	1	35	CRACKING	8.5	8.5	6.0*	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	9.5	9.5	
349				2	12.1	6600	RIDE	8.2	8.3	7.9	7.1	7.0	6.9	7.1	6.9	6.7	6.4	6.2			
SHOPPING ENT(23.6R) FC125M																					
2084472	23.492	23.593	L	2011	0012		CRACKING	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	8.0	8.0	7.4	7.5	4.5*
ANDERSON	COLUMBIA CO., INC(2012)						SPRIDE													4.2*	3.8*
2084473	23.507	39.021	C	2031	0012																

30030000	23.640	39.021	C	1	1	60	CRACKING	8.5	8.5	6.0*	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	
349				2	12.1	2815	RIDE	8.2	8.3	7.9	7.1	7.0	6.9	7.1	6.9	6.7	6.4*	6.2*	8.3	8.3	
JOHN O GREEN RD(23.7L) FC125M																					
2084472	29.037	39.021	C	2011	0012		CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.5	7.5	6.0*	7.0	6.5	6.2*	3.5*
ANDERSON	COLUMBIA CO., INC(2012)						SPRIDE	8.0	7.9	7.9	7.8	7.8	7.8	7.5	7.5	7.4	7.4	7.3	7.3	7.2	6.8
2084473	23.507	39.021	C	2031	0012																

30050000	0.000	1.518	C	1	7	60	CRACKING	8.5	8.0	8.0	7.0	7.0	7.0	6.5	5.5*	5.5*	5.5*		10.0	10.0	
51				2	8.7	600	RIDE	8.0	8.0	7.8	6.9	7.4	7.4	7.3	6.7	7.1	7.0		7.8	7.7	
FC125M																					
2100853	0.000	1.518	C	2025	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.9	10.0	9.0
ANDERSON	COLUMBIA CO., INC(2026)						RIDE	7.6	7.3	6.8	6.7	6.5	6.6	6.4*	6.4*	6.1*	6.1*	6.2*	6.2*	8.3	7.9

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 *@ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2031 FORECASTED BY PAVEMARS (PMRS).