

# FLORIDA DEPARTMENT OF TRANSPORTATION

## ALL SYSTEM PAVEMENT CONDITION FORECAST

**PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 01/30/2026**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = GILCHRIST -----																							
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR											FUTURE				
SR	US	G_BMP	G_EMP	LN	%T	ADT	RATINGS	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2031		
INTERSECT AT (MP SIDE)								=====															
ITMSEG-P W_BMP W_EMP RW FY-P WKMX-P								2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031		
CONTRACTOR (AGE_ONE YEAR) ASTYPE																							
ITMSEG-F W_BMP W_EMP RW FY-F WKMX-F																							
31010000		0.000	7.822	C	1	1	60	CRACKING	6.5	6.5	6.0*	3.5*	3.5*	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5		
26				2	7.0		7600	RIDE	8.2	8.2	7.5	7.0	6.8	8.5	8.6	8.5	8.4	8.2	8.2	8.2	8.1		
FANNING SPRINGS CITY LIM( 0.0C)								FC125M															
4412591		0.000	7.653	C	2023		0012	CRACKING	7.0	7.0	7.0	6.5	6.5	6.5	6.5	5.5*	4.0*	4.0*		10.0	10.0	9.0	
V. E. WHITEHURST & SONS, I(2025)								SPRIDE															
31010000		7.822	17.730	C	1	1	60	CRACKING	7.0	7.0	5.5*	3.5*	3.0*	1.0*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0		
26				2	7.0		10500	RIDE	8.1	7.9	7.4	6.9	6.8	7.2	6.3*	8.4	8.3	8.2	8.2	8.2	8.0		
SE 1ST ST( 7.8R)								FC125M															
2097372		10.511	15.482	C	2007		0012	CRACKING	10.0	9.0	9.0	8.5	8.5	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	5.8*	2.5*	
ANDERSON COLUMBIA CO., INC(2008)								RIDE															
2097906		7.818	17.530	C	2025		0012		8.0	7.8	7.8	7.7	7.8	7.6	7.7	7.5	7.3	7.4	7.1	7.2	7.0	6.6	
ANDERSON COLUMBIA CO., INC(2025)																							
31030000		0.000	2.100	C	1	1	60	CRACKING	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0		
49	129			2	7.7		6400	RIDE	7.9	8.8	8.7	8.4	8.4	8.5	8.6	8.5	8.5	8.4	8.4	8.3	8.3		
SW 103 ST( 0.2R)								FC125M															
4376201		0.000	1.394	C	2019		0012	CRACKING	7.5	7.5	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0	9.2	10.0	8.5	
V. E. WHITEHURST & SONS, I(2021)								SPRIDE															
31030000		2.100	2.767	C	1	1	30	CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0		
49	129			2	9.6		8100	RIDE	8.4	8.5	8.3	8.0	8.0	7.9	7.9	7.6	7.2	7.3	7.1	7.3	7.1		
NE FIRST AVE( 2.1R)								FC125M															
4376201		1.608	2.758	C	2019		0012	CRACKING	6.0*	6.0*	5.5*	10.0	10.0	10.0		10.0	10.0	10.0	10.0	9.2	9.0	7.5	
V. E. WHITEHURST & SONS, I(2021)								SPRIDE															
31030000		2.767	12.804	C	1	1	60	CRACKING		10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.5		
49	129			2	9.6		5300	RIDE		8.9	8.8	8.6	8.6	8.5	8.5	8.3	8.3	8.2	8.2	8.2	8.1	7.9	
PIEDMONT DAIRY RD( 4.5R)								FC125M															
								CRACKING	7.0	7.0	6.0*	6.0*	6.0*	6.0*	6.0*		10.0	10.0	10.0	9.5	10.0	8.5	
								RIDE	7.9	7.8	7.8	7.8	7.8	7.6	7.7		8.6	8.6	8.5	8.5	8.3	7.9	
(2022)																							
31030000		12.804	23.488	C	1	7	60	CRACKING	7.5	7.5	4.5*	4.5*	3.5*	1.0*	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0		
49	129			2	9.6		5600	RIDE	8.6	8.5	8.1	7.1	6.9	6.5	6.4*	6.1*	8.6	8.4	8.3	8.3	8.1		
RODEO RD(12.9L)								FC125M															
4470361		15.625	23.488	C	2024		0012	CRACKING	8.5	8.5	7.5	6.0*	6.0*	6.0*	6.0*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	9.0	
ANDERSON COLUMBIA CO., INC(2026)								SPRIDE															
31040000		0.000	0.612	R	1	1	35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0		
55	19			2	13.6		15700	RIDE	8.2	8.2	8.0	8.0	7.9	7.9	8.0	7.9	7.9	7.8	7.8	7.7	7.6		
SIDE ROAD( 0.0C)								FC125M															
								CRACKING	6.0*	6.0*	6.0*	4.0*	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	9.0	
								RIDE	7.5	7.3	7.3	7.2	8.1	8.0	7.9	7.9	7.8	7.8	7.5	7.5	8.4	8.3	7.9
(2025)																							
31040000		0.000	0.612	L	1	1	35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.0	7.0	7.0	7.0		
55	19			2	13.6		15700	RIDE	8.3	8.2	8.0	7.9	7.8	7.9	7.9	7.9	7.9	7.8	7.8	7.7	7.6		
SIDE ROAD( 0.0C)								FC125M															
								CRACKING	6.0*	6.0*	6.0*	4.0*	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	9.0	
								RIDE	7.5	7.1	7.2	7.1	8.2	8.1	8.1	8.0	7.8	7.8	7.6	8.3	8.3	7.9	
(2025)																							
31050000		0.000	18.364	C	1	1	60	CRACKING	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
47				2	13.3		2600	RIDE	7.6	8.7	8.6	8.4	8.4	8.3	8.5	8.4	8.4	8.3	8.3	8.3	8.2		
SR 49( 0.0C)								FC125M															
4453551		0.000	8.379	C	2023		0012	CRACKING	8.5	8.5	8.0	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	9.0	
PREFERRED MATERIALS, INC. (2025)								SPRIDE															
									8.2	8.1	7.9	7.9	7.9	7.9	7.7	7.9	7.8	7.6	7.7	7.6	8.7	8.7	

\*\*\* INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.  
 \*\*\* INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.  
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.  
 2031 FORECASTED BY PAVEMARS (PMRS).