

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = SUWANNEE -----																						
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE		
SR	US	G_BMP	G_EMP	LN	*T	AADT	RATINGS	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2031	
INTERSECT AT (MP SIDE)		W_BMP		W_EMP		RW		FY-P		WKMX-P		ASTYPE										(PMRS)
		(AGE_ONE YEAR)		YEAR		FY-F		WKMX-F														
37010000	0.000	4.983	C	1	1	60	CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0	
10 90			2	7.2		3200	RIDE	8.8	8.8	8.6	7.9	8.1	8.0	7.9	8.0	7.8	7.9	7.8	7.6	7.6		
OLD LOCATION OF SR 10(0.1L)																						
4342961	0.000	4.952	C	2019		0012	CRACKING	6.5	6.0*	6.0*	6.0*	4.0*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.0	8.5	7.0	
ANDERSON	COLUMBIA	CO., INC	(2021)				SPRIDE	7.6	7.4	7.5	7.4	7.5	7.4	7.3	8.7	8.4	8.3	8.1	8.0	7.9	7.5	
37010000	4.983	6.252	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	10.0		
10 90			2	7.2		3200	RIDE	8.2	8.3	8.3	7.9	8.0	7.9	7.8	7.8	7.8	7.9	7.8	7.6	8.7		
FC125M																						
(2020)																						
2135604	4.963	6.272	C	2026		0012	CRACKING	10.0	10.0	10.0	10.0	9.5		10.0	7.5	7.0	7.0	6.0*	4.0*	4.0*	2.5*	
							RIDE	8.5	8.4	8.3	8.3	8.2		8.4	8.3	8.1	8.0	8.0	7.8	7.9	7.5	
37010000	6.252	10.165	C	1	1	60	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5		
10 90			2	7.2		8700	RIDE	8.7	8.8	8.8	8.1	8.0	8.0	7.8	7.9	7.8	8.0	7.8	7.7	7.5		
FC125M																						
161 RD(6.4R)																						
4342961	6.261	10.177	C	2019		0012	CRACKING	7.0	7.0	7.0	7.0	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.9	9.5	8.0	
ANDERSON	COLUMBIA	CO., INC	(2021)				SPRIDE	7.5	7.5	7.3	7.2	7.3	7.0	7.0	8.5	8.2	8.1	7.9	7.8	7.7	7.3	
37010000	10.165	10.686	R	1	1	60	CRACKING	10.0		10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5		
10 90			1	7.2		8700	RIDE	8.7		8.6	8.1	8.1	8.0	7.9	8.1	7.8	8.0	7.8	7.7	7.5		
FC125M																						
MITCHELL RD(10.3R)																						
4342961	10.177	10.700	R	2019		0012	CRACKING	7.0	7.0	7.0	7.0	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.9	9.5	8.0	
ANDERSON	COLUMBIA	CO., INC	(2021)				SPRIDE	7.5	7.5	7.3	7.2	7.3	7.0	7.0	8.5	8.2	8.1	7.9	7.8	7.6	7.2	
37010000	10.686	12.270	C	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5		
10 90			2	7.2		9700	RIDE	8.7	8.5	8.6	7.9	7.8	7.6	7.5	7.6	7.8	8.0	7.8	7.7	7.5		
FC125M																						
MADISON ST(11.0R)																						
4342961	11.132	12.277	C	2019		0012	CRACKING	7.0	7.0	7.0	7.0	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.9	9.5	8.0	
ANDERSON	COLUMBIA	CO., INC	(2021)				SPRIDE	7.5	7.5	7.3	7.2	7.3	7.0	7.0	8.5	8.2	8.1	7.9	7.8	8.0	7.6	
37010000	12.270	13.320	C	1	1	35	CRACKING	3.5*		10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.5		
10 90			2	7.2		9700	RIDE	6.7		8.5	8.1	8.1	7.7	7.6	7.6	7.8	7.9	7.5	7.4	7.3		
FC125M																						
GREEN AVE(12.4R)																						
							CRACKING	7.0	7.0	7.0	6.0*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.0	8.0	6.5	
							RIDE	7.4	7.3	7.3	7.3	7.3	7.2	7.2	7.7	7.3	7.1	7.1	6.9	6.5	6.1	
37010000	13.320	15.090	C	1	1	45	CRACKING	4.5*		10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.5		
10 90			2	5.6		5700	RIDE	7.9		8.5	8.1	8.1	7.7	7.6	7.6	7.8	7.9	7.5	7.4	7.3		
FC125M																						
CONNER ST(13.3C)																						
							CRACKING	7.0	7.0	7.0	6.0*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.5	9.2	7.5	
							RIDE	7.4	7.3	7.3	7.3	7.3	7.2	7.2	8.4	8.3	8.1	8.0	7.8	7.8	7.4	
37010000	15.090	26.152	C	1	1	60	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5		
10 90			2	5.6		9400	RIDE	8.7	8.7	8.7	8.4	8.3	8.2	8.1	8.0	7.9	8.0	7.8	7.7	7.6		
FC125M																						
97TH LN(15.3L)																						
4432831	15.035	26.152	C	2022		0012	CRACKING	7.0	7.0	6.0*	6.0*	4.5*	4.0*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	10.0	9.0	
ANDERSON	COLUMBIA	CO., INC	(2024)				SPRIDE	7.6	7.5	7.6	7.6	7.7	7.7	7.7	7.7	7.6	7.6	8.9	8.9	8.8	8.4	
37010000	4.983	6.252	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	10.0		
10 90			2	7.2		3200	RIDE	8.2	8.6	8.6	7.8	8.0	8.0	7.9	7.9	7.8	7.8	7.5	7.6	8.8		
FC125M																						
169 RD(5.3L)																						
							CRACKING	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.0	7.0	7.0	6.0*	6.0*	3.9*	1.0*	
							RIDE	8.5	8.5	8.3	8.3	8.3	8.2	8.4	8.4	8.2	8.2	8.0	8.0	7.8	7.4	
2135604	4.963	6.272	C	2026		0012																
37030000	0.000	8.555	C	1	7	60	CRACKING	3.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0		
20 27			2	7.3		6200	RIDE	8.1	7.8	7.6	8.5	8.5	8.5	8.5	8.6	8.4	8.3	8.2	8.1	8.1		
FC125M																						
SR 249(0.1L)																						
							CRACKING	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	3.5*	10.0	9.0	
							RIDE	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.9	7.8	7.8	7.7	7.6	8.8	8.4	
37030000	8.555	8.623	C	1	8	60	CRACKING	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0		
20 27			2	7.3		6200	RIDE	8.3	7.8	7.8	8.5	8.5	8.5	8.5	8.5	8.4	8.3	8.2	8.1	8.1		
DGFC																						
							CRACKING	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	3.5*			
							RIDE	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.9	7.8	7.8	7.7	7.6			

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = SUWANNEE -----																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR		2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE	
SR	US	G_BMP	G_EMP	LN	*T	ADT	RATINGS	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	
INTERSECT	AT	(MP	SIDE)				*****														
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	WKM	-P		2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031
CONTRACTOR	(AGE_ONE	YEAR)			ASTYPE																(PMRS)
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKM	-F															
37040000	0.000	0.438	C	1	1	30	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	10.0	10.0	10.0	10.0	
249 129				4	15.4		6200 RIDE	6.5	6.5	6.5	6.6	6.0	5.8	6.2	6.0	6.4	8.2	7.8	7.9	7.9	
US-27/US-129/SR-20(0.0R)																					
2108063	0.000	0.347	C	2008			0221 CRACKING	10.0	9.0	9.0	9.0	9.0	9.0	8.5	7.5	7.0	7.0	7.0	6.5	6.5	3.5*
ANDERSON	COLUMBIA CO.,	INC(2010)					SPRIDE	7.8	7.6	7.6	7.5	7.5	7.5	7.4	7.5	7.4	7.5	7.1	7.1	7.2	6.8
37040000	0.438	12.889	C	1	1	60	CRACKING	8.5	8.5	7.0	5.5*	5.5*	3.5*	3.5*			10.0	10.0	10.0	10.0	
249 129				2	15.4		3412 RIDE	8.7	8.6	8.5	7.9	7.8	7.5	7.4	7.2		8.5	8.4	8.3	8.2	
HENRY AVE NW(0.4C)																					
2108063	0.438	12.889	C	2008			0221 CRACKING	9.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.5	3.5*
ANDERSON	COLUMBIA CO.,	INC(2010)					SPRIDE	8.1	8.1	8.1	8.0	8.1	7.9	7.9	7.9	7.8	7.8	7.6	7.6	7.4	7.0
37040000	12.889	23.138	C	1	1	60	CRACKING	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	7.5	7.5	
249 129				2	15.4		5200 RIDE	8.1	7.7	8.9	8.4	8.4	8.4	8.3	8.5	8.4	8.4	8.4	8.2	8.2	
OLD ALIGN RD(13.0L)																					
4454011	12.851	22.495	C	2023			0012 CRACKING	7.0	7.0	6.0*	6.0*	5.5*	5.5*	4.0*	4.0*	1.5*	1.5*	10.0	10.0	10.0	9.0
ANDERSON	COLUMBIA CO.,	INC(2024)					SPRIDE	8.0	8.0	8.0	7.9	7.9	7.7	7.9	7.9	7.7	7.8	8.5	8.4	8.4	8.0
37040000	23.138	24.685	R	1	1	35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.5	7.5	6.0*	
249 129				1	15.4		7200 RIDE	7.4	7.7	7.6	7.3	7.3	7.0	7.0	7.1	7.0	6.7	6.8	6.2	6.1	
MANOR ST(23.3R)																					
4305571	23.141	24.178	R	2016			0012 CRACKING	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	8.0	8.0	8.0	7.5	4.7*	2.5*
ANDERSON	COLUMBIA CO.,	INC(2018)					SPRIDE	6.9	6.9	7.1	6.8	7.8	7.8	7.8	7.6	7.4	7.2	7.2	6.9	6.4	6.0
37040000	24.685	25.200	R	1	3	35	CRACKING	10.0	10.0	10.0	8.5	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	8.5	
51 129				2	3.9		15500 RIDE	7.9	7.5	7.0	7.3	7.5	6.5	7.0	7.1	8.0	7.8	7.7	7.8	7.6	
HAINES ST(24.7C)																					
2107502	24.651	25.322	C	2008			0012 CRACKING	8.5	8.5	7.0	7.0	6.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*
ANDERSON	COLUMBIA CO.,	INC(2009)					SPRIDE	7.5	7.2	6.8	6.7	6.8	7.3	6.9	6.7	7.0	6.5	6.9	6.5	6.4	6.0
2107503	24.685	27.201	C	2025			0012														
37040000	25.200	25.610	R	1	3	45	CRACKING	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	8.5	8.5	8.5	8.5	8.5	
51 129				2	3.9		14400 RIDE	8.3	8.5	8.5	7.8	7.8	7.8	7.7	7.7	7.6	7.5	7.6	7.5	7.5	
HAMILTON ST(25.3R)																					
2107502	25.322	25.610	C	2008			0012 CRACKING	7.5	7.5	6.0*	6.0*	5.5*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*
ANDERSON	COLUMBIA CO.,	INC(2009)					SPRIDE	7.2	7.1	6.4	6.4	6.5	7.7	7.4	7.6	7.5	7.5	7.6	7.3	7.4	7.0
2107503	24.685	27.201	C	2025			0012														
37040000	25.610	27.579	R	1	1	45	CRACKING	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	
51 129				2	3.9		13600 RIDE	8.3	8.5	8.5	7.8	7.8	7.8	7.7	7.7	7.7	8.5	8.3	8.2	8.3	8.2
GRAND ST(25.8R)																					
2107502	25.610	27.579	C	2008			0012 CRACKING	9.0	8.5	8.5	8.5	7.5	6.5	6.5	5.5*	5.5*	5.5*	5.5*	3.5*	2.6*	0.0*
ANDERSON	COLUMBIA CO.,	INC(2009)					SPRIDE	8.3	8.1	8.1	8.1	8.1	8.0	8.1	8.0	7.8	7.9	7.8	7.8	7.7	7.3
2107503	24.685	27.201	C	2025			0012														
37040000	27.579	32.407	C	1	1	60	CRACKING	7.0	7.0	7.0	5.5*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
51 129				2	3.9		6400 RIDE	8.2	8.3	8.2	7.8	7.7	7.5	8.3	8.4	8.4	8.5	8.4	8.4	8.3	
58TH ST(28.6R)																					
2107814	27.925	32.407	C	2026			(2007) 0012	9.0	8.5	8.5	8.5	8.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	2.3*	0.0*
2107814	27.925	32.407	C	2026			0012	8.3	8.3	8.1	8.1	8.1	8.0	8.1	8.0	7.9	8.0	7.9	8.0	7.9	7.5
37040000	25.610	27.579	L	1	1	45	CRACKING	8.5	8.5	7.0	6.0*	3.0*	3.0*	3.0*	3.0*	10.0	10.0	10.0	9.0	8.5	
51 129				2	3.9		13600 RIDE	8.6	8.5	8.5	7.9	8.0	7.8	7.9	7.9	8.3	8.2	8.3	8.0	8.1	
72ND TRACE(26.4C)																					
2107502	25.610	27.579	C	2008			0012 CRACKING	8.5	8.5	8.5	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	3.0*	2.1*	0.0*
ANDERSON	COLUMBIA CO.,	INC(2009)					SPRIDE	8.0	8.1	7.9	8.0	7.9	7.8	7.9	7.8	7.6	7.8	7.7	7.7	7.6	7.2
2107503	24.685	27.201	C	2025			0012														
37040000	25.200	25.610	L	1	1	45	CRACKING	8.5	8.5	7.0	6.0*	3.0*	3.0*	3.0*	3.0*	8.5	8.5	7.5	7.5	7.5	
51 129				2	3.9		14400 RIDE	8.6	8.5	8.5	7.9	8.0	7.8	7.9	7.9	8.0	7.8	7.9	7.7	7.5	
HAMILTON ST(25.3L)																					
2107502	25.322	25.610	C	2008			0012 CRACKING	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	3.0*	1.3*	0.0*
ANDERSON	COLUMBIA CO.,	INC(2009)					SPRIDE	7.4	7.5	7.4	7.3	7.1	7.1	7.2	7.1	7.0	6.8	6.9	6.8	6.6	6.2
2107503	24.685	27.201	C	2025			0012														
37040000	24.685	25.200	L	1	3	35	CRACKING	10.0	10.0	10.0	8.5	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	8.5	
51 129				2	3.9		15500 RIDE	7.9	7.5	7.0	7.3	7.5	6.5	7.0	7.1	8.0	7.8	7.7	7.8	7.6	
HAINES ST(24.7C)																					
2107502	24.651	25.322	C	2008			0012 CRACKING	8.5	8.5	7.0	7.0	6.0*	0.0*	0.0*	0.0*	0.0*	6.0*	6.0*	5.5*	0.0*	0.0*
ANDERSON	COLUMBIA CO.,	INC(2009)					SPRIDE	7.5	7.2	6.8	6.7	6.8	7.3	6.9	6.7	7.0	6.8	7.2	6.7	6.4	6.0
2107503	24.685	27.201	C	2025			0012														

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 ** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = SUWANNEE -----																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE	
SR	US	G_BMP	G_EMP	LN	*T	ADT	RATINGS	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2031
INTERSECT AT (MP SIDE)	W_BMP	W_EMP	W_YEAR	FW-P	WKM-F	WKM-F	ASTYPE	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031
ITMSEG-P	W_BMP	W_EMP	W_YEAR	FW-P	WKM-F	WKM-F	ASTYPE														(PMRS)
CONTRACTOR (AGE_ONE YEAR)	W_BMP	W_EMP	W_YEAR	FW-F	WKM-F	WKM-F	ASTYPE														(PMRS)
ITMSEG-F	W_BMP	W_EMP	W_YEAR	FW-F	WKM-F	WKM-F	ASTYPE														(PMRS)
37040000	23.138	24.685	L	1	1	35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5		7.5	7.5	7.5	6.0*	
249 129				1	15.4		RIDE	7.4	7.7	7.6	7.3	7.3	7.0	7.0	7.5		6.7	6.8	6.2	6.1	
LAVONIA ST(23.2L)							FC125M														
4305571	23.141	24.178	L	2016		0012	CRACKING	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	8.0	8.5	8.5	7.0	5.2*	3.0*
ANDERSON COLUMBIA CO., INC(2018)							SPRIDE	6.9	6.9	7.1	6.8	7.8	7.8	7.8	7.6	7.4	7.6	7.6	7.3	7.3	6.9
37050000	0.000	0.424	C	1	1	45	CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	10.0	10.0	10.0	10.0	10.0
136				2	12.1		RIDE	8.2	8.0	7.9	7.4	7.4	7.3	7.2	7.4	7.4	8.3	8.2	8.2	7.8	
							DGFC														
							CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.0	7.0	7.0	10.0	10.0	9.0
							RIDE	8.1	8.1	7.7	7.5	7.6	7.3	7.6	7.5	7.3	7.1	7.1	7.6	7.7	7.3
							(2025)														
37050000	0.424	1.046	C	1	1	55	CRACKING	7.0	7.0	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	9.0	
136				2	12.1		RIDE	8.3	8.3	8.2	7.1	6.7	6.3*	8.0	8.5	8.3	8.2	8.3	8.2	8.1	
EXIT FARMERS MARKET(0.5R)							FC125														
2107752	0.424	0.789	C	2006		0012	CRACKING	8.5	8.5	7.5	7.0	7.0	6.5	6.5	6.0*	6.0*	6.0*	5.5*	5.5*	1.9*	0.0*
ANDERSON COLUMBIA CO., INC(2007)							RIDE	8.3	8.2	8.0	7.9	7.9	7.8	7.9	7.9	7.8	7.8	7.7	7.6	7.6	7.2
37060000	0.000	17.455	C	1	1	60	CRACKING	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	
51				2	6.6		RIDE	8.3	8.3	8.8	8.5	8.4	8.4	8.4	8.4	8.3	8.3	8.2	8.0	8.0	
COUNTY LINE INSPECTION S(1.3C)							FC125M														
4322611	0.000	16.658	C	2016		0012	CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.0	6.5	4.5*
ANDERSON COLUMBIA CO., INC(2017)							SPRIDE	7.9	7.8	7.8	8.6	8.5	8.3	8.0	7.8	7.8	7.7	7.6	7.6	7.4	7.0
37060000	17.455	17.491	C	1	6	35	CRACKING	0.0*	0.0*		10.0	10.0	10.0	10.0	10.0						
51				1	6.6		RIDE	8.3	8.3												
S WALKER AVE(17.5R)							FC95														
							CRACKING				8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	8.3	7.6	3.5*
							RIDE														
							(2004)														
37060000	17.491	17.994	C	1	1	35	CRACKING	9.0	9.0	6.5	6.5	10.0	8.5	8.5	7.5	7.0	10.0	10.0	10.0	10.0	
51				2	6.6		RIDE	6.7	6.8	6.1	5.8	7.3	6.9	6.6	6.2	5.5	7.7	7.5	7.3	7.2	
BYNUM AVE SW(17.6R)							DGFC														
							CRACKING	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	6.0*			10.0	10.0	9.0
							RIDE	7.0	6.9	6.4	6.3	6.2	6.0	6.0	6.1	5.8			7.2	6.8	6.4
							(2025)														
37070000	0.000	2.755	C	1	1	60	CRACKING	8.5	8.5	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	10.0	10.0	8.5	8.5	
49 129				2	11.3		RIDE	8.6	8.5	8.4	8.1	8.0	7.9	7.6	7.4	7.4	8.7	8.2	8.2	8.2	
SANDY POINT RD(0.0L)							FC125														
2107762	0.000	2.648	C	2009		0012	CRACKING	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	6.0*	6.0*	6.0*	5.5*	3.8*	0.5*
ANDERSON COLUMBIA CO., INC(2010)							RIDE	8.3	8.2	8.2	8.1	8.0	7.9	7.9	7.8	7.7	7.7	7.6	7.4	7.4	7.0
2107763	0.000	2.276	C	2029		0012															
37080000	0.000	0.600	C	1	1	35	CRACKING	9.0	9.0	7.0	7.0	6.0*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	
247				2	7.2		RIDE	8.4	8.3	8.3	7.8	7.6	7.4	7.2	6.5	6.8	8.4	7.9	7.8	8.0	
SR 249(0.0C)							FC125M														
2107192	0.000	0.600	C	2008		0221	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.5	6.8	3.5*
ANDERSON COLUMBIA CO., INC(2010)							RIDE	8.0	8.0	7.8	7.8	7.8	7.8	7.8	7.8	7.7	7.5	7.5	7.4	7.1	6.7
37080000	0.600	10.700	C	1	1	60	CRACKING	9.0	9.0	7.0	7.0	6.0*	5.5*	5.5*	5.0*		10.0	10.0	10.0	10.0	
247				2	15.4		RIDE	8.4	8.3	8.3	7.8	7.6	7.4	7.2	7.1		8.7	8.6	8.5	8.4	
SIDE ROAD(1.2C)							FC125M														
2107192	0.690	10.700	C	2008		0221	CRACKING	10.0	10.0	9.0	9.0	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.7	6.6	3.5*
ANDERSON COLUMBIA CO., INC(2010)							RIDE	8.1	8.1	8.2	8.1	8.1	7.9	7.9	7.8	7.8	7.7	7.6	7.4	7.3	6.9
37120000	0.000	5.861	R	4	1	70	CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0	
8 110	268.2	274.1	2	26.0		28000	RIDE	8.9	8.9	8.9	8.4	8.4	8.0	8.3	8.0	8.1	8.2	8.2	8.1	8.1	
							FC5M														
4413371	0.000	5.861	C	2021		0012	CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	6.5	6.5		10.0	10.0	9.7	10.0	8.5
ANDERSON COLUMBIA CO., INC(2023)							SPRIDE	8.1	8.0	8.3	8.3	8.5	8.4	8.4	8.4		8.8	8.8	8.7	8.8	8.7
37120000	5.861	15.099	R	4	1	70	CRACKING	10.0	10.0	10.0	10.0	9.0	8.0	7.5	7.5	7.5	6.5	6.0*		10.0	
8 110	274.1	283.3	2	27.7		24000	RIDE	8.9	8.9	8.9	8.3	8.2	8.0	8.0	7.7	7.6	7.3	7.0		8.7	
							FC5M														
2135603	5.861	15.099	C	2011		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	6.5	4.0*
PREFERRED MATERIALS, INC. (2013)							SPRIDE	8.7	8.6	8.9	8.9	9.1	9.0	9.0	9.1	9.1	8.9	8.8	8.7	8.6	8.5
2135604	5.861	15.132	C	2026		0012															

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @* INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = SUWANNEE -----																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE	
SR	US	G_BMP	G_EMP	LN	*T	AADT	RATINGS	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2031
INTERSECT	AT	(MP		SIDE)			SURFTYPE	=====													
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	WKM	P															
CONTRACTOR	(AGE_ONE	YEAR)		ASTYPE				2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKM	F															(PMRS)
37120000	15.099	25.508	R	4	8	70	CRACKING	10.0	9.0	6.5	6.5	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
8	I10	283.3	293.8	2	27.7	30110	RIDE	9.0	8.6	8.3	7.7	6.8	6.4*	8.4	8.5	8.5	8.5	8.5	8.5	8.4	8.3
							FC5M														
2135202	15.144	25.523	C	2006	0012		CRACKING	9.0	9.0	9.0	7.5	7.5	4.5*	4.5*	4.5*	4.5*	3.5*	1.0*	1.0*		
ANDERSON	COLUMBIA	CO.,	INC(2007)				RIDE	8.1	7.9	8.3	8.3	8.6	8.5	8.5	8.5	8.4	8.2	8.0	8.0		
37120000	15.099	25.508	L	4	8	70	CRACKING	10.0	9.0	6.5	6.5	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
8	I10	283.3	293.8	2	27.7	30110	RIDE	8.9	8.7	8.3	7.4	7.0	6.7	8.5	8.5	8.5	8.5	8.4	8.3	8.2	
							FC5M														
2135202	15.144	25.523	C	2006	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	4.5*	4.5*	4.5*	4.5*	4.5*	1.0*			
ANDERSON	COLUMBIA	CO.,	INC(2007)				RIDE	8.1	7.9	8.4	8.3	8.7	8.5	8.5	8.4	8.1	7.8	7.8			
37120000	5.861	15.099	L	4	1	70	CRACKING	10.0	10.0	10.0	9.0	9.0	8.0	7.5	7.5	6.5	6.0*	6.0*		10.0	
8	I10	274.1	283.3	2	27.7	24000	RIDE	8.8	8.8	8.8	8.2	8.1	7.9	7.7	7.4	7.4	7.1	6.6		8.7	
							FC5M														
2135603	5.861	15.099	C	2011	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	7.0	6.5	6.5	6.5	4.0*
PREFERRED	MATERIALS,	INC.	(2013)				SPRIDE	8.7	8.6	8.8	8.8	9.0	8.9	8.9	9.1	9.0	8.8	8.8	8.6	8.5	8.4
2135604	5.861	15.132	C	2026	0012																
37120000	0.000	5.861	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0
8	I10	268.2	274.1	2	26.0	28000	RIDE	8.8	8.9	8.9	8.4	8.3	8.2	8.2	8.1	8.1	8.2	8.2	8.1	8.1	
							FC5M														
4413371	0.000	5.861	C	2021	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	6.5	6.5	6.5		10.0	10.0	9.6	10.0	8.5
ANDERSON	COLUMBIA	CO.,	INC(2023)				SPRIDE	8.0	7.8	8.3	8.2	8.5	8.4	8.4	8.4		8.9	8.8	8.8	8.8	8.7
37130000	0.000	3.656	R	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	10.0	10.0	10.0	10.0	10.0
93	I75	438.3	442.0	3	31.3	38500	RIDE	8.5	8.9	8.9	8.3	8.3	8.1	7.9	7.7	7.5	8.7	8.7	8.6	8.6	
							FC5M														
4455451	0.000	3.656	R	2022	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	7.5	7.5	10.0	10.0	9.0
ANDERSON	COLUMBIA	CO.,	INC(2025)				SPRIDE	8.5	8.3	8.7	8.6	9.0	8.8	8.9	8.9	8.8	8.6	8.6	8.9	9.0	8.9
37130000	0.000	3.656	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.0	10.0	10.0	10.0	10.0	10.0
93	I75	438.3	442.0	3	31.3	38500	RIDE	8.9	8.9	8.8	8.4	8.3	8.2	8.1	8.0	7.7	8.6	8.6	8.5	8.5	
							FC5M														
4455451	0.000	3.656	L	2022	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	6.5	4.5*	10.0	10.0	9.0
ANDERSON	COLUMBIA	CO.,	INC(2025)				SPRIDE	8.4	8.2	8.5	8.5	8.7	8.6	8.6	8.6	8.3	8.2	8.1	8.7	8.8	8.7

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2031 FORECASTED BY PAVEMARS (PMRS).