

7151005 HIGHWAY LIGHTING SYSTEM  
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

.....  
Anonymous

Comments: (7-2-20)

Should the Spec state to coordinate the load center and pole number sequence with the local FDOT Maintenance office vs as shown in the plans? Otherwise, what happens if the plans always start with pole#1, etc.? Understanding that there should be coordination about numbering, it does not always happen and thus such a requirement in the Spec would be beneficial.

Response:

This comment is beyond the scope of the proposed revision for label color. This feedback will be logged and considered for future publications.

\*\*\*\*\*