

9160201 BITUMINOUS MATERIALS  
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Mark Musselman  
(850) 222-7300  
mmusselman@acaf.org

Comments: (5-29-20, Internal)

*The DSR test in the 916-2 #1. deleted part of the test method. The redline reads AASHTO T 319 (extraction/recovery) --> should be T 315-19. Similar to #2.*

Response: (Wayne Rilko) Test method AASHTO T 315-19. The reference in 916-2 #1 has been corrected. The reference in #2 has a space inserted between 'T' and '315'.

All AASHTO and ASTM references were checked to ensure that test method number and date are correct.

Thank you.

\*\*\*\*\*