

9160201 BITUMINOUS MATERIALS  
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

.....  
Mark Musselman  
(850) 222-7300  
mmusselman@acaf.org

Comments: (5-29-20, Internal)

*The DSR test in the 916-2 #1. deleted part of the test method. The redline reads AASHTO T 319 (extraction/recovery) --> should be T 315-19. Similar to #2.*

**Response:**

\*\*\*\*\*