

0050104-1 CONTROL ON THE WORK  
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Keith Waugh  
kwaugh@lewarecc.com

Comments: (11-29-18, Internal)

I don't have a real problem unless we get multiple interpretations of "continuous span". My understanding is that "continuous span" is where the entire superstructure is continuous over the cap, not just the deck.

Comments?

Response: Your understanding is correct. Our main concern is the stability of the remaining structure when a portion of its superstructure is being removed and this is not an issue when only the deck is continuous. We may get questions on the interpretation of "continuous span" every now and then, but that's preferable over not having this requirement at all.

\*\*\*\*\*