

RON DESANTIS GOVERNOR 605 Suwannee Street Tallahassee, FL 32399-0450 JARED W. PERDUE, P.E. SECRETARY

October 23, 2023

Khoa Nguyen
Director, Office of Technical Services
Federal Highway Administration
3500 Financial Plaza, Suite 400
Tallahassee, Florida 32312

Re: State Specifications Office

Section: 685

Proposed Specification: 6850201 Traffic Control System Auxiliaries.

Dear Mr. Nguyen:

We are submitting, for your approval, two copies of the above referenced Supplemental Specification.

The changes are proposed by Derek Vollmer to add reference to Section 996 for material and APL requirements.

Please review and transmit your comments, if any, within two weeks (10 business days). Comments should be sent via email daniel.strickland@dot.state.fl.us.

If you have any questions relating to this specification change, please call me at (850) 414-4130.

Sincerely,

Signature on File

Daniel Strickland, P.E. State Specifications Engineer

DS/dh

Attachment

cc: Florida Transportation Builders' Assoc.

State Construction Engineer

## TRAFFIC CONTROL SYSTEM AUXILIARIES. (REV 8-7-23)

SUBARTICLE 685-2.1 is deleted and the following substituted:

## 685-2 Materials.

685-2.1: General: Use traffic control system auxiliaries listed on the Department's Approved Product List (APL). Meet the following requirements:

ARTICLE 685-5 is deleted ad the following substituted:

## 685-5 Warranty.

Ensure the UPS includes a manufacturer's warranty covering defects for a minimum of three 3 years (5 years for the batteries in accordance with 685-2.2) from the date of final acceptance in accordance with 5-11 and Section 608. The warranty must include provisions for providing a replacement UPS within 10 calendar days of notification for any UPS found to be defective during the warranty period at no cost to the FDOT or the maintaining agency.

Ensure the RPMU includes a manufacturer's warranty covering defects for a minimum of three 3 years from the date of final acceptance in accordance with 5-11 and Section 608.

# TRAFFIC CONTROL SYSTEM AUXILIARIES. (REV 8-7-23)

SUBARTICLE 685-2.1 is deleted and the following substituted:

#### 685-2 Materials.

**685-2.1:** General: Meet the following requirements:

ARTICLE 685-5 is deleted ad the following substituted:

#### 685-5 Warranty.

Ensure the UPS includes a manufacturer's warranty covering defects for a minimum of 3 years (5 years for the batteries in accordance with 685-2.2) from the date of final acceptance in accordance with 5-11 and Section 608. The warranty must include provisions for providing a replacement UPS within 10 calendar days of notification for any UPS found to be defective during the warranty period at no cost to the FDOT or the maintaining agency.

Ensure the RPMU includes a manufacturer's warranty covering defects for a minimum of 3 years from the date of final acceptance in accordance with 5-11 and Section 608.