

Dev305 - Bituminous Crack and Joint Seal

| District | FPID Number | Letting | Monitor | Description | Revision Date |
|----------|----------------|-----------|-------------|---|---------------|
| 5 | 433848-1-52-01 | 6/1/2014 | John Fowler | Bituminous Crack and Joint Sealing | 6/4/2015 |
| TP | 442061-1-52-01 | 9/13/2022 | Greg Sholar | RESURFACE TPK MAINLINE IN BROWARD CNTY (MP 57.3 - 65.2) | 6/4/2015 |
| TP | 442061-2-52-01 | 9/13/2022 | Greg Sholar | SAFETY IMPROVEMENTS FOR TPK MAINLINE IN BROWARD CNTY (MP 57.3 - 65.2) | 6/4/2015 |