

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
1	Alachua	26005000	SR 222/ SR 26	West of I-75 to East of I-75	0.000	0.457	I-75 Interchange	0.055	None. Corrected by 428803-1 / 423071-1		428803-1/423071-1	PA	
1	Alachua	26005000	SR 222/ SR 26	West of I-75 to East of I-75	0.000	0.457	I-75 Interchange	0.275	None. Corrected by 428803-1 / 423071-1		428803-1/423071-1	PA	
1	Alachua	26005000	SR 222/ SR 26	West of I-75 to East of I-75	0.000	0.457	I-75 Interchange	0.305	None. Corrected by 428803-1 / 423071-1		428803-1/423071-1	PA	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 95th Blvd	0.404	Missing Detectable Warning System (DWS)		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	Circle K Gas station	0.438	Missing DWS		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 92nd CT	0.476	Damaged sidewalk (SW)	Pushbutton not parallel to crossing direction at	447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	Shopping Entrance	0.476	Missing DWS		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	SHOPPING ENT	0.557	Missing DWS		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 91ST ST	0.651	Replace DWS, broken SW, & replace ped signs	Pushbutton not parallel to crossing direction	447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 89 BLVD	0.780	Broken SW & Ramp Slope		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	School Entrance	0.912	Missing DWS		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 83RD ST	1.180	None	Pushbutton not parallel to crossing direction	N/A	PA	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 78 TER	1.462	Missing DWS		447032-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 75 ST	1.659	Replace DWS & Ramp Slope		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 71 BLVD	1.900	Replace DWS		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 71 ST	1.914	Replace DWS		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 51ST ST	3.157	Broken SW & replace ped signs	Pushbutton not parallel to crossing direction	447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	NW 48 TER	3.322	Replace DWS		447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	East of I-75 to 43rd St	0.457	3.693	CR-2053/ NW 43RD ST	3.667	Broken SW & replace ped signs	Pushbutton not parallel to crossing direction	447032-1	E or C	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	CEMETERY ENT	3.775	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 40TH TER	3.799	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 40TH ST	3.885	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 39TH WAY	4.001	Missing DWS & Broken SW		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 38TH ST	4.064	Missing DWS, Broken SW & Curb Ramp Slope		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 37TH TER	4.257	Missing DWS & Broken SW		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 37TH TER	4.304	Missing DWS		N/A	TO	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 37TH ST	4.304	Missing DWS, Broken SW & Curb Ramp Slope		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 36TH TER	4.368	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 36TH ST	4.410	Missing DWS, Broken SW & Curb Ramp Slope		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 36TH ST	4.442	Missing DWS & Broken SW		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 35TH ST	4.508	Missing DWS & Broken SW		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	SR-121/ NW 34TH ST	4.664	Replace DWS, Broken SW & Curb Ramp Slope, & replace ped signs	Pushbutton not parallel to crossing direction	N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 32ND ST	4.822	Missing DWS & Broken SW		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 31ST TER	4.878	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 29TH TER	5.043	Missing DWS, Broken SW & Curb Ramp Slope, & replace ped signs	Pushbutton not parallel to crossing direction	N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 28TH TER	5.141	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 26TH TER	5.331	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 25TH TER	5.437	Missing DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 24TH BLVD	5.500	Missing DWS, Broken SW, & replace ped signs	Pushbutton not parallel to crossing direction	N/A	TO	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 22ND DR	5.743	Replace DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 21ST DR	5.818	Replace DWS		N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NW 19TH TER	6.122	Replace ped signs	Pushbutton not parallel to crossing direction	N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	US-441/SR-25/ NW 13TH	6.667	Replace ped signs	Pushbutton not parallel to crossing direction	N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	SR-20 / NW 6TH ST	7.157	Replace DWS, broken SW, & replace ped signs	Pushbutton not parallel to crossing direction	N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NE 2ND ST	7.660	None	Pushbutton not parallel to crossing direction	N/A	PA	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	CR-329/ N MAIN ST	7.849	Replace DWS, broken SW, & replace ped signs	Pushbutton not parallel to crossing direction	N/A	TO	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	NE 15TH ST	8.668	None	Pushbutton not parallel to crossing direction	N/A	PA	
1	Alachua	26005000	SR 222/ SR 26	43rd St to Airport Entrance	3.693	10.573	SR-24/ WALDO RD	9.716	None	Pushbutton not parallel to crossing direction	N/A	PA	
2	Alachua	26050000	SR 331/ SR 24A	NE 3rd Ave to NE 8th Ave	3.525	3.964	NE 3rd Ave	3.525	Missing DWS		435890-1	E or C	
2	Alachua	26050000	SR 331/ SR 24A	NE 3rd Ave to NE 8th Ave	3.525	3.964	NE 5th Ave	3.672	Replace DWS		435890-1	E or C	
2	Alachua	26050000	SR 331/ SR 24A	NE 3rd Ave to NE 8th Ave	3.525	3.964	NE 8th St	3.964	Missing DWS & Replace Ped Signs	Pushbutton not parallel to crossing direction at	435890-1	E or C	
3	Alachua	26090000	SR 24	Archer Woods Apts to Gale Lemerand Dr	13.941	15.146	Unsigned Road	14.170	None. Corrected by 434323-1		434323-1	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
3	Alachua	26090000	SR 24	Archer Woods Apts to Gale Lemerand Dr	13.941	15.146	SW 23rd Terr	14.410	None. Corrected by 434323-1		434323-1	PA	
3	Alachua	26090000	SR 24	Archer Woods Apts to Gale Lemerand Dr	13.941	15.146	Fire Dept Entrance	14.874	Missing DWS at 3 Curb Ramps		N/A	Maint	
3	Alachua	26090000	SR 24	Archer Woods Apts to Gale Lemerand Dr	13.941	15.146	Unsigned Road	14.915	None. Corrected by 434323-1		434323-1	PA	
3	Alachua	26090000	SR 24	Archer Woods Apts to Gale Lemerand Dr	13.941	15.146	Unsigned Road	15.075	None. Corrected by 434323-1		434323-1	PA	
3	Alachua	26090000	SR 24	Archer Woods Apts to Gale Lemerand Dr	13.941	15.146	Gale Lemerand Dr	15.150	None. Corrected by 434323-1		434323-1	PA	
4	Alachua	26110000	SR 235/ SR 231	NW 150 Ave to NW 152 PL	0.406	0.562	SR 25/ US 441	0.485	Replace DWS, Pedestrian Signs Worn out, Ped pushbutton too far from SW, Broken		N/A	TO	
4	Alachua	26110001	SR 235/ SR 232	NW 150 Ave to NW 152 PL	0.406	0.562	Unsigned Road	0.554	Missing DWS		N/A	TO	
4	Alachua	26110002	SR 235/ SR 233	NW 150 Ave to NW 152 PL	0.406	0.562	NW 152 Pl	0.562	Curb Ramps Slope & missing DWS		N/A	TO	
5	Alachua	26110000	SR 235/ SR 231	NW 152 PL to NW 158 PL	0.562	0.923	Unsigned Road	0.624	Curb Ramps Slope & missing DWS		N/A	TO	
5	Alachua	26110000	SR 235/ SR 231	NW 152 PL to NW 158 PL	0.562	0.923	NW 154 Ave	0.645	Missing DWS		N/A	TO	
5	Alachua	26110000	SR 235/ SR 231	NW 152 PL to NW 158 PL	0.562	0.923	NW 155 Ave	0.695	Missing DWS		N/A	TO	
5	Alachua	26110000	SR 235/ SR 231	NW 152 PL to NW 158 PL	0.562	0.923	NW 155 Lane	0.743	Missing DWS		N/A	TO	
5	Alachua	26110000	SR 235/ SR 231	NW 152 PL to NW 158 PL	0.562	0.923	NW 156 Ave	0.766	Missing DWS		N/A	TO	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
5	Alachua	26110000	SR 235/ SR 231	NW 152 PL to NW 158 PL	0.562	0.923	NW 158 Ave	0.896	Missing DWS & Broken SW		N/A	TO	
6	Alachua	26220000	SR 121/SR 331	West of I-75(SW 35 Way) to SR 121/SW 34th St	8.616	9.046	SW 35 Dr	8.697	No Curb Ramps & Missing DWS		N/A	Maint	
6	Alachua	26220000	SR 121/SR 331	West of I-75(SW 35 Way) to SR 121/SW 34th St	8.616	9.046	Business Entrance	8.765	No Curb Ramps & Missing DWS		N/A	Maint	
6	Alachua	26220000	SR 121/SR 331	West of I-75(SW 35 Way) to SR 121/SW 34th St	8.616	9.046	Business Entrance	8.931	No Curb Ramps & Missing DWS		N/A	Maint	
6	Alachua	26220000	SR 121/SR 331	West of I-75(SW 35 Way) to SR 121/SW 34th St	8.616	9.046	SR 121	9.046	None	Pushbutton not parallel to crossing direction	N/A	PA	
7	Baker	27010000	SR 10 (US 90)	CR 231 to Derek Arline Rd	1.763	2.097	Unsigned Road	1.895	None		N/A	PA	
7	Baker	27010000	SR 10 (US 90)	CR 231 to Derek Arline Rd	1.763	2.097	Unsigned Road	2.085	None		N/A	PA	
8	Baker	27070000	SR 228/CR 228	East Jonathan St to the Railroad	6.987	7.49	S Blvd E	7.147	None. Corrected by 437613-1		437613-1	PA	
8	Baker	27070000	SR 228/CR 228	East Jonathan St to the Railroad	6.987	7.49	E Minnesota	7.237	None. Corrected by 437613-1		437613-1	PA	
8	Baker	27070000	SR 228/CR 228	East Jonathan St to the Railroad	6.987	7.49	E Michigan Ave	7.327	None. Corrected by 437613-1		437613-1	PA	
8	Baker	27070000	SR 228/CR 228	East Jonathan St to the Railroad	6.987	7.49	Mciver Ave	7.412	None. Corrected by 437613-1		437613-1	PA	
8	Baker	27070000	SR 228/CR 228	The Railroad to East RR Ave	7.490	7.499	E Railroad Ave	7.502	Curb ramps slope & Missing DWS		N/A	Maint	
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Harley Cir	7.888	Missing DWS		N/A	Maint	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Lorenzo Dr	8.058	Missing DWS		N/A	Maint	
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Gene Dr	8.205	Broken curb ramp and missing DWS		N/A	Maint	
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Church Entrance	8.466	Missing DWS & landing pad width		N/A	Maint	
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Meadows Dr	8.600	Broken curb ramp & missing DWS		N/A	Maint	
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Evergreen	8.678	Broken curb ramp, missing DWS & landing pad width		N/A	Maint	
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Southern Villas	8.719	Missing DWS		N/A	Maint	
9	Bradford	28030001	SR 16	Harley Circle to Glendale St	7.814	8.769	Glendale St	8.794	Broken curb ramp, missing DWS & landing pad width		N/A	Maint	
10	Bradford	28050000	SR 230	US 301/SR 200 to N Cherry St	0.000	0.221	Mid-block Crossing	0.095	Mid-block Crossing missing DWS and no Curb Ramps		439284-1/436558-1	E or C	
10	Bradford	28050000	SR 230	US 301/SR 200 to N Cherry St	0.000	0.221	Walnut	0.106	Ped signs, missing DWS	Pushbutton not parallel to crossing direction	439284-1/436558-1	E or C	
10	Bradford	28050000	SR 230	US 301/SR 200 to N Cherry St	0.000	0.221	Thompson St	0.150	Missing DWS		439284-1/436558-1	E or C	
10	Bradford	28050000	SR 230	US 301/SR 200 to N Cherry St	0.000	0.221	Railroad	0.180	Missing DWS		439284-1/436558-1	E or C	
10	Bradford	28050000	SR 230	US 301/SR 200 to N Cherry St	0.000	0.221	Unsigned Road	0.210	Missing DWS		439284-1/436558-1	E or C	
10	Bradford	28050000	SR 230	US 301/SR 200 to N Cherry St	0.000	0.221	N Cherry	0.221	Missing DWS		439284-1/436558-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	School Entrance	0.046	Missing DWS & Curb Ramp slope		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	School Entrance	0.152	None	Pushbutton not parallel to crossing direction	N/A	PA	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	School Entrance	0.227	None	Pushbutton not parallel to crossing direction	N/A	PA	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Professional Ctr Dr	0.357	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Fox Valley Dr	0.431	Missing DWS & landing pad width		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Professional Ctr Dr	0.466	None	Pushbutton not parallel to crossing direction	N/A	PA	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Hospital Entrance	0.535	Replace Damaged DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Driveways	0.750	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Foxwood Dr	0.966	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Village Way/ Belle Blvd	1.044	None	Pushbutton not parallel to crossing direction	N/A	PA	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Orange Ave	1.445	None	Pushbutton not parallel to crossing direction	N/A	PA	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Post Office	1.485	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	De Barry Ave	1.599	Replace Damaged DWS & broken SW		445342-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Hopkins St	1.693	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Azalea ln/ Grove Park Dr	1.815	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Park Entrance/Magnolia	1.867	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Solomon St	2.000	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Miller St	2.063	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Railroad	2.211	None		N/A	PA	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	CR 224A/ Doctors Lake	2.234	Broken SW, Missing DWS & sidewalk slope		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Railroad Ave	2.252	Replace damaged DWS	Pushbutton not parallel to crossing direction	445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Carnes St	2.284	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Driveways	2.415	Missing DWS		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Plainfield Ave	2.453	Missing DWS	Pushbutton not parallel to crossing direction	445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Mound St	2.562	Missing DWS at N Side		445342-1	E or C	
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	Smith St	2.672	None	Pushbutton not parallel to crossing direction	N/A	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
11	Clay	71130000	SR 224	SR 21/ Blanding Blvd to US 17/SR 15	0.000	2.781	US 17/SR 15	2.781	Missing DWS at island	Pushbutton not parallel to crossing direction	445342-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	US 441/Marion Ave	10.055	Replace Ped Signs		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Vickers Ter	10.247	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Church Ave	10.343	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	McCray Ave	10.435	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Laguna Dr	10.420	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Gordon PL	10.609	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Patterson Ave	10.710	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Ermine Ave	10.762	Missing DWS at side streets & at mid-block crossing		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Anderson Ter	10.809	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Bradley	10.854	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Murray Ter	10.892	Missing DWS & Cross slope more than 5%		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Chestnut Ave	10.969	Missing DWS at side streets & at mid-block crossing		441258-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Webster Ave	11.054	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Colburn Ave	11.086	Missing DWS		441258-1	E or C	
12	Columbia	29010000	SR 10/ SR 47/ SR 100	US 441/SR 25A/ Marion Ave to SE Lomond Ave	10.055	11.182	Lomond Ave	11.182	Missing DWS		441258-1	E or C	
13	Columbia	29050000	SR 20 (US 27)	SW Jordan St to SW Dortch St	7.801	7.956	Jordan St	7.801	Broken SW & missing DWS		N/A	Maint	
13	Columbia	29050000	SR 20 (US 27)	SW Jordan St to SW Dortch St	7.801	7.956	Dortch	7.956	Missing DWS		N/A	Maint	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Stockton St	19.538	None	Pushbutton not parallel to crossing direction	N/A	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Baker Ave	19.623	None		N/A	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Robinson Ave	19.740	None	Pushbutton not parallel to crossing direction	N/A	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	CSX RR	19.877	None		N/A	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Acorn St	20.059	None	Pushbutton not parallel to crossing direction	N/A	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Tyler St	20.196	None	Pushbutton not parallel to crossing direction	N/A	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Rushing St.	20.358	Under Construction (FPID 441298-1)		432308-1/441298-1	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Barnett St	20.358	Under Construction (FPID 441298-1)		432308-1/441298-1	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Myrtle Ave	20.500	Under Construction (FPID 441298-1)		432308-1/441298-1	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Blanche St	20.559	Under Construction (FPID 441298-1)		432308-1/441298-1	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Minnie St	20.607	Under Construction (FPID 441298-1)		432308-1/441298-1	PA	
14	Duval	72010000	SR 10/ SR 200 (US 90/US 301)	Stockton St to Eaverson St	19.538	20.658	Eaverson St	20.658	Under Construction (FPID 441298-1)		432308-1/441298-1	PA	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Lucente Dr	0.521	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Shopping Center Entrance	0.598	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Wiley Rd	0.647	Missing DWS, & Utility poles in the sidewalk	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	School Entrance	0.703	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Dayton Rd	0.772	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	SR 128/San Juan Ave	0.830	Missing DWS	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	McMullin St	0.897	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Hyde Grove Ave	1.022	Missing DWS	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Golfview St	1.147	Missing DWS		434299-1/439358-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Bakersfield Dr	1.305	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Apartment Entrance	1.420	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Apartment Entrance	1.451	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Apartment Entrance	1.532	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	London Towne Ln/Manotak Ave	1.626	Missing DWS	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Watergate Ln	1.684	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Park St.	1.950	Missing DWS	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Lenox Ave	2.090	Missing DWS, Curb ramp slope, and pushbuttons are too far from edge of SW	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Shopping Center Entrance	2.186	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Apartment Entrance	2.371	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Shopping Center Entrance	2.467	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	SR 228/Normandy Blvd	2.554	Missing DWS, less than 3 ft of SW at concrete island, replace ped signs, and	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Grace Ln	2.784	None	Pushbutton not parallel to crossing direction	N/A	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Mercel Ln	2.882	Missing DWS		434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Shopping Center Entrance	2.906	Missing DWS	Pushbutton not parallel to crossing direction	434299-1/439358-1	E or C	
15	Duval	72012000	SR 103	Lucente Dr to Ramona Blvd (S of I-10)	0.521	3.106	Ramona Blvd	3.106	None	Pushbutton not parallel to crossing direction	N/A	PA	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Apartment Entrance	4.450	Missing DWS		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Bartram Rd	4.545	Missing DWS & Damaged Curb Ramps		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Kellow Dr	4.776	Missing DWS & Damaged Curb Ramps		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	St. Cecilia Rd/Apartment	5.151	Missing DWS		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Hinely Ln	5.176	Missing DWS & Damaged Curb Ramps		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Riverhills Dr/Bartram Dr E	5.290	Missing DWS & Damaged Curb Ramps		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Atlantic Univ Cr	5.431	Under construction		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	US 90A/SR 10	5.943	Under construction		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Lawrence Pl	5.536	Under construction		445427-1	E or C	
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Robbins Cir S	5.619	Under construction		445427-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
16	Duval	72014000	SR 109	SR 228 to Robbins Cir N	4.426	5.776	Allen Pl	5.667	Missing DWS & Damaged Curb Ramps		445427-1	E or C	
17	Duval	72014000	SR 109	Arlington River Bridge to Service Road	6.216	6.406	Egret Point Ln	6.293	Missing DWS		N/A	Maint	
17	Duval	72014000	SR 109	Arlington River Bridge to Service Road	6.216	6.406	Service Road	6.409	Replace DWS	Pushbutton not parallel to crossing direction	N/A	Maint	
18	Duval	72030000	SR 15/ SR 228	Roosevelt Blvd to McDuff Ave S	9.219	9.434	Roosevelt Blvd	9.219	No Curb Ramps Landing Pad (Drop-off) & Missing DWS		N/A	Maint	
18	Duval	72030000	SR 15/ SR 228	Roosevelt Blvd to McDuff Ave S	9.219	9.434	Randall St	9.250	Missing DWS		N/A	Maint	
18	Duval	72030000	SR 15/ SR 228	Roosevelt Blvd to McDuff Ave S	9.219	9.434	Day St	9.296	No SW or Curb Ramps (SW gaps) & Missing DWS		N/A	Maint	
18	Duval	72030000	SR 15/ SR 228	Roosevelt Blvd to McDuff Ave S	9.219	9.434	McDuff Ave	9.434	Replace DWS	Pushbutton not parallel to crossing direction	N/A	Maint	
19	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Geraldine Ave to Riverside Ave	3.632	3.737	Geraldine Ave	3.643	Missing DWS & less than 3ft SW Pedestrian clearance		445431-1	E or C	
19	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Geraldine Ave to Riverside Ave	3.632	3.737	Oaks St	3.689	Missing DWS, 3ft SW width & no Curb Ramps		445431-1	E or C	
19	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Geraldine Ave to Riverside Ave	3.632	3.737	Riverside Ave	3.724	Missing DWS		445431-1	E or C	
20	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Lancaster St to I-95	6.369	6.729	Lancaster St	6.369	None	Pushbutton not parallel to crossing direction	N/A	PA	
20	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Lancaster St to I-95	6.369	6.729	Lomax St	6.465	Replace DWS		445431-1	E or C	
20	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Lancaster St to I-95	6.369	6.729	Bishop Gate Ln	6.507	Replace DWS		445431-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
20	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Lancaster St to I-95	6.369	6.729	CR-228/ Post St	6.567	Replace DWS	Pushbutton not parallel to crossing direction	445431-1	E or C	
20	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	Lancaster St to I-95	6.369	6.729	Riverside Park Pl	6.678	None	Pushbutton not parallel to crossing direction	N/A	PA	
21	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	23rd St to 29th St E	10.624	10.879	24th St	10.634	Missing DWS		445417-1	E or C	
21	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	23rd St to 29th St E	10.624	10.879	SR 122/ 27th St	10.773	Replace DWS	Pushbutton not parallel to crossing direction	445417-1	E or C	
21	Duval	72050000	SR 211/ SR 10 (US 1/US 90)	23rd St to 29th St E	10.624	10.879	29th St	10.879	Missing DWS & Ramp slope more than 20%		445417-1	E or C	
22	Duval	72070000	SR 5 / SR 10 (US 1/ US 90)	Shad Road to Perry Creek	8.331	8.477	Shad Rd/ Shopping Entrance	8.331	Missing curb ramps at Shopping entrance		N/A	Maint	
22	Duval	72070000	SR 5 / SR 10 (US 1/ US 90)	Shad Road to Perry Creek	8.331	8.477	Shopping Entrance	8.438	Missing DWS		N/A	Maint	
23	Duval	72070443	SR 5/ SR 13 (US 1)	Manning St to Louisa St	0.624	0.906	Manning St	0.620	None. Corrected by 436158-1		436158-1	PA	
23	Duval	72070443	SR 5/ SR 13 (US 1)	Manning St to Louisa St	0.624	0.906	Gary St	0.840	None. Corrected by 436158-1		436158-1	PA	
24	Duval	72080000	SR 139/ SR 228/ SR 15 (US 23/	US 1/SR 5 to W of I-95	0.000	0.965	N Laura St	0.093	None. Corrected by 432452-1		432452-1	PA	
24	Duval	72080000	SR 139/ SR 228/ SR 15 (US 23/	US 1/SR 5 to W of I-95	0.000	0.965	N Pearl St	0.308	None. Corrected by 432452-1		432452-1	PA	
24	Duval	72080000	SR 139/ SR 228/ SR 15 (US 23/	US 1/SR 5 to W of I-95	0.000	0.965	I-95 Interchange Ramps	0.792	None. Corrected by 432452-1		432452-1	PA	
24	Duval	72080000	SR 139/ SR 228/ SR 15 (US 23/	US 1/SR 5 to W of I-95	0.000	0.965	I-95 Interchange Ramps	0.895	None. Corrected by 432452-1		432452-1	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
24	Duval	72080000	SR 139/ SR 228/ SR 15 (US 23/	US 1/SR 5 to W of I-95	0.000	0.965	Cleveland St	0.998	None	Pushbutton not parallel to crossing direction	N/A	PA	
25	Duval	72080000	SR 139/ SR 228/ SR 15 (US 23/	CR 115A/ Soutel to MLK Drive	6.216	6.5	CR 115A/ Soutel	6.216	None	Pushbutton not parallel to crossing direction	N/A	PA	
25	Duval	72080000	SR 139/ SR 228/ SR 15 (US 23/	CR 115A/ Soutel to MLK Drive	6.216	6.5	Lorida Ave	6.460	None. Corrected by 436114-/436163-1		436114-1/436163-1	PA	
26	Duval	72110000	SR 109	Harris Ave to Arlington Rd	0.405	0.56	Harris Ave	0.405	None		N/A	PA	
26	Duval	72110000	SR 109	Harris Ave to Arlington Rd	0.405	0.56	Arlington Rd	0.555	None	Pushbutton not parallel to crossing direction	N/A	PA	
27	Duval	72120000	CR 228/ SR 228	West of Herlong Airport Entrance @ MP 16.058	16.021	16.058	Guardian Dr	16.058	Missing DWS, broken SW & no Curb Ramps		N/A	Maint	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Wilson Blvd	5.717	Missing DWS, 3ft SW Pedestrian clearance & no Curb Ramps	Pushbutton not parallel to crossing direction	447127-1	E or C	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Shopping Center Entrance	5.770	Missing DWS		447127-1	E or C	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Cedar Park Ln	5.788	Missing DWS		447127-1	E or C	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Hyde Park Rd	5.825	Missing DWS		447127-1	E or C	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Lake Shore Blvd	6.093	Missing DWS & broken Curb Ramps	Pushbutton not parallel to crossing direction	447127-1	E or C	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Timothy Ln	6.170	Missing DWS		447127-1	E or C	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	SR 111/Cassat Ave	6.220	Missing DWS & broken Curb Ramps	Pushbutton not parallel to crossing direction	447127-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Manchester Rd	6.255	Missing DWS		447127-1	E or C	
28	Duval	72170000	SR 21	Cedar Forrest Dr to Blackburn St	5.620	6.305	Blackburn St	6.271	Missing DWS & no Curb Ramps		447127-1	E or C	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Parental Home Rd	3.639	Currently Under Construction (432404-1)		432404-1	PA	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Walker Ln	3.811	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Everlee Rd	3.838	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Palm Ln	3.878	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Foster Dr	3.908	Currently Under Construction (432404-1)		432404-1	PA	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Grove Park Blvd	4.219	Currently Under Construction (432404-1)		432404-1	PA	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Killarney Dr	4.315	Missing DWS, no Curb Ramps & Broken SW		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Shopping Entrance/Sunbeam	4.496	Broken SW, No Curb Ramp	Pushbutton not parallel to crossing direction	N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Newell Rd	4.697	Replace DWS		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	SB Off Ramp/EB Off Ramp	4.753	Replace DWS	Pushbutton not parallel to crossing direction	N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	SR 115	4.785	Replace DWS	Pushbutton not parallel to crossing direction	N/A	Maint	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Eve Dr W	4.869	Replace DWS at Right Side & Sidewalk Gaps from Eve Dr W (MP 4.869 to MP		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Unsigned	4.990	Sidewalk Gaps from Eve Dr W (MP 4.869 to MP 4.99)		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Eve Dr E/Barkley Rd	5.037	Currently Under Construction (432404-1)		432404-1	PA	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Kline Rd E	5.105	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Peach Dr	5.415	Currently Under Construction (432404-1)		432404-1	PA	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Forest Blvd	5.680	Currently Under Construction (432404-1)		432404-1	PA	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Oregan Ln	5.779	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Lantana Lake Dr	5.906	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Anniston Rd	5.988	Currently Under Construction (432404-1)		432404-1	PA	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Saland Way	6.077	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Shopping Entrance	6.141	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Leon Dr	6.188	Missing DWS & no Curb Ramps		N/A	Maint	
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Countryside Village/Desalvo Dr	6.317	Currently Under Construction (432404-1)		432404-1	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
29	Duval	72190000	SR 212 (US 90)	Parental Home Rd to St Johns Bluff Rd	3.639	6.784	Shopping Entrance/Cortez Rd	6.663	Currently Under Construction (432404-1)		432404-1	PA	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	12th St	14.215	Missing DWS, and pushbuttons are too far from edge of SW	Pushbutton not parallel to crossing direction	445420-1	E or C	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	11th St	14.254	Missing DWS		445420-1	E or C	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	10th St	14.313	Missing DWS		445420-1	E or C	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	8th St	14.451	Missing DWS. Missing DWS at driveways and broken SW.		445420-1	E or C	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	6th St	14.586	Missing DWS and Ramp slope too steep		445420-1	E or C	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	5th St	14.654	Missing DWS		445420-1	E or C	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	4th St	14.721	Missing DWS		445420-1	E or C	
30	Duval	72190000	SR 212 (US 90)	12th St S to SR A1A/ 3rd St	14.145	14.826	SR A1A/ 3rd St	14.826	Missing DWS		445420-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Daniell Terrace	7.874	Replace DWS	Pushbutton not parallel to crossing direction	441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Cemetery Rd	7.920	Curb Ramps landing pad width & Missing DWS		441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Harlow Blvd	8.040	Missing DWS	Pushbutton not parallel to crossing direction	441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Tampico Rd	8.104	None		N/A	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	The Forest Apts/Walmart	8.175	Missing DWS		441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Walmart	8.228	None	Pushbutton not parallel to crossing direction	N/A	PA	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Norde Dr W	8.350	Missing DWS		441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Batley Rd	8.377	Curb Ramps landing pad width & Missing DWS		441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Cardan Rd	8.426	Curb Ramps landing pad width & Missing DWS		441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Moret Dr E/Dugdale Rd	8.488	Curb Ramps landing pad width & Missing DWS		441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	Jammes Rd	8.654	Replace DWS	Pushbutton not parallel to crossing direction	441261-1	E or C	
31	Duval	72220000	SR 134	I-295 to Wesconnett Blvd	7.776	9.136	SR 21/Blanding Blvd	8.847	Replace DWS	Pushbutton not parallel to crossing direction	441261-1	E or C	
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	Driveway	0.000	Missing DWS & Broken Sidewalk		443294-1	E or C	
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	SR 10 Interchange	0.021	Missing DWS & Broken Sidewalk	Pushbutton not parallel to crossing direction	443294-1	E or C	
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	2nd St	0.143	Missing DWS		443294-1	E or C	
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	3rd St	0.191	Missing DWS		443294-1	E or C	
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	4th St (Ocean Gate Ln)	0.239	Missing DWS		443294-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	5th St	0.284	Missing DWS		443294-1	E or C	
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	Cornell Ln	0.295	Missing DWS		443294-1	E or C	
32	Duval	72230000	SR A1A/ SR 101	SR 10 to W 6th St	0.000	0.335	6th St	0.335	Missing DWS		443294-1	E or C	
33	Duval	72291000	SR 111	S Edgewood Ave to Doolittle Rd	3.244	3.64	S Edgewood Ave	61-1	Missing DWS & Broken Sidewalk	Pushbutton not parallel to crossing direction	445429-1	E or C	
33	Duval	72291000	SR 111	S Edgewood Ave to Doolittle Rd	3.244	3.64	Edgewood Ct	3.392	Replace DWS	Pushbutton not parallel to crossing direction	445429-1	E or C	
33	Duval	72291000	SR 111	S Edgewood Ave to Doolittle Rd	3.244	3.64	Railroad	3.509	None		N/A	PA	
33	Duval	72291000	SR 111	S Edgewood Ave to Doolittle Rd	3.244	3.64	US 90/ SR 10	3.562	Missing DWS & Broken Sidewalk	Pushbutton not parallel to crossing direction	445429-1	E or C	
33	Duval	72291000	SR 111	S Edgewood Ave to Doolittle Rd	3.244	3.64	Doolittle Rd	3.640	Missing DWS		445429-1	E or C	
34	Duval	72291000	SR 111	Tory Place (E of I-95) to Bruce St	10.625	11.438	Tory Pl	10.625	Replace Signs	Pushbutton not parallel to crossing direction	N/A	Maint	
34	Duval	72291000	SR 111	Tory Place (E of I-95) to Bruce St	10.625	11.438	Iva Pl	10.650	Broken Sidewalk at East of Iva St		N/A	Maint	
34	Duval	72291000	SR 111	Tory Place (E of I-95) to Bruce St	10.625	11.438	W 67th St	11.145	None		437616-1	PA	
34	Duval	72291000	SR 111	Tory Place (E of I-95) to Bruce St	10.625	11.438	W 66th St/ Vermillion St	11.185	None		437616-1	PA	
34	Duval	72291000	SR 111	Tory Place (E of I-95) to Bruce St	10.625	11.438	Pearl St	11.351	Broken Curb Ramps & missing DWS at SW corner of Pearle S		N/A	Maint	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
35	Duval	72300001	SR 228	US 17/ N Newman St to US 1/5/ Ocean St N	0.168	0.241	US 17/ Newman St	0.168	Replace DWS at Curb ramps and at Driveways		N/A	Maint	
35	Duval	72300001	SR 228	US 17/ N Newman St to US 1/5/ Ocean St N	0.168	0.241	US-1/ Ocean St	0.241	Missing DWS		N/A	Maint	
36	Hamilton	32010000	SR 25/SR 100 (US 41/US 129)	CR 135/ 3rd St to Wesson St	0.780	1.141	CR 135/3rd St	0.780	Replace Damaged DWS		N/A	Maint	
36	Hamilton	32010000	SR 25/SR 100 (US 41/US 129)	CR 135/ 3rd St to Wesson St	0.780	1.141	2nd St	0.866	Missing DWS, no Curb Ramps & silts cover part of the SW		N/A	Maint	
36	Hamilton	32010000	SR 25/SR 100 (US 41/US 129)	CR 135/ 3rd St to Wesson St	0.780	1.141	1st St	0.950	Replace Damaged DWS		N/A	Maint	
36	Hamilton	32010000	SR 25/SR 100 (US 41/US 129)	CR 135/ 3rd St to Wesson St	0.780	1.141	Wesson St	1.141	Replace Damaged DWS		N/A	Maint	
37	Nassau	74040000	SR 200/ SR A1A	RR Track (RR # 620822-X) to US 17/ SR 5	30.238	30.548	US 17/ SR 5	30.548	None	Pushbutton not parallel to crossing direction	N/A	PA	
38	Putnam	76010000	SR 15/SR 20/SR 100 (US 17)	Worcester Road to Feagle Ave	11.916	12.39	E Main ST/ Prospect ST	11.978	Broken curb ramps		N/A	Maint	
38	Putnam	76010000	SR 15/SR 20/SR 100 (US 17)	Worcester Road to Feagle Ave	11.916	12.39	W Main St	11.996	Replace damaged DWS		N/A	Maint	
38	Putnam	76010000	SR 15/SR 20/SR 100 (US 17)	Worcester Road to Feagle Ave	11.916	12.39	Perry St	12.079	None		N/A	PA	
39	St Johns	78010026	SR 5A	St George Street to Cordova St	0.112	0.185	St. George St	0.112	Missing DWS		N/A	Maint	
39	St Johns	78010026	SR 5A	St George Street to Cordova St	0.112	0.185	Cordova St	0.185	Missing DWS and Curb ramp slope		N/A	Maint	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Driveway	12.828	Missing DWS		445546-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Shopping Entrance	12.960	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Mason Manatee Way/ National Guard Armor	13.227	Missing DWS & Broken curb ramps at National Guard Armor		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Driveway	13.341	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Twin Lakes Dr	13.894	Replace DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Driveway	14.101	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Wildwood Dr	14.455	Missing DWS, Broken SW, Replace Ped Signs	Pushbutton not parallel to crossing direction at	445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Hilltop Rd	14.866	Replace DWS, Replace Ped Signs	Pushbutton not parallel to crossing direction at	445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Lightsey Rd	15.510	Missing DWS, Broken SW, Replace Ped Signs	Pushbutton not parallel to crossing direction at	445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Rolling Hills Dr/ Holmes Blvd.	16.085	Replace DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Osceola Elem Rd	16.745	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Dobbs Rd	16.850	Missing DWS & Broken curb ramps		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Railroad	16.950	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Pinecrest St	17.091	Missing DWS		445546-1	E or C	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Sunrise Blvd	17.105	Missing DWS & Broken curb ramps		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Highland Blvd	17.161	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Hasting Rd	17.197	Missing DWS & Broken curb ramps/ SW		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	San Juline Cir	17.220	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	San Juline Cir	17.271	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Los Robles Ave	17.324	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	West St/ Henry St	17.372	Missing DWS & Broken curb ramps at Henry St		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	Helen Rd	17.465	Missing DWS		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	St Josephs Academy	17.538	Missing DWS & Broken curb ramps		445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	CR-5A/S Dixie Hwy	17.652	Missing DWS, Broken Curb ramps/SW, Replace Ped Signs	Pushbutton not parallel to crossing direction at	445546-1	E or C	
40	St Johns	78051000	SR 207	E of I-95 (SR 9) to CR 5A/ Dixie Hwy	12.828	17.652	US-1/ SR 5	17.652	None	Pushbutton not parallel to crossing direction	N/A	PA	
41	Suwannee	37010000	SR 10 (US 90)	Walker Ave to CR 249/Houston Ave	12.439	12.625	Walker Ave	12.439	SW Corner missing DWS and broken SW. No work was shown on the roadway Plans		N/A	Maint	
41	Suwannee	37010000	SR 10 (US 90)	Walker Ave to CR 249/Houston Ave	12.439	12.625	Irvin Ave	12.505	None. Corrected by 434296-1		434296-1	PA	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
42	Suwannee	37010000	SR 10 (US 90)	Church Ave to Suwannee Ave	12.702	12.798	Church Ave	12.737	None. Corrected by 434296-1		434296-1	PA	
42	Suwannee	37010000	SR 10 (US 90)	Church Ave to Suwannee Ave	12.702	12.798	Suwannee Ave	12.798	None. Corrected by 434296-1		434296-1	PA	
43	Suwannee	37030000	SR 20 (US 27/US 129)	SW Ivey to SR 249	0.035	0.075	SW Ivey	0.034	Missing DWS & broken curb ramp at side street and mid-block crossing		N/A	Maint	
43	Suwannee	37030000	SR 20 (US 27/US 129)	SW Ivey to SR 249	0.035	0.075	US 129/SR 249	0.080	Missing DWS, broken curb ramp & steep cross slope at some ramps		N/A	Maint	
44	Suwannee	37060000	SR 51	S Walker Ave to Bynum Ave SW	17.525	17.55	Roundabout	17.525	Missing DWS, broken curb ramp & steep cross slope		N/A	Maint	
44	Suwannee	37060000	SR 51	S Walker Ave to Bynum Ave SW	17.525	17.55	Bynum Ave	17.575	Missing DWS		N/A	Maint	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	US 221/SR 55 Jefferson Street	0.000	Replace DWS, broken curb ramp, steep cross slope, replace ped signs	Pushbutton not parallel to crossing direction at	N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Baker St	0.238	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Saxton St/Thomas Demps Ln	0.350	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Church St	0.599	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	Super Pufft St	0.686	Missing DWS & broken curb ramp		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	RR-713447 R	0.701	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Short St	0.713	Missing DWS		N/A	TO	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Duval St	0.780	Missing DWS & broken curb ramp		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Union St	0.828	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Bacon St	0.877	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Dundee St	0.923	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Homer/J Smith Ave	0.966	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	US 98/US 27 Hampton Spgs	1.029	Missing DWS, broken curb ramp, steep cross slope, replace ped signs	Pushbutton not parallel to crossing direction at	N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Richard Bell Ave	1.077	Missing DWS, broken curb ramp & steep cross slope		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Malloy St	1.130	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Willow St	1.159	Missing DWS & steep cross slope		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Spring PL	1.205	Missing DWS & broken curb ramp		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Summer St	1.248	Missing DWS & broken curb ramp		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Drew St	1.333	Missing DWS		N/A	TO	
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	W Green St	1.407	Missing DWS		N/A	TO	

LEGEND

	Previously Addressed
	Will be Addressed by Existing or Candidate Project
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)
	May be addressed by Traffic Ops and including in Yearly Review of New Candidate Projects (Anticipated Fiscal Year 2026 or Later unless Funding is Available Earlier)

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.

Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us

FDOT - ADA CAP - FY 2019/20

D2 - October 1, 2020

Seg No	County	RDWY ID	Roadway Name	Project Description	BMP	EMP	ADA Issues Location	MP	ADA Issues As of Field Review	Issue Already Addressed	FPID	Responsibility	FDOT Resolution
45	Taylor	38020000	SR 30/SR 20 (US 27/US98)	US 221/SR 55 to N of Main St	0.000	1.584	Main St	1.461	Replace DWS, broken curb ramp, steep cross slope, replace ped signs	Pushbutton not parallel to crossing direction at	N/A	TO	

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.


Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us



No corrective action required (DWS meet standards)

Project under construction or letting scheduled

Candidate project

Work to be performed utilizing Maintenance forces

FDOT - ADA CAP - FY 2019/20

D5 - October 1, 2020

#	RANDOM	RDWYID	BMP	EMP	NET	SIDE	SDWLKL	SDWLKR	Curb Ramp	DWS	Traffic Signal	Ped Signal	APS	Review Date	Correct? y or n	Comments/Notes	Corrective Action	
1	14872	11010000	1.518	1.593	0.075	R		5	Flush	Y	N	n/a	n/a	n/a	9/26/2019	N	No DW @ Executive Dr.; No DW @ asphalt	DWS to be added utilizing Maintenance
7	14379	11010000	12.748	13.028	0.28	R		12	Flush	n/a	N	n/a	n/a	n/a	9/26/2019	N	DW @ Blanton Ln may be bleached white w/o	DWS, yellow or black truncated domes are
20	14845	11050000	12.028	12.058	0.03	R		7	Raised	Y	N	n/a	n/a	n/a	9/26/2019	N	DW missing @ Stevens Ave/Bay St.	DWS replacement/update
22	14421	11050101	0.685	0.72	0.035	L	5	Raised	Y	Y	n/a	n/a	n/a	9/26/2019	N	DWs on SE corner at SR-19/E McDonald Ave	DWS, yellow or black truncated domes	
57	14766	36010000	23.842	24.959	1.117	R		5	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DWs multi-locs (US-27/SE 23rd Pl	DWS replacement/update
61	14878	36060000	0.153	0.278	0.125	L	8	Raised	Y	N	n/a	n/a	n/a	9/27/2019	N		DWS to be added utilizing Maintenance	
62	14886	36060000	0.278	0.648	0.37	L	5	Raised	Y	N	Y	Y	n/a	9/27/2019	N		DWS to be added utilizing Maintenance	
70	14498	36100000	8.056	8.226	0.17	L	6	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DWs at SW SR-200/Friendship	DWS replacement/update	
76	14720	36100000	18.01	18.25	0.24	R		5	Raised	N	N	n/a	n/a	9/27/2019	N	Missing CR & DWs at SR-200/SW 7th Rd.,	DWS replacement/update	
78	14776	36110000	24.981	25.041	0.06	L	6	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DWs at SR-40/NW 27th Ave	DWS replacement/update	
79	14377	36110500	0.33	0.358	0.028	R		5	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing/improperly placed DW at SR-40/N	DWS replacement/update
80	14838	36180000	13.638	13.668	0.03	L	5	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DW at RR crossing near SR-	DWS replacement/update	
81	14393	70002000	0.56	0.74	0.18	R		5	Raised	Y	N	n/a	n/a	n/a	9/27/2019	N	Missing DW at SR-406/Town Pl., SR-	DWS to be added utilizing Maintenance
87	14949	70012000	3.063	3.183	0.12	L	8	Raised	Y	N	n/a	n/a	n/a	9/27/2019	N	Missing DWs at SR-507/Lake in the Woods	DWS replacement/update	
113	14654	70050000	9.958	11.843	1.885	L	5	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DWs at SR-500/Hickory St, and	DWS replacement/update	
115	14598	70050000	15.818	15.893	0.075	L	5	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DWs at US-192/Waverly Pl.	DWS replacement/update	

Corrective Action Plans -- Districts 2 & 5

Contact: Randy E. (Brad) Bradley II, P.E.


Transition Plan Validation

FDOT State ADA Coordinator

FDOT Fiscal Year 2019/20

850-414-4295

ADACoordinator@dot.state.fl.us



No corrective action required (DWS meet standards)

Project under construction or letting scheduled

Candidate project

Work to be performed utilizing Maintenance forces

FDOT - ADA CAP - FY 2019/20

D5 - October 1, 2020

116	14413	70050000	17.938	18.478	0.54	R			5	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DWs at US-192/Riverside Dr., S.	DWS replacement/update
119	14773	70060000	20.167	20.237	0.07	L	5	Flush			n/a	N	n/a	n/a	n/a	9/27/2019	N	Missing DWs at Palm Colony Club.	DWS to be added utilizing Maintenance
120	14752	70060000	20.667	20.702	0.035	L	5	Flush			n/a	N	n/a	n/a	n/a	9/27/2019	N	Missing DWs at multilocations along Ocean	DWS to be added utilizing Maintenance
121	14468	70060000	20.742	20.752	0.01	L	8	Flush			n/a	N	n/a	n/a	n/a	9/27/2019	N	Missing DWs at multilocations along Ocean	DWS to be added utilizing Maintenance
128	14509	70070000	3.349	3.464	0.115	L	8	Flush			n/a	N	n/a	n/a	n/a	9/27/2019	N	Missing DWs at SR-524/Westminster Dr.,	DWS to be added utilizing Maintenance
129	14427	70070000	3.714	3.794	0.08	L	8	Flush			n/a	N	n/a	n/a	n/a	9/27/2019	N	Missing DWs at SR-524/Lance Blvd.	DWS to be added utilizing Maintenance
131	14436	70080000	0.314	0.339	0.025	R			5	Flush	n/a	N	n/a	n/a	n/a	9/27/2019	N	Missing DWs at E Osceola	DWS replacement/update
149	14666	70120004	1.84	2.135	0.295	R			5	Raised	Y	N	Y	Y	n/a	9/27/2019	N	Missing DWs at SR-518/"Old Time	DWS replacement/update
152	14397	70140000	1.936	2.071	0.135	L	5	Flush			n/a	N	Y	Y	n/a	9/27/2019	N	Missing DWs at SR-3/"Merritt Crossing".	DWS upgraded utilizing Maintenance
158	14689	73020000	7.941	7.956	0.015	L	5	Raised			n/a	N	Y	Y	n/a	9/30/2019	N	Missing DWs at FL-100/N. Flagler Ave.	DWS to be added utilizing Maintenance
159	14538	73020000	8.065	8.135	0.07	R			5	Raised	Y	N	n/a	n/a	n/a	9/30/2019	N	Missing DWs at SR-100/S. Daytona Ave.,	DWS to be added utilizing Maintenance
160	14959	73030000	4.708	5.13	0.422	L	8	Flush			n/a	N	n/a	n/a	n/a	9/30/2019	N	Missing DWs at SR-A1A/N 16th St., 15th,	DWS added utilizing Maintenance forces
161	14665	73030000	12.499	12.578	0.079	R			8	Flush	n/a	N	n/a	n/a	n/a	9/30/2019	N	Missing DWs at FL-A1A/Hammock Park	DWS to be added utilizing Maintenance
297	14924	77060000	6.957	6.992	0.035	L	5	Raised			Y	Y	Y	Y	n/a		N	Ped buttons are in the dirt, away from the	Intersection was reconstructed under
304	14626	77080000	9.935	10.225	0.29	R			5	Raised	Y	Y	Y	Y	n/a		N	SR425 at Lake Howell Lane- crossing of Lake	DWS have been upgraded to current
363	14770	92090000	8.569	8.609	0.04	L	10	Raised			Y	Y	n/a	n/a	n/a		N	US192/Vine just east of Illahaw Station	DWS to be replaced/updated