

<webmaster@dot.state.fl.us>

10/31/2002 11:49 AM

To: <duane.brautigam@dot.state.fl.us>

cc:

Subject: Data posted to form 1 of http:  
//www11.myflorida.com/specificationsoffice/IndustryReview.htm

\*\*\*\*\*  
File: D3000009 - Prime and Tack Coats for Base Courses - Measurement.  
Username: Bob DIon  
UserEmail: bob.dion@dot.state.fl.us  
UserTel: SC 373-5161  
UserFAX:  
ContactRequested:  
Remote Name: 156.75.64.64  
Remote User:

Comments:

Deleting 300-10 and not mentioning how payment for prime and tack is to be addressed is not a good idea. I suggest that language be included similar to "No separate payment will be made for prime coat, tack coat or prime coat cover material (including hot-asphalt coated cover material and the bituminous material therein), the cost of these materials and their application is to be included in the other items of related work. "or" There is no direct payment for the work specified in this Section, it is incidental to, and is to be included in the other items of related work.

Douglas Iles

To: john.owens@dot.state.fl.us

10/30/2002 12:44 PM

cc:

Subject: Re: Industry review of the following: D3000009 - Prime and Tack Coats for Base Courses - Measurement, D7050000 - Highway Delineators and D9930000 - Highway Delineators.

John,

We offer the following comments: additions in blue and deletions in ~~strike through~~.

In section 300-9.1: ".....~~This~~ The spread rate will be determined from the volume measurements made by the Contractor....."

300-9.2: Can we use the calibration certificate from the manufacturer?

Douglas K. Iles, E.I.

Assistant District Bituminous Engineer

District Five Materials and Research

1650 North Kepler Road

DeLand, Florida 32724

Office: (386) 740-3514 s/c 373

Fax: (386) 736-5239 s/c 383

<webmaster@dot.state.fl.us>

11/14/2002 02:07 PM

To: <duane.brautigam@dot.state.fl.us>

cc:

Subject: Data posted to form 1 of http:  
//www11.myflorida.com/specificationoffice/IndustryReview.htm

\*\*\*\*\*  
File: D3000009 - Prime and Tack Coats for Base Courses - Measurement.  
Username: Paul A. Grochowski  
UserEmail:  
UserTel: 352-381-4200  
UserFAX: 352-381-4250  
ContactRequested:  
Remote Name: 156.75.20.227  
Remote User:

Comments:

sect. 300-9.1 - Contractors sometimes spread tack down and don't cover  
it with hot mix. Do we want to pay for the amount not covered?

<webmaster@dot.state.fl.us>

11/13/2002 08:17 AM

To: <duane.brautigam@dot.state.fl.us>  
cc:  
Subject: Data posted to form 1 of http:  
//www11.myflorida.com/specificationsoffice/IndustryReview.htm

\*\*\*\*\*  
File: D3000009 - Prime and Tack Coats for Base Courses - Measurement.  
Username: Tami Toms  
UserEmail: Tami.toms@ dot.state.fl.us  
UserTel: (727)725-7950  
UserFAX: (727)725-7962  
ContactRequested:  
Remote Name: 156.75.110.41  
Remote User:

Comments:

There will no longer be a pay item for tack or prime, so couldn't we move toward a visual inspection with a calculation of the spread rate done only if the engineer believes that there is a problem. The reasoning would be streamline paperwork and testing. Now that this item is not paid, it seems that making a correction for temperature should not be necessary, and tracking this can be quite an amount of paperwork and time being spent on an incidental item.