



Karen Byram

11/15/2002 04:46 PM

To: John H Owens/CO/FDOT@FDOT

cc:

Subject: Response to Comments received from Industry Review for
D9670001 - Rail Elements For Guardrail. 

John;

Response to Dwayne Kile Comment.

Mr. Kile's comment is true. Dissimilar metals should not be used together, this is why the 967 Specification is divided into two sections. The specification change proposed applies only to 967-1 Steel Guardrail. In this case, galvanized supports, fastenings, and other accessories are also galvanized. Section 967-2 Aluminium Guardrail is unchanged. Aluminum alloy is identified for associated hardware.

Response to Joseph Gimigliano Comment.

Thank you for your support.

Karen Byram

Chemist Administrator

Florida DOT - State Materials Office

(352) 337-3122

SC (8) 642-3122

karen.byram@dot.state.fl.us

John H Owens