

3380502, Value Added Asphalt Pavement

Response to Comments From Industry Review

Nour Nazef
352-955-6322
abdenour.nazef@dot.state.fl.us

Comments:

My comments are mainly editorial Note1: add the word "of" before 55mph 338-5.2 Category 1 Pavement: For purposes of this Specification, "Category 1 Pavement" is defined as mainline roadways, access roads and frontage roads with a design speed of 55 mph and greater. Note 2: add a hyphen to 338 1. Threshold values are specified in Table 338-1 Note 3: In table 338-1 change "3A" from an upper case "A" to a lower case "a" Settlement/Depression(3a) Note 4: In Table 338-1 , add the word "wide" after "1/8 inch" Cracking (4) Any Survey Cumulative length of cracking > 30 feet for Cracks > 1/8 inch wide. Note 5: In Table 338-1, under "(3) Ride: Ride Number (RN)", remove the "6" in "330-12.6" Note 6: In table 338-1, under "(7) Patched Areas: At the time of final survey," replace "patcheds areas are not ..." with "patched area(s) is not ..." . Note 7: The first Table 338-2 header is an "orphan" and should be deleted (the complete table follows right after.) TABLE 338-2 Category 2 Pavements Type of Distress Type of Survey Threshold Values Remedial Work

Response:

I concur with all the comments except Note 7. The current Format for the Tables is used in all the other Sections of the Specifications.

Thank you for the comments.
