

5380500 RESETTING GUARDRAIL
COMMENTS FROM INDUSTRY REVIEW

Ken Zinck
386-740-3471
ken.zinck@dot.state.fl.us

Comments:

Comment by Charles M. Heffenger, P.E. Orlando Maintenance 407-858-5900: For resetting G-Rail, why not make it per section? The smallest section is 12.5' and to move any of it would require moving the entire section...

Response:

Comments:

Response:

Comments:

Response:

Comments:

Response:

Comments:

Response:
