

EXPECTED IMPLEMENTATION JANUARY 2010

538 RESETTING GUARDRAIL-BASIS OF PAYMENT. (REV 1-30-09) (FA 4-3-09) (1-10)

ARTICLE 538-5 (Page 613) is deleted and the following substituted:

538-5 Basis of Payment.

Prices and payments for resetting guardrail will be full compensation for all work specified in this Section, including furnishing all required new hardware and additional posts, all new offset blocks, and replacement of any material damaged by the Contractor except as specified below.

Price and payment for end anchorage assemblies, special guardrail posts, and bridge anchorage assemblies will be as specified in Section 536.

Payment for new guardrail panels and posts furnished to replace such items determined to be non-salvageable, excluding any items damaged by the Contractor, will be paid for at the actual invoiced cost including transportation charges, to which cost will be added an amount equal to 25% of the total charges.

Payment will be made under:

Item No. 538- 1- Resetting Guardrail - per foot.