

3370205 ASPHALT CONCRETE FRICTION COURSE  
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

.....  
D4 Construction

Comments: (6-26-12)

**337-7.5.1 Air Temperature at Laydown:**

“Meet the requirements of Table 330-1”. When looking in 330, Section 330 directs the reader to 337 for the temperature, so this information is missing in both sections.

**Response:**

\*\*\*\*\*