

1021110 MAINTENANCE OF TRAFFIC
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Anonymous

Comments: (9-23-15)

We are not in agreement for the specification as it relates to LCD. The delineator is not necessary and will only make the stacking and transporting of these devices difficult.

Response:

FDOT, D3 (via Barbara Strickland)

Comments: (10-8-15)

D3 Design comment: The Originator deleted through the word “or” and replaced it with the word “and”. A delineator cannot be installed on top of both a barrier wall and a vehicular LCD. It must be installed on either the barrier wall or a vehicular LCD.

Response:
