

5150504 METAL PEDESTRIAN/BICYCLE RAILINGS, GUIDERAILS, AND HANDRAILS
INTERNAL/INDUSTRY REVIEW COMMENTS

Karen Byram
414-4353
karen.byram@dot.state.fl.us

Comments: (7-1-16, Internal)
Suggest highlighted changes.

■ SUBARTICLE 515-5.4.4 is deleted and the following substituted:¶
→ → **515-5.4.4 Embedded Guiderail Posts:** Core holes into the foundation concrete, then clean holes, in accordance with the manufacturer's instructions. At a minimum, use oil-free compressed air to remove loose particles, brush the inside surface to free loose particles, then use compressed air again to remove any remaining particles. Use a Type ~~AB~~ **B**, or F epoxy **mortar compound** to secure guiderail posts into the cored holes.¶

Response:
