

RICK SCOTT GOVERNOR 605 Suwannee Street Tallahassee, FL 32399-0450 JIM BOXOLD SECRETARY

November 29, 2016

Khoa Nguyen Director, Office of Technical Services Federal Highway Administration 3500 Financial Plaza, Suite 400 Tallahassee, Florida 32312

Re: State Specifications Office

Section: 654

Proposed Specification: 6540204 Midblock Crosswalk Enhancement Assemblies.

REVISED

Dear Mr. Nguyen:

We are submitting, for your approval, two copies of the above referenced Supplemental Specification. Revisions (highlighted) were made in response to a comment from Frank Corrado.

The changes are proposed by Steve Duke of the State Materials Office to update an Industry reference. ASTM A325 and ASTM A490 have been withdrawn and consolidated into new ASTM F3125.

Please review and transmit your comments, if any, within two weeks. Comments should be sent via email to dan.hurtado@dot.state.fl.us.

If you have any questions relating to this specification change, please call me at 414-4130.

Sincerely,

Signature on file

Dan Hurtado, P.E. State Specifications Engineer

DH/dt

Attachment

cc: Florida Transportation Builders' Assoc.

State Construction Engineer

MIDBLOCK CROSSWALK ENHANCEMENT ASSEMBLIES.

(REV 9-20-1611-29-16)

SUBARTICLE 654-2.4 is deleted and the following substituted:

654-2.4 Cabinets, Housings, and Hardware: Cabinets used as part of the midblock crosswalk enhancement assembly must meet the applicable criteria of Section 676.

All housings other than approved cabinets must be powder coat painted dull black FED-STD-595-37038) with a reflectance value not exceeding 25 percent as measured by American Society for Testing and Material E1347. Cabinets and housings must prevent unauthorized access.

Pole-mount assemblies shall allow installation on 4-1/2 inch outer diameter posts. Ensure all assembly hardware, including nuts, bolts, external screws and locking washers less than 5/8 inch in diameter, are Type 304 or 316 passivated stainless steel. Stainless steel bolts, screws, and studs must meet ASTM F593. Stainless steel nuts must meet ASTM F594. All assembly hardware greater than or equal to 5/8 inch in diameter must be galvanized. Carbon steel bolts, studs, and threaded rod must meet ASTM A307. Structural bolts must meet ASTM F3125, Grade A325.

MIDBLOCK CROSSWALK ENHANCEMENT ASSEMBLIES. (REV 11-29-16)

SUBARTICLE 654-2.4 is deleted and the following substituted:

654-2.4 Cabinets, Housings, and Hardware: Cabinets used as part of the midblock crosswalk enhancement assembly must meet the applicable criteria of Section 676.

All housings other than approved cabinets must be powder coat painted dull black FED-STD-595-37038) with a reflectance value not exceeding 25 percent as measured by American Society for Testing and Material E1347. Cabinets and housings must prevent unauthorized access.

Pole-mount assemblies shall allow installation on 4-1/2 inch outer diameter posts. Ensure all assembly hardware, including nuts, bolts, external screws and locking washers less than 5/8 inch in diameter, are Type 304 or 316 passivated stainless steel. Stainless steel bolts, screws, and studs must meet ASTM F593. Stainless steel nuts must meet ASTM F594. All assembly hardware greater than or equal to 5/8 inch in diameter must be galvanized. Carbon steel bolts, studs, and threaded rod must meet ASTM A307. Structural bolts must meet ASTM F3125, Grade A325.