

1450200 Geosynthetic Reinforcement
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Will Gelner
(352) 363-9196
willg@dabcon.com

Comments: (Industry, 11-16-17)

"FDOT Design Manual" is inconsistent with "Florida Design Manual" that has been used and incorporated into previous specification changes (SEE 1020000)

Response: Agree. Specification 102-4 will be updated to "FDOT Design Manual." Thank you.
