

EXPECTED IMPLEMENTATION JULY 2018

555 DIRECTIONAL BORE. **(REV 10-27-17) (FA 11-13-17) (7-18)**

ARTICLE 555-6 is expanded by the following:

555-6 Compensation.

No direct payment will be made for directional bore. Include the cost to perform this operation in the Contract price for the item being installed.

No compensation will be made for failed bore paths, injection of flowable fill, products taken out of service, or incomplete installations.

No compensation will be made for the pay item associated with the directional bore until a Bore Path Report has been submitted and accepted by the Engineer.

D

R

A

F

T