

CONCRETE DITCH AND SLOPE PAVEMENT - REPAIR.
(REV 1-28-15) (FY 2023-24)

ARTICLE 524-1 is deleted and the following substituted:

524-1 Description.

Repair concrete pavement in the flow channel of drainage ditches and on slopes as identified in the Contract Documents and as directed by the Engineer.

ARTICLE 524-9 is expanded by the following new Subarticle:

524-9.3 Concrete Ditch and Slope Pavement Repair: The quantities to be paid for concrete ditch pavement and concrete slope pavement repair will be the quantity, in cubic yards, completed and accepted.