

Specification Section 105

Subarticle 105-4

ORIGINATION

Date: 6-24-24

Name: Oliver Chung

Email: Oliver.Chung@dot.state.fl.us

COMMENTARY

Materials Manual Section 8.2 Volume 2 has been revised.

INTERNAL COMMENTS AND RESPONSES

BLACK = Comment BLUE = Specifications Response GREEN = Change Made to Specification

Name: Andrew Pinkham

Date: 7-26-24

COMMENT: In our submittal of MM 8.2 revisions, we erroneously sent a working copy of the redlined document, not the final, which has the “A copy of...” line deleted. Attached is the real final submittal.

~~provided in *FDOT Specifications Section 450* include any available proposed repair methods for minor deficiencies as part of the QC Plan.~~

~~A copy of the Plant's proposed repair methods of the structural deficiencies shall be included as part of the QC Plan.~~

Complete the Incidental Precast Concrete Producer QC Plan Checklist (**Appendix B08**) and submit it along with the QC Plan, in a separate file. The

RESPONSE: To clarify the changes, “A copy of the Plant’s proposed repair methods of the structural deficiencies shall be included as part of the QC plan.” has been removed. FDOT Specification Section 450 introduces the requirements and details of the Precast Concrete Producer’s QC Plan.

ACTION TAKEN: Change has been reviewed, accepted, and submitted.