

Name	Address	Phone	Web site	Test/Standard
Applied Testing & Geosciences	401 E. Fourth Street, Bldg 12-B; Bridgeport, PA 19405	(800) 277-6400	http://www.appliedtesting.com	ANSI/SCTE 77 Section 7
Austin Reliability Labs	12317 Technology Blvd., Suite 100; Austin, TX 78727	(512) 490-2294	https://austinrl.com/environmental-testing	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Blue Guide EMC Lab	Joseph Cardijnstraat 21; B-9420 Erpe-Mere; Belgium	32 (0)53 43 23 04	https://www.bgemc.com	FCC Title 47 Subpart B Section 15
Calcoast-ITL	683 Thornton St; San Leandro, CA 94577	(510) 924-7100	http://www.calcoast-itl.com	SAE J595 for Class 1
CAL-TECH Technology Corp.	3F., No.331, Tanmei St.,Neihu Dist.; Taipei City 114; Taiwan	886 2 2796 5371	http://www.cal-tech.com.tw	NEMA-TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Central Research Technology Co.	11, Lane 41, Fushuen St.; Jungshan Chiu, Taipei 104; Taiwan	886-2-25872719	http://www.crc-lab.com/econtent/about.htm	NEMA TS4 Section 2
Cerpass Technology Corp.	No. 10, Lane 2, Lianfu Street, Luzhu Area; Taoyuan City; Taiwan	886-3-3226-888	http://www.cerpass.com.tw	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Cobham Advanced Electronic Solutions	4350 Centennial Blvd.; Colorado Springs, CO 80907	(719) 594-8000	https://caes.com/capabilities/testing-tuning	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Compatible Electronics, Inc.	114 Olinda Drive; Brea, CA 92823	(714) 579-0500	http://www.celectronics.com	FCC Title 47 Subpart B Section 15
CRT Laboratories, Inc.	1680 North Main Street; Orange, CA 92867	(714) 283-2032	http://www.crtlabs.com	ANSI/SCTE 77 Section 7
DATASYST Engineering & Testing Services, Inc.	S14 W33511 Highway 18; Delafield, WI 53018	(262) 968-4003	http://www.datasysttest.com	NEMA TS4 Section 2

Independent Test Labs_October 2025

Dayton T. Brown, Inc.	1175 Church Street; Bohemia, NY 11716	(800) 837-8456	https://www.dtb.com	ANSI/SCTE 77 Section 7; NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
DynaQual Test Labs	301 Wells Fargo Dr., Ste 10; Houston, TX 77090	(281) 773-7944	https://www.dynaqual.com/service/testing-with-dynaqual	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Element Materials Technology	1530 Vista View Drive; Longmont, CO 80504	(720) 340-7810	https://www.element.com/our-services/testing-services	NEMA TS4 Section 2
Element Materials Technology	662 Cromwell Ave.; St. Paul, MN 55114	(651) 645-3601	https://www.element.com/our-services/testing-services	NEMA TS2 Sections 2.2.7, 2.2.8, and 2.2.9
Element Materials Technology	6775 NE Evergreen Pkwy #400;	(503) 844-4066	https://www.element.com/our-services/testing-services	FCC Title 47 Subpart B Section 15
Element Materials Technology	9725 Girard Ave South; Minneapolis, MN 55431	(952) 888-7795	https://www.element.com/our-services/testing-services	NEMA TS4 Section 2; ANSI/SCTE 77
Element Materials Technology	1701 E. Plano Parkway #150; Plano, TX 75074	(972) 509-2566	https://www.element.com/our-services/testing-services	NEMA TS2 Sections 2.2.7, 2.2.8, and 2.2.9
Environment Associates	9604 Variel Avenue; Chatsworth, CA 91311	(818) 709-0568	http://www.eatest.com	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Eurofins E&E	914 W Patapsco Ave; Baltimore, MD 21230	(410) 354-3300	http://www.metlabs.com	NEMA TS1 Section 2
Global Testing Laboratories	3029 Gov. John Sevier Hwy; Knoxville, TN 37914	(865) 523-9972	https://www.globaltestinglabs.com	NEMA TS2 Sections 2.2.7 and 2.2.9; FCC Title 47 Subpart A Section 15
International Compliance Laboratories	1057 Tullar Court; Neenah, WI 54956	(920) 720-5555	http://icl-us.com	FCC Title 47 Subpart B Section 15
Interocean EMC Technology Corp.	No. 5-2 Lin 1 Tin-Fu Tsun; Lin-Kou Hsiang, Taipei County 244; Taiwan	(714) 671-9000	https://www.ietc.com.tw	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Intertek	3933 US Route 11; Cortland, NY 13045	(607) 753-6711	https://www.intertek.com/testing	ITE Standard for Vehicle Traffic Control Signal Heads

Independent Test Labs_October 2025

Intertek	7250 Hudson Blvd., Suite 100; Oakdale, MN 55128	(651) 730-1188	http://www.intertek.com/testing	ITE Standard for Vehicle Traffic Control Signal Heads
Intertek	70 Codman Hill Road; Boxborough, MA 01719	(978) 263-2662	http://www.intertek.com/testing	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Intertek	4700 Broadmoor Ave SE, Suite 200; Kentwood, MI 49512	(616) 656-7401	https://www.intertek.com/testing	SAE J595, Class 1
Investissement Quebec CRIQ	1201 boulevard Crémazie Est; Bureau 1.210; Montréal, H2M 0A6; Canada	(800) 667-4570	http://www.criq.qc.ca	NEMA TS4 Section 2
Keystone Compliance	131 N. Columbus Innerbelt; New Castle, PA 16101	(724) 657-9940	https://keystonecompliance.com	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
K-Light Laboratories Corp.	15705 Arrow Highway, Suite 3; Irwindale, CA 91706	(626) 960-0400	https://klightlaboratories.com	ITE Standard for Vehicle Traffic Control Signal Heads; NEMA TS4 Section 2
KONCAR - Electrical Engineering Institute Ltd.	Fallerovo setaliste 22; 10000 Zagreb; Croatia	385-1-3667-315	https://www.koncar- institut.hr/en/services-page	NEMA TS4 Section 2
LabTest Certification, Inc.	3128-20800 Westminster Hwy; Richmond, B.C. V6V 2W3;	(604) 247-0444	http://www.labtestcert.com	NEMA 250; FCC Title 47 Subpart B Section 15
Matric Group	2099 Hill City Rd; Seneca, PA 16346	(814) 677-0716	https://www.matric.com	NEMA TS5 Sections 4 and 13
Nemko	1601 North A.W. Grimes Blvd., Suite B; Round Rock, TX 78665	(512) 244-3371	https://www.nemko.com/product- testing	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
NTS	36 Gilbert Street South; Tinton Falls, NJ 07701	(732) 936-0800	https://www.nts.com/services/testin g	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
NTS	1536 East Valencia Drive; Fullerton, CA 92831	(714) 879-6110	https://www.nts.com/services/testin g	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9

Independent Test Labs_October 2025

NTS	1146 Massachusetts Avenue; Boxborough, MA 01719	(978) 266-1001	https://www.nts.com/services/testing	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
NTS	1701 E. Plano Pkwy, Suite 150; Plano, TX 75074	(972) 509-2566	https://www.nts.com/services/testing	NEMA TS4 Section 2; NEMA 250; NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9; FCC Title 47 Subpart B Section 15
NTS	2425 Industrial Boulevard; Chambly, QC J3L 4W3 Quebec; Canada	(450) 279-1006	https://www.nts.com/services/testing	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
NTS	5325 Old Winter Garden Road; Orlando, FL 32811	(407) 293-5844	https://www.nts.com/services/testing	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
NTS	6881 Kingspointe Parkway; Suite 15; Orlando, FL 32819	(407) 313-4230	https://www.nts.com/services/testing	NEMA TS2 Sections 2.2.7, 2.2.8, 2.2.9
Penn State University - Aerospace Engineering Dept	229 Hammond Building; University Park, PA 16802	(814) 865-2569	http://www.aero.psu.edu	FDOT Structures Manual 150 mph Wind Tunnel Test
Powertech Labs, Inc.	12388 88th Ave.; Surrey, B.C. V3W 7R7; Canada	(604) 590-7500	http://www.powertechlabs.com	NEMA TS2 Sections 2.2.8 and 2.2.9
Precision Test Solutions	6120 Hanging Moss Road; Orlando, FL 32807	(407) 678-6900	http://www.precisiontestsolutions.com	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Professional Testing (EMI), Inc.	1601 North A.W. Grimes Blvd., Suite B; Round Rock, TX 78665	(512) 244-3371	http://www.ptitest.com	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9

Independent Test Labs_October 2025

QAI Laboratories	8385 White Oak Avenue; Rancho Cucamonga, CA 91730	(888) 540-4024	http://www.QAI.org	ANSI/SCTE 77 Section 7
QAI Laboratories	3980 North Fraser Way; Burnaby, B.C. V5J 5K5; Canada	(604) 527-8378	http://www.QAI.org	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9; FCC Title 47 Subpart B Section 15
S&ME, Inc.	1413 Topside Road; Louisville, TN 37777	(865) 970-0003	http://www.smeinc.com	ANSI/SCTE 77 Section 6
San Diego Air and Space Technology, Low Speed Wind Tunnel	3050 Pacific Highway; San Diego, CA 92101	(619) 683-8900	http://www.lswt.com	FDOT Structures Manual 150 mph Wind Tunnel Test
SGS	620 Old Peachtree Rd. NW, Suite 100; Suwanee, GA 30024	(770) 570-1800	https://www.sgsgroup.us.com	NEMA TS4
SGS	No.31 Wu Chyuan Rd.; New Taipei Industrial Park,Wu Ku Dist.; New Taipei City 248016; Taiwan	(886-2) 2299- 3279	https://www.sgs.com.tw/en	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
SGS	No.163-1, Zhongsheng Rd.; Xindian Dist.; New Taipei City 231041; Taiwan	(886-2) 2217- 0894	https://www.sgs.com.tw/en	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Tarang Labs at Wipro Technologies	Survery # 70, 77, 78/8A Doddakanelli, Sarjapur Road; Bangalore, 560035; India	91-80-30292929	https://www.wipro.com/engineering-NXT/tarang-product-compliance-and-certification-labs	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Tektronix, Inc.	1133 Route 23 South; Wayne, NJ 07470	(877) 853-1942	https://www.tek.com/testing-services	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9; NEMA TS4 Section 2

Independent Test Labs_October 2025

Thales Cryogenics B.V.	Hooge Zijde 14; 5626 DC, Eindhoven; The Netherlands	31 (0) 40-250-36-03	https://www.thalesgroup.com/en/markets/specific-solutions/cryogenics-activities	NEMA TS2 Sections 2.2.8 and 2.2.9
The Specialty Lab, Inc.	1454 West County Road C W.; Roseville, MN 55113	(651) 482-2778	http://www.thespecialtylab.com	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
Timco Engineering, Inc.	849 NW State Road 45; Newberry, FL 32669	(352) 472-5500	https://timcoengr.com/wireless-emc-laboratory-testing-services/	FCC Title 47 Subpart B Section 15
TÜV NORD Hochfrequenztechnik GmbH & Co. KG	LESKANPARK, Gebäude 10; Waltherstr. 49-51, 51069 Köln; Germany	49-221-8888950	https://www.tuev-nord.de/de/werkstoffpruefung/homepage	FCC Title 47 Subpart C Section 15
TÜV SÜD America Inc.	141 14th ST NW; New Brighton, MN 55112	(651) 631-2487	https://www.tuvsud.com/en-us/services/testing	NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9
TÜV SÜD America Inc.	5610 West Sligh Ave Suite 100;	(813) 284-2715	https://www.tuvsud.com/en-us/services/testing	FCC Title 47 Subpart B Section 15
Underwriters Laboratories, Inc.	1285 Walt Whitman Rd; Melville, NY 11747	(631) 271-6200	https://www.ul.com/services/testing	UL 1449
Underwriters Laboratories, Inc.	12 Laboratory Drive; P.O. Box 13995; Raleigh, NC 27709	(919) 549-1400	https://www.ul.com/services/testing	UL 1449
Washington Laboratories, Ltd	4840 Winchester Blvd.; Frederick, MD 21703	(301) 216-1500	http://www.wll.com	FCC Title 47 Subpart B Section 15; NEMA TS2 Sections 2.2.7, 2.2.8 and 2.2.9