Improving Design Phase Evaluations of High Pile Rebound Soils with an Emphasis on SPT Testing

> Task Work Order BDV28 Two 977-05 15 month study

PI: Paul J Cosentino Ph.D., P.E., Florida Institute of Technology Melbourne Fl 32901-6975 321-674-7555 Direct

PM: David Horhota, Ph.D., P.E



#### Outline

- Introduction and Background
- \land Objective
- 🔍 Approach
  - Task 1 Additional Sites
  - Task 2 HPR Trends
  - Task 3 Draft Final Report and Closeout Teleconference
  - Task 4 Final Report
- Schedule of Tasks
- Implementation Items or Issues
- Project Benefits
- Closing




Florida Institute of Technology

### **FDOT Sites Tested to Date**

SPT on 11 of 12
CPTu on 8 of 12
Shelby on 6 of 12

Number	Description	Testing							
		SPT	CPTu	Undisturbed					
1	I-4 / US-192 Interchange / Osceola County / Florida.	<b>v</b>	<ul> <li>✓</li> </ul>	<ul> <li>✓</li> </ul>					
2	State Road 417 International Parkway / Osceola County / Florida.	<b>v</b>	<ul> <li>✓</li> </ul>	<ul> <li>✓</li> </ul>					
3	I-4 / Osceola Parkway / Osceola County / Florida.			<ul> <li>✓</li> </ul>					
4	State Road 50 and State Road 436 / Orange County / Florida.	<b>v</b>	<ul> <li>✓</li> </ul>						
5	I-4 / State Road 408 Ramp B / Orange County / Florida.	<b>v</b>	<ul> <li>✓</li> </ul>						
6	Anderson Street Overpass at I-4/SR-408 / Orange County / Florida.	<b>v</b>	<ul> <li>✓</li> </ul>						
7	I-4 John Young Parkway/ Orange County / Florida	<b>v</b>							
8	I-4 Widening Daytona / Volusia County / Florida.	<b>v</b>	<ul> <li>✓</li> </ul>						
9	SR 528 over Indiam River, Brevard County / Florida	<b>v</b>							
10	Saint Johns Heritage Parkway, Brevard County / Florida	<b>v</b>	<ul> <li>✓</li> </ul>	<ul> <li>✓</li> </ul>					
11	I-10 Chaffee Road, Duval County / Florida	<b>v</b>		<ul> <li>✓</li> </ul>					
12	State Road 83 over Ramsey Branch Bridge / Walton County / Florida.	<b>v</b>	<ul> <li>✓</li> </ul>	<ul> <li>✓</li> </ul>					




Florida Institute of Technology

#### HPR Decision Tree

Three Levels
Only Level 1 shown
Level 1 should be refined
Based on limited data
Based on ½ " rebound
¼ " produced poor results
Other rebound levels may help clarify

### Trends from CPTu Charts

 Based on Layers 4B thick
 Layer Thickness is critical
 Similar Trends maybe available using SPT data





#### **Rebound CPTu Data**

#### Nonrebound CPTu Data



### Objective

Refine the BDV28 977-01 Decision Matrix Level I soil classification criteria based on rebound level with N values and FC.



#### Approach

Identify & Organize Additional HPR and NonHPR sites Based on Rebound Level

Acceptable [rebound but pile driven]

No Rebound [< 1/4<sup>th</sup> inch rebound]

Unacceptable [Rebound Greater than 1/4 1/2 or 1"]

Evaluation of HPR Rebound Trends

Oraft Final Report and Closeout Teleconference

Final Report



#### Schedule of Tasks

FLORIDA DEPARTMENT OF TRANSPORTATION																
RESEARCH CENTER																
PROJECT SCHEDULE									_			_				
Project Title	Impro	ving Des	ign Phas	e Evalu	ations	of High l	Pile Rebou	nd Soils	with an 1	Emphas	is on SP	<b>F</b> Testing				
FDOT Project No.												FY	2	017	Month	April
			Technology	y												
		sentino, Ph														
	Apr-17	May-17	1	Jul-17	Aug-17			Nov-17	1	1	-	Mar-18	-	May-18	1	Comments
RESEARCH TASK	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
Project Kickoff Meeting	1															
Task 1 Identification and Organization of Additional HPR and NonHPR sites Based on Rebound Level	1	2	3	4	5	6									<u> </u>	
Task Evaluation of HPR Rebound Trends			1	2	3	4	5	6	7	8	9					
Task 3 Draft Final Report and Closeout Conference															<u> </u>	
									1	2	3	4		1		
Task 4 Final Report													1	2	3	




# Task 1 Identification and Organization of Additional HPR and NonHPR sites Based on Rebound Level

- Up to SIX new HPR sites will be identified- 4 identified to date
- Soil profiles with SPT plus PDA data from these sites will be organized so that the rebound can be categorized as follows:
  - Acceptable (rebound with acceptable set i.e. the pile driven),
  - no rebound (less than 0.25 inches of rebound)
  - In unacceptable (rebound greater than one of the three proposed rebound levels ¼-inch, ½-inch and 1-inch).




I-75 and SR 64Pier 3 Pile 1






Toledo BladePier 2 Pile 3






# University Parkway:Bent 1 (SB) Pile 2






# University Parkway:Bent 2 (SB) Pile 3






## University Parkway:Bent 3 (NB) Pile 7






# University Parkway:Bent 2 (NB) Pile 3





Saddle Creek:





Florida Institute of Technology

### Task 2 Evaluation of HPR Rebound Trends

- Existing and New Data to be used
- Divided into 4 subtasks
  - CPTu Soil Behavior Type Charts will be used to determine CPTu rebound trends and correlations
    - Based on pile penetration into the rebound layers of 2B, 4B and 8B
  - Correlations will be developed between the CPTu N equivalent values and the measured N values
  - SPT N and FC versus rebound correlations will be investigated using the 2B, 4B and 8B layer thicknesses
  - Conclusions will be developed and the Level I Decision Tree will be updated to reflect the new findings



### Final Two Tasks

#### Task 3 Draft Final Report and Closeout Teleconference

- Contains two deliverables
- Identified as 1 item in budget
- A well Written document will be submitted and reviewed for approval

#### Task 4 Final Report

- After revisions Final Report will be submitted on 2 Professionally labeled CD's
- Each CD will contain the report in both a word and pdf format



#### Questions

