



# Pit Proctor Quarterly Report

Print Date: 6/30/2015  
5:28:52PM

Valid from July 1, 2015 through September 30, 2015

## DISTRICT: 01

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
01305	EARTHSOURCE INC.	B11	1	Shell Rock	9.0	125
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock		Roadway Testing Required
01730	ALLIGATOR ALLEY AGGREGATE AND ASPHAL	B11	1	Shell Rock		Roadway Testing Required
01786	INFINITY MINING MATERIALS	B11	1	Shell Rock		Roadway Testing Required
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell		Roadway Testing Required
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell	9.7	127
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock	8.7	124
03340	ALLIGATOR ALLEY AGGREGATE AND ASPHAL	B01	1	Limerock		Roadway Testing Required
03616	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock	9.1	128
05354	RIDGDILL & SONS INC.	B01	1	Limerock	9.5	128
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock	7.5	132
12008	CEMEX	B01	2	Limerock	7.0	133
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock	8.7	129
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock		Roadway Testing Required
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock	9.2	127
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock		Roadway Testing Required
12726	WHITEHEAD AND JOHNS, LLC	B12	1	Recycled Concrete Agg		Roadway Testing Required
12743	DS & S CONSTRUCTION MATERIALS, INC.	B12	1	Recycled Concrete Agg		Roadway Testing Required
17724	MASTERROCK LLC.	B12	1	Recycled Concrete Agg	13.0	116

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2015 to 6/21/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2015  
5:30:24PM

Valid from July 1, 2015 through September 30, 2015

## DISTRICT: 02

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock	13.4	114
26098	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	12.4	118
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock	12.8	118
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26782	LIMESTONE MATERIALS	B01	1	Limerock	12.4	118
33496	BLUE ROK INC.	B01	1	Limerock	11.6	120
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock	12.3	117
37112	SUWANNEE AMERICAN CEMENT	B01	1	Limerock	11.7	121
37112	SUWANNEE AMERICAN CEMENT	B01	2	Limerock		Roadway Testing Required
37622	DENALI INVESTMENTS INC.	B01	1	Limerock	13.7	114
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock	8.5	128
38627	A MINING GROUP, LLC	B01	1	Limerock	9.8	124
72768	ANDERSON COLUMBIA	B01	1	Limerock	11.4	119
78697	EAST COAST AGGREGATES LLC	B11	1	Shell Rock	8.0	132
GA206	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate		Roadway Testing Required
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2015 to 6/21/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2015  
5:30:24PM

Valid from July 1, 2015 through September 30, 2015

## DISTRICT: 03

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
53271	DOLOMITE INC.	B01	1	Limerock	14.0	115
53357	NORTH FLORIDA ROCK LTD.	B01	1	Limerock	13.4	113
53357	NORTH FLORIDA ROCK LTD.	B01	2	Limerock	13.0	113
53575	MARIANNA LIMESTONE, LLC	B01	1	Limerock		Roadway Testing Required
53575	MARIANNA LIMESTONE, LLC	B01	2	Limerock		Roadway Testing Required
53575	MARIANNA LIMESTONE, LLC	B01	3	Limerock		Roadway Testing Required
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
53706	ANDERSON COLUMBIA	B01	1	Limerock	12.3	120
56626	GULF COAST AGGREGATES	B01	1	Limerock		Roadway Testing Required
61377	SIKES SAND & GRAVEL	B12	1	Recycled Concrete Agg		Roadway Testing Required
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	11.0	121
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate		Roadway Testing Required
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock	14.2	118
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock	12.7	121
AL612	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock	11.7	122

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2015 to 6/21/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2015  
5:30:24PM

Valid from July 1, 2015 through September 30, 2015

## DISTRICT: 04

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina		Roadway Testing Required
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina	8.3	132
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock	8.3	126
93366	STAR QUARRIES LLC	B01	1	Limerock		Roadway Testing Required
93366	STAR QUARRIES LLC	B11	1	Shell Rock		Roadway Testing Required
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock	8.0	129
93721	5 STONES MINE, LLC	B11	1	Shell Rock	9.3	127
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Agg		Roadway Testing Required
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina	8.0	129
94488	STEWART MINING INDUSTRIES INC.	B03	1	Cemented Coquina		Roadway Testing Required
94745	PATRICK JAMES ECYCLE	B12	1	Recycled Concrete Agg		Roadway Testing Required
94789	STEWART MINING INDUSTRIES INC.	B03	1	Cemented Coquina	8.5	129

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2015 to 6/21/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2015  
5:30:24PM

Valid from July 1, 2015 through September 30,2015

## DISTRICT: 05

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock	12.2	118
18020	CEMEX	B01	2	Limerock		Roadway Testing Required
18056	DIXIE LIME & STONE CO.	B01	1	Limerock	12.5	116
18058	CEMEX	B01	1	Limerock	12.4	118
18058	CEMEX	B01	2	Limerock		Roadway Testing Required
18393	BEDROCK RESOURCES	B01	1	Limerock	12.3	116
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock	12.6	118
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock	11.8	120
36350	MAGNUM CONSTRUCTION SOLUTIONS	B01	1	Limerock	12.6	119
36566	COUNTS CONSTRUCTION CO. INC.	B01	1	Limerock		Roadway Testing Required
79767	FLORIDA SAND AND SHELL	B11	1	Shell Rock		Roadway Testing Required
92757	BUCK HAMMOCK MINE	B02	1	Bank Run Shell		Roadway Testing Required
BA348	BAHAMAS ROCK LIMITED	B01	1	Limerock		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2015 to 6/21/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2015  
5:30:24PM

Valid from July 1, 2015 through September 30,2015

## DISTRICT: 06

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock	10.3	127
87089	CEMEX	B01	1	Limerock	7.8	130
87090	CEMEX	B01	1	Limerock	7.8	129
87090	CEMEX	B01	2	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	1	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	2	Limerock	9.7	130
87145	TITAN AMERICA, LLC.	B01	4	Limerock		Roadway Testing Required
87339	WHITE ROCK QUARRIES	B01	1	Limerock	8.8	131
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock	8.0	133
87633	WHITE ROCK QUARRIES	B01	1	Limerock	8.7	128
87648	SDI QUARRY, INC.	B01	1	Limerock	8.0	130
90638	CHARLIE TOPPINO & SONS INC.	B01	1	Limerock		Roadway Testing Required
90765	GRADER MIKE, LLC	B01	1	Limerock		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2015 to 6/21/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2015  
5:30:24PM

Valid from July 1, 2015 through September 30,2015

## DISTRICT: 07

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock		Roadway Testing Required
02675	CEMEX	B01	1	Limerock	8.4	131
08050	E.R. JAHNA INDUSTRIES INC.	B01	1	Limerock		Roadway Testing Required
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Agg		Roadway Testing Required
13662	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Agg		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	1	Limerock		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock	12.0	118
14262	CENTRAL STATE AGGREGATES, LLC	B01	3	Limerock		Roadway Testing Required
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock	11.4	118
15755	SONNY GLASBRENNER	B12	1	Recycled Concrete Agg		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2015 to 6/21/2015  
Reference: Section 200