



Pit Proctor Quarterly Report

Print Date: 1/4/2016
1:24:00PM

Valid from January 1, 2016 through March 31, 2016

DISTRICT: 01

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
01305	EARTHSOURCE INC.	B11	1	Shell Rock	9.0	126
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock		Roadway Testing Required
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell	8.3	125
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell	9.8	125
01800	ICS MATERIALS INC.	B11	1	Shell Rock		Roadway Testing Required
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock	8.3	122
03340	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B01	1	Limerock		Roadway Testing Required
03616	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock		Roadway Testing Required
05354	RIDGDILL & SONS INC.	B01	1	Limerock	9.5	129
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock		Roadway Testing Required
12008	CEMEX	B01	2	Limerock	7.3	134
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock	8.7	127
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock		Roadway Testing Required
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock		Roadway Testing Required
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock	9.7	127
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock		Roadway Testing Required
12726	WHITEHEAD AND JOHNS, LLC	B12	1	Recycled Concrete Agg		Roadway Testing Required
12743	DS & S CONSTRUCTION MATERIALS, INC.	B12	1	Recycled Concrete Agg		Roadway Testing Required
17724	MASTERROCK LLC.	B12	1	Recycled Concrete Agg		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 9/21/2015 to 12/22/2015
Reference: Section 200



Pit Proctor Quarterly Report

Print Date: 1/4/2016
1:26:40PM

Valid from January 1, 2016 through March 31, 2016

DISTRICT: 02

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock	12.4	121
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock	13.7	114
26098	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	12.2	119
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26782	LIMESTONE MATERIALS	B01	1	Limerock	11.5	120
33496	BLUE ROK INC.	B01	1	Limerock	11.4	122
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock		Roadway Testing Required
37112	SUWANNEE AMERICAN CEMENT	B01	1	Limerock	12.3	117
37112	SUWANNEE AMERICAN CEMENT	B01	2	Limerock		Roadway Testing Required
37622	DENALI INVESTMENTS INC.	B01	1	Limerock	13.7	114
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock	9.5	131
38627	A MINING GROUP, LLC	B01	1	Limerock	9.4	124
78697	EAST COAST AGGREGATES LLC	B11	1	Shell Rock		Roadway Testing Required
GA178	AGGREGATES USA	B10	1	Graded Aggregate		Roadway Testing Required
GA206	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate		Roadway Testing Required
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 9/21/2015 to 12/22/2015
Reference: Section 200



Pit Proctor Quarterly Report

Print Date: 1/4/2016
1:26:40PM

Valid from January 1, 2016 through March 31, 2016

DISTRICT: 03

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
53271	DOLOMITE INC.	B01	1	Limerock	14.6	117
53357	NORTH FLORIDA ROCK LTD.	B01	1	Limerock	14.1	116
53357	NORTH FLORIDA ROCK LTD.	B01	2	Limerock	14.0	115
53575	MARIANNA HI-CAL LLC	B01	1	Limerock		Roadway Testing Required
53575	MARIANNA HI-CAL LLC	B01	2	Limerock		Roadway Testing Required
53575	MARIANNA HI-CAL LLC	B01	3	Limerock		Roadway Testing Required
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
53706	ANDERSON COLUMBIA	B01	1	Limerock	12.8	117
61377	SIKES SAND & GRAVEL	B12	1	Recycled Concrete Agg		Roadway Testing Required
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	12.8	122
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate		Roadway Testing Required
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock	13.7	119
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock	13.5	118
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock		Roadway Testing Required
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock	13.4	118
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock	13.9	117

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
 Data from Mines for Date Range: 9/21/2015 to 12/22/2015
 Reference: Section 200



Pit Proctor Quarterly Report

Print Date: 1/4/2016
1:26:40PM

Valid from January 1, 2016 through March 31, 2016

DISTRICT: 04

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina		Roadway Testing Required
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina		Roadway Testing Required
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock	8.3	130
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock		Roadway Testing Required
93366	STAR QUARRIES LLC	B01	1	Limerock		Roadway Testing Required
93366	STAR QUARRIES LLC	B11	1	Shell Rock		Roadway Testing Required
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock	8.3	127
93721	MAYACA MATERIALS	B11	1	Shell Rock	9.0	126
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Agg	15.8	111
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina	8.7	129
94745	PATRICK JAMES ECYCLE	B12	1	Recycled Concrete Agg		Roadway Testing Required
94789	STEWART MINING INDUSTRIES INC.	B03	1	Cemented Coquina	8.4	129

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 9/21/2015 to 12/22/2015
Reference: Section 200



Pit Proctor Quarterly Report

Print Date: 1/4/2016
1:26:40PM

Valid from January 1, 2016 through March 31, 2016

DISTRICT: 05

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock	12.6	118
18056	DIXIE LIME & STONE CO.	B01	1	Limerock	12.3	117
18058	CEMEX	B01	1	Limerock	12.2	118
18393	BEDROCK RESOURCES	B01	1	Limerock	12.4	117
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock	12.4	116
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock	11.8	119
36350	MAGNUM CONSTRUCTION SOLUTIONS	B01	1	Limerock	11.7	119
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock	11.3	120
92757	BUCK HAMMOCK MINE	B02	1	Bank Run Shell		Roadway Testing Required
BA348	BAHAMAS ROCK LIMITED	B01	1	Limerock		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 9/21/2015 to 12/22/2015
Reference: Section 200



Pit Proctor Quarterly Report

Print Date: 1/4/2016
1:26:40PM

Valid from January 1, 2016 through March 31, 2016

DISTRICT: 06

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock	8.7	127
87089	CEMEX	B01	1	Limerock	7.4	132
87090	CEMEX	B01	1	Limerock	7.2	133
87090	CEMEX	B01	2	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	1	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	2	Limerock	8.3	129
87145	TITAN AMERICA, LLC.	B01	4	Limerock		Roadway Testing Required
87339	WHITE ROCK QUARRIES	B01	1	Limerock	8.0	132
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock	7.3	133
87633	WHITE ROCK QUARRIES	B01	1	Limerock	7.8	126
87648	SDI QUARRY, INC.	B01	1	Limerock	7.1	132
90638	CHARLIE TOPPINO & SONS INC.	B01	1	Limerock		Roadway Testing Required
90765	GRADER MIKE, LLC	B01	1	Limerock		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 9/21/2015 to 12/22/2015
Reference: Section 200



Pit Proctor Quarterly Report

Print Date: 1/4/2016
1:26:40PM

Valid from January 1, 2016 through March 31, 2016

DISTRICT: 07

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock		Roadway Testing Required
02675	CEMEX	B01	1	Limerock	8.2	132
08050	E.R. JAHNA INDUSTRIES INC.	B01	1	Limerock		Roadway Testing Required
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Agg		Roadway Testing Required
13662	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Agg		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	1	Limerock		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock	11.8	118
14262	CENTRAL STATE AGGREGATES, LLC	B01	3	Limerock		Roadway Testing Required
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock	11.7	117
15755	SONNY GLASBRENNER	B12	1	Recycled Concrete Agg		Roadway Testing Required

Est. Optimum Moisture* = Department's estimate of optimum moisture based on data from the mine.
Data from Mines for Date Range: 9/21/2015 to 12/22/2015
Reference: Section 200