



# Pit Proctor Quarterly Report

Print Date: 6/30/2016  
2:24:09PM

Valid from July 1, 2016 through September 30,2016

## DISTRICT: 01

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
01305	EARTHSOURCE INC.	B11	1	Shell Rock	8.8	126
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock		Roadway Testing Required
01730	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B11	1	Shell Rock	8.3	131
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell	9.6	124
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell	9.3	124
01800	ICS MATERIALS INC.	B11	1	Shell Rock	8.3	131
01805	MAGNUM MATERIALS, LLC	B11	1	Shell Rock	7.7	130
01807	BERMONT RESERVOIR - LAKE EXCAVATION	B02	1	Bank Run Shell		Roadway Testing Required
01815	HIGHLAND MATERIALS	B02	1	Bank Run Shell	8.9	121
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock	7.9	126
03616	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock	8.8	127
03811	846 MINE	B01	1	Limerock		Roadway Testing Required
05354	RIDGDILL & SONS INC.	B01	1	Limerock	9.7	126
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock		Roadway Testing Required
12008	CEMEX	B01	2	Limerock	7.6	131
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock	9.0	127
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock	9.0	124
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock		Roadway Testing Required
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock		Roadway Testing Required
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock	8.7	127
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock	8.3	128
17710	FREDERICK DERR & COMPANY	B12	1	Recycled Concrete Agg		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 3/22/2016 to 6/21/2016  
 Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2016  
2:27:14PM

Valid from July 1, 2016 through September 30, 2016

17724 MASTERROCK LLC.

B12 1 Recycled Concrete Agg

Roadway Testing Required

**DISTRICT: 02**

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock	12.1	120
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock	13.9	114
26098	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	11.9	120
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
26782	LIMESTONE MATERIALS	B01	1	Limerock	12.1	114
33496	BLUE ROK INC.	B01	1	Limerock	11.4	121
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock	12.6	118
37112	SUWANNEE AMERICAN CEMENT	B01	1	Limerock		Roadway Testing Required
37112	SUWANNEE AMERICAN CEMENT	B01	2	Limerock		Roadway Testing Required
37622	DENALI INVESTMENTS INC.	B01	1	Limerock	13.5	115
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock	9.0	128
38627	A MINING GROUP, LLC	B01	1	Limerock	9.9	125
78697	EAST COAST AGGREGATES LLC	B11	1	Shell Rock		Roadway Testing Required
GA206	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate		Roadway Testing Required
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate		Roadway Testing Required
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 3/22/2016 to 6/21/2016  
 Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2016  
2:27:14PM

Valid from July 1, 2016 through September 30,2016

## DISTRICT: 03

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
53271	DOLOMITE INC.	B01	1	Limerock	14.0	115
53357	NORTH FLORIDA ROCK LTD.	B01	1	Limerock	14.3	116
53357	NORTH FLORIDA ROCK LTD.	B01	2	Limerock	13.8	115
53575	MARIANNA HI-CAL LLC	B01	1	Limerock		Roadway Testing Required
53575	MARIANNA HI-CAL LLC	B01	2	Limerock		Roadway Testing Required
53575	MARIANNA HI-CAL LLC	B01	3	Limerock		Roadway Testing Required
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock		Roadway Testing Required
53706	ANDERSON COLUMBIA	B01	1	Limerock	12.2	118
61377	SIKES SAND & GRAVEL	B12	1	Recycled Concrete Agg		Roadway Testing Required
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock	13.4	119
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate		Roadway Testing Required
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate		Roadway Testing Required
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock	14.9	118
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock	14.8	119
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock		Roadway Testing Required
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock	13.3	117
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock	14.3	115
AL775	BROOKLYN LIMESTONE QUARRY	B01	3	Limerock	14.2	117

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 3/22/2016 to 6/21/2016  
 Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2016  
2:27:14PM

Valid from July 1, 2016 through September 30,2016

## DISTRICT: 04

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina		Roadway Testing Required
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina	8.5	130
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock	8.3	131
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock	8.0	130
93366	STAR QUARRIES LLC	B01	1	Limerock		Roadway Testing Required
93366	STAR QUARRIES LLC	B11	1	Shell Rock	9.5	122
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock	8.3	128
93721	MAYACA MATERIALS	B11	1	Shell Rock	8.7	125
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Agg		112
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina	8.0	129
94745	PATRICK JAMES ECYCLE	B12	1	Recycled Concrete Agg		Roadway Testing Required
94789	STEWART MINING INDUSTRIES INC.	B03	1	Cemented Coquina	7.8	130

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 3/22/2016 to 6/21/2016  
 Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2016  
2:27:14PM

Valid from July 1, 2016 through September 30, 2016

## DISTRICT: 05

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock	11.7	120
18056	DIXIE LIME & STONE CO.	B01	1	Limerock	12.6	117
18058	CEMEX	B01	1	Limerock	12.0	118
18393	BEDROCK RESOURCES	B01	1	Limerock	12.8	115
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock	12.2	117
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock	11.9	120
36350	MAGNUM CONSTRUCTION SOLUTIONS	B01	1	Limerock		Roadway Testing Required
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock		Roadway Testing Required
36812	MAGNUM MATERIALS	B01	1	Limerock		Roadway Testing Required
92757	BUCK HAMMOCK MINE	B02	1	Bank Run Shell		Roadway Testing Required
BA348	BAHAMAS ROCK LIMITED	B01	1	Limerock		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2016 to 6/21/2016  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2016  
2:27:14PM

Valid from July 1, 2016 through September 30, 2016

## DISTRICT: 06

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock	9.0	129
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock	9.1	126
87089	CEMEX	B01	1	Limerock	7.3	132
87090	CEMEX	B01	1	Limerock	7.9	130
87090	CEMEX	B01	2	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	1	Limerock	9.2	127
87145	TITAN AMERICA, LLC.	B01	2	Limerock		Roadway Testing Required
87145	TITAN AMERICA, LLC.	B01	4	Limerock		Roadway Testing Required
87339	WHITE ROCK QUARRIES	B01	1	Limerock	8.2	130
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock	7.3	132
87633	WHITE ROCK QUARRIES	B01	1	Limerock	9.3	129
87648	SDI QUARRY, INC.	B01	1	Limerock	7.3	130

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2016 to 6/21/2016  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 6/30/2016  
2:27:14PM

Valid from July 1, 2016 through September 30,2016

## DISTRICT: 07

Mine	Company Name	Product	Process	Description	Est. Optimum Moisture*	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock		Roadway Testing Required
02675	CEMEX	B01	1	Limerock	8.0	132
08050	E.R. JAHNA INDUSTRIES INC.	B01	1	Limerock		Roadway Testing Required
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Agg		Roadway Testing Required
13662	VULCAN MATERIALS COMPANY	B01	1	Limerock		Roadway Testing Required
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Agg		Roadway Testing Required
13810	C-SQUARED CGC, INC	B12	1	Recycled Concrete Agg		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	1	Limerock		Roadway Testing Required
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock	12.6	116
14262	CENTRAL STATE AGGREGATES, LLC	B01	3	Limerock		Roadway Testing Required
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock	11.6	117
15755	SONNY GLASBRENNER	B12	1	Recycled Concrete Agg		Roadway Testing Required

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 3/22/2016 to 6/21/2016  
Reference: Section 200