



# Pit Proctor Quarterly Report

Generated: 5/03/2017 11:57:49 AM

**Valid from 04/01/ 2017 to 06/30/ 2017**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01305	EARTHSOURCE INC.	B11	1	Shell Rock Base	9.5	123
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock Base	**	**
01730	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B11	1	Shell Rock Base	8.3	131
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell Base	9.1	127
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell Base	10.1	125
01800	ICS MATERIALS INC.	B11	1	Shell Rock Base	**	**
01805	MAGNUM MATERIALS	B11	1	Shell Rock Base	**	**
01807	BERMONT RESERVOIR - LAKE EXCAVATION	B02	1	Bank Run Shell Base	**	**
01815	HIGHLAND MATERIALS	B02	1	Bank Run Shell Base	9.5	125
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.3	120
03340	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B01	1	Limerock Base	**	**
03616	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	9.0	127
03811	THE 846 MINE	B01	1	Limerock Base	**	**
05354	RIDGDILL & SONS INC.	B01	1	Limerock Base	10.1	126
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock Base	**	**
12008	CEMEX	B01	2	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	8.1	125
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2017 to 03/31/ 2017 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

**Valid from 04/01/ 2017 to 06/30/ 2017**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	8.4	129
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	**	**
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**
13810	C-SQUARED CGC, INC.	B12	1	Recycled Concrete Base	**	**
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**
17724	MASTERROCK LLC.	B12	1	Recycled Concrete Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2017 to 03/31/ 2017 | Reference: Section 200

\*\* Roadway Testing Required  
 Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/ 2017 to 06/30/ 2017**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	13.0	117
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	13.1	118
26098	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	12.2	118
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	13.4	117
33496	BLUE ROK INC.	B01	1	Limerock Base	12.2	116
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	**	**
37112	SUWANNEE AMERICAN CEMENT	B01	1	Limerock Base	12.0	118
37112	SUWANNEE AMERICAN CEMENT	B01	2	Limerock Base	**	**
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	**	**
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	15.0	127
38627	A MINING GROUP, LLC	B01	1	Limerock Base	10.5	121
78697	EAST COAST AGGREGATES LLC	B11	1	Shell Rock Base	9.3	129
TM445	CEMEX	B01	1	Limerock Base	**	**
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2017 to 03/31/ 2017 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 5/03/2017 11:57:49 AM

**Valid from 04/01/ 2017 to 06/30/ 2017**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
53271	DOLOMITE INC.	B01	1	Limerock Base	11.6	115
53357	NORTH FLORIDA ROCK LTD.	B01	1	Limerock Base	12.7	113
53357	NORTH FLORIDA ROCK LTD.	B01	2	Limerock Base	12.6	114
53575	MARIANNA HI-CAL LLC	B01	1	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	2	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	3	Limerock Base	**	**
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock Base	**	**
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	12.8	118
61377	SIKES SAND & GRAVEL	B12	1	Recycled Concrete Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	11.6	120
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	13.2	119
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	13.4	117
AL775	BROOKLYN LIMESTONE QUARRY	B01	3	Limerock Base	**	**
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2017 to 03/31/ 2017 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Valid from 04/01/ 2017 to 06/30/ 2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	**	**
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	8.2	130
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock Base	9.0	128
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	8.1	128
93366	STAR QUARRIES LLC	B01	1	Limerock Base	43.3	124
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	**	**
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	8.0	128
93721	MAYACA MATERIALS	B11	1	Shell Rock Base	8.2	125
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	15.5	111
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	7.8	129
94745	PATRICK JAMES ECYCLE	B12	1	Recycled Concrete Base	**	**
94789	STEWART MINING INDUSTRIES INC.	B03	1	Cemented Coquina Base	7.8	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2017 to 03/31/ 2017 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/ 2017 to 06/30/ 2017**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock Base	12.3	120
18020	CEMEX	B01	2	Limerock Base	**	**
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	12.9	116
18058	CEMEX	B01	1	Limerock Base	12.3	118
18058	CEMEX	B01	2	Limerock Base	**	**
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.7	116
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	13.0	116
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	11.6	122
36350	MAGNUM MATERIALS	B01	1	Limerock Base	**	**
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	**	**
36812	MAGNUM MATERIALS	B01	1	Limerock Base	**	**
36818	MAGNUM MATERIALS	B01	1	Limerock Base	**	**
36826	SCI MATERIALS	B01	1	Limerock Base	13.5	118
75780	S&L MATERIALS, INC.	B12	1	Recycled Concrete Base	11.8	117
92757	BUCK HAMMOCK MINE	B02	1	Bank Run Shell Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM447	CEMEX	B01	1	Limerock Base	**	**
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2017 to 03/31/ 2017 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/ 2017 to 06/30/ 2017**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	7.3	130
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	7.0	132
87089	CEMEX	B01	1	Limerock Base	7.8	131
87090	CEMEX	B01	1	Limerock Base	7.4	132
87090	CEMEX	B01	2	Limerock Base	**	**
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	**	**
87145	TITAN AMERICA, LLC.	B01	2	Limerock Base	**	**
87145	TITAN AMERICA, LLC.	B01	4	Limerock Base	**	**
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	8.6	130
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	8.3	132
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	9.2	126
87648	SDI QUARRY, INC.	B01	1	Limerock Base	7.3	131
87823	THE REDLAND COMPANY, INC.	B01	1	Limerock Base	7.4	130
90638	CHARLIE TOPPINO & SONS INC.	B01	1	Limerock Base	**	**
90765	GRADER MIKE, LLC	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/ 2017 to 03/31/ 2017 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



## Pit Proctor Quarterly Report

**Valid from 04/01/2017 to 06/30/2017**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

### District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock Base	12.6	115
02675	CEMEX	B01	1	Limerock Base	8.7	131
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	13.0	115
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	11.9	121
13662	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	1	Limerock Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	11.8	117
14262	CENTRAL STATE AGGREGATES, LLC	B01	3	Limerock Base	**	**
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock Base	11.4	118
15755	SONNY GLASBRENNER	B12	1	Recycled Concrete Base	12.8	115
15814	INDEPENDENCE RECYCLING OF FLORIDA INC.	B12	1	Recycled Concrete Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 01/01/2017 to 03/31/2017 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter