



Pit Proctor Quarterly Report

Valid from 10/01/2017 to 12/31/2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01305	EARTHSOURCE INC.	B11	1	Shell Rock Base	**	**
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock Base	**	**
01730	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B11	1	Shell Rock Base	**	**
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell Base	9.7	123
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell Base	8.5	126
01800	ICS MATERIALS INC.	B11	1	Shell Rock Base	**	**
01805	MAGNUM MATERIALS	B11	1	Shell Rock Base	**	**
01807	BERMONT RESERVOIR - LAKE EXCAVATION	B02	1	Bank Run Shell Base	**	**
01815	HIGHLAND MATERIALS	B02	1	Bank Run Shell Base	9.0	126
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
03340	ALLIGATOR ALLEY AGGREGATE AND ASPHALT	B01	1	Limerock Base	**	**
03616	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	9.1	129
03811	THE 846 MINE	B01	1	Limerock Base	**	**
05354	RIDGDILL & SONS INC.	B01	1	Limerock Base	9.0	127
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock Base	**	**
12008	CEMEX	B01	2	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/2017 to 09/30/2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Valid from 10/01/ 2017 to 12/31/ 2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	8.9	123
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	9.0	125
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**
13810	C-SQUARED CGC, INC.	B12	1	Recycled Concrete Base	**	**
16822	ANGELO'S AGGREGATE MATERIALS LAKELAND	B12	1	Recycled Concrete Base	**	**
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**
17724	MASTERROCK LLC.	B12	1	Recycled Concrete Base	**	**
91821	SAND HILL ROCK LLC	B03	1	Cemented Coquina Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/ 2017 to 09/30/ 2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 10/18/2017 8:30:10 AM

Valid from 10/01/2017 to 12/31/2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	12.5	117
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	13.3	116
26098	WHITE HOLDING COMPANY, LLC.	B01	1	Limerock Base	12.1	118
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	13.0	117
33496	BLUE ROK INC.	B01	1	Limerock Base	11.7	121
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	**	**
37112	SUWANNEE AMERICAN CEMENT	B01	1	Limerock Base	12.1	118
37112	SUWANNEE AMERICAN CEMENT	B01	2	Limerock Base	**	**
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	13.4	114
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.5	127
38627	A MINING GROUP, LLC	B01	1	Limerock Base	10.9	118
72835	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
78697	EAST COAST AGGREGATES LLC	B11	1	Shell Rock Base	**	**
TM445	CEMEX	B01	1	Limerock Base	**	**
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/2017 to 09/30/2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 10/18/2017 8:30:10 AM

Valid from 10/01/2017 to 12/31/2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
53271	DOLOMITE INC.	B01	1	Limerock Base	11.3	116
53357	NORTH FLORIDA ROCK LLC.	B01	1	Limerock Base	12.2	115
53357	NORTH FLORIDA ROCK LLC.	B01	2	Limerock Base	12.1	115
53575	MARIANNA HI-CAL LLC	B01	1	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	2	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	3	Limerock Base	**	**
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock Base	**	**
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	**	**
61377	SIKES SAND & GRAVEL	B12	1	Recycled Concrete Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	12.8	120
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	13.0	118
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	14.0	116
AL775	BROOKLYN LIMESTONE QUARRY	B01	3	Limerock Base	**	**
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/2017 to 09/30/2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Valid from 10/01/ 2017 to 12/31/ 2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
TM833	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
The date range used for the mine data are from: 07/01/ 2017 to 09/30/ 2017 | Reference: Section 200
** Roadway Testing Required
Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 10/18/2017 8:30:10 AM

Valid from 10/01/ 2017 to 12/31/ 2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	**	**
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	7.9	131
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock Base	8.9	123
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	7.8	130
93366	STAR QUARRIES LLC	B01	1	Limerock Base	**	**
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	**	**
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	7.7	129
93721	MAYACA MATERIALS	B11	1	Shell Rock Base	8.7	126
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	**	**
93824	ALLSTAR AGGREGATES	B12	1	Recycled Concrete Base	**	**
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	7.9	129
94745	RECYCLING ROCKS	B12	1	Recycled Concrete Base	**	**
94789	STEWART MATERIALS LLC	B03	1	Cemented Coquina Base	7.9	130

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/ 2017 to 09/30/ 2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 10/18/2017 8:30:10 AM

Valid from 10/01/2017 to 12/31/2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock Base	11.3	118
18020	CEMEX	B01	2	Limerock Base	**	**
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	12.4	117
18058	CEMEX	B01	1	Limerock Base	11.5	119
18058	CEMEX	B01	2	Limerock Base	**	**
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.5	116
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	13.3	116
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	10.9	123
36350	MAGNUM MATERIALS	B01	1	Limerock Base	**	**
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	**	**
36812	MAGNUM MATERIALS	B01	1	Limerock Base	**	**
36818	MAGNUM MATERIALS	B01	1	Limerock Base	**	**
36826	SCI MATERIALS	B01	1	Limerock Base	12.3	117
75780	S&L MATERIALS, INC.	B12	1	Recycled Concrete Base	**	**
75819	ON SITE RECYCLED CONCRETE AGGREGATE FOR	B12	1	Recycled Concrete Base	**	**
92757	BUCK HAMMOCK MINE	B02	1	Bank Run Shell Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM447	CEMEX	B01	1	Limerock Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/2017 to 09/30/2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Valid from 10/01/ 2017 to 12/31/ 2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
The date range used for the mine data are from: 07/01/ 2017 to 09/30/ 2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Valid from 10/01/ 2017 to 12/31/ 2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	8.0	127
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	7.3	131
87089	CEMEX	B01	1	Limerock Base	7.3	132
87090	CEMEX	B01	1	Limerock Base	7.6	132
87090	CEMEX	B01	2	Limerock Base	**	**
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	8.0	130
87145	TITAN AMERICA, LLC.	B01	2	Limerock Base	**	**
87145	TITAN AMERICA, LLC.	B01	4	Limerock Base	**	**
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	8.5	132
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	7.4	135
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	9.0	126
87648	SDI AGGREGATES, INC.	B01	1	Limerock Base	7.8	132
87823	THE REDLAND COMPANY, INC.	B01	1	Limerock Base	9.0	131
90638	CHARLIE TOPPINO & SONS INC.	B01	1	Limerock Base	**	**
90765	GRADER MIKE, LLC	B01	1	Limerock Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/ 2017 to 09/30/ 2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 10/18/2017 8:30:10 AM

Valid from 10/01/ 2017 to 12/31/ 2017

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock Base	**	**
02675	CEMEX	B01	1	Limerock Base	7.8	132
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	**	**
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.0	127
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	**	**
13662	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	1	Limerock Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	11.8	116
14262	CENTRAL STATE AGGREGATES, LLC	B01	3	Limerock Base	**	**
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock Base	11.2	120
15755	SONNY GLASBRENNER	B12	1	Recycled Concrete Base	11.3	119
15814	INDEPENDENCE RECYCLING OF FLORIDA INC.	B12	1	Recycled Concrete Base	**	**
15820	ANGELO'S AGGREGATE MATERIALS ST. PETE	B12	1	Recycled Concrete Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine
 The date range used for the mine data are from: 07/01/ 2017 to 09/30/ 2017 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter