FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM Inspection/CIDR Report with PDF attachment(s)

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

STRUCTURE NAME: US41NB/FAKA UNION CANAL

INSPECTION DATE: 3/27/2019 MYDL

OWNER: 1 State Highway Agency YEAR BUILT: 1969

MAINTAINED BY: 1 State Highway Agency SECTION NO.: 03 010 000

STRUCTURE TYPE: 5 Prestressed Concrete - 02 Stringer/Girder MP: 34.229

LOCATION: 13.7 MILES SE OF SR-951 ROUTE: 00041

SERV. TYPE ON: 1 Highway FACILITY CARRIED: US-41 NB

SERV. TYPE UNDER: 5 Waterway FEATURE INTERSECTED: FAKA UNION CANAL

FUNCTIONALLY OBSOLETE STRUCTURALLY DEFICIENT

TYPE OF INSPECTION: Regular NBI

BY: Volkert

DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 3/27/2019 UNDERWATER: 2/12/2019

Attach Sufficiency Rating: 99.9
HEALTH INDEX: 95.81