



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock Base	9.5	134
01495	SOUTHWEST AGGREGATES	B11	2	Shell Rock Base	**	**
01730	FLORIDA SHELL	B11	1	Shell Rock Base	7.8	132
01791	WATERMELON PIT, LLC	B02	1	Bank Run Shell Base	9.2	129
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell Base	9.5	129
01815	HIGHLAND MATERIALS	B02	1	Bank Run Shell Base	**	**
01863	WILLIAMS FARMS SAND AND SHELL, INC.	B02	1	Bank Run Shell Base	9.5	125
01864	R & J DIRTWORKS, LLC.	B02	1	Bank Run Shell Base	9.3	125
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
03616	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	8.6	130
03811	THE 846 MINE	B01	1	Limerock Base	**	**
03848	SOUTH GROVE MINE L.L.C.	B11	1	Shell Rock Base	7.5	131
05354	RIDGDILL & SONS INC.	B01	1	Limerock Base	10.2	125
05771	SEMINOLE TRIBE OF FLORIDA, INC.	B11	1	Shell Rock Base	8.7	129
05854	STATE ROAD 80 MINE	B02	1	Bank Run Shell Base	**	**
05856	EHC, INC	B11	1	Shell Rock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.6	125
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	9.6	126
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	9.4	129
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	**	**
12841	TITAN AMERICA	B01	1	Limerock Base	**	**
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**
16822	ANGELO'S AGGREGATE MATERIALS LAKELAND	B12	1	Recycled Concrete Base	**	**
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	12.4	118
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26098	LIMEROCK INDUSTRIES, INC.	B01	1	Limerock Base	11.4	121
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	12.1	119
33496	BLUE ROK INC.	B01	1	Limerock Base	11.4	121
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	12.4	120
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	13.5	115
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	10.1	127
38627	CONRAD YELVINGTON DISTRIBUTORS A MINING	B01	1	Limerock Base	10.8	120
72835	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
78697	SRM MATERIALS	B11	1	Shell Rock Base	**	**
TM445	CEMEX	B01	1	Limerock Base	8.0	130
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.5	132

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
50845	ANDERSON COLUMBIA, INC.	B12	1	Recycled Concrete Base	**	**
50846	ANDERSON COLUMBIA INC.	B12	1	Recycled Concrete Base	**	**
53271	DOLOMITE INC.	B01	1	Limerock Base	12.6	114
53357	NORTH FLORIDA ROCK LLC.	B01	1	Limerock Base	13.0	112
53357	NORTH FLORIDA ROCK LLC.	B01	3	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	1	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	2	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	3	Limerock Base	**	**
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock Base	**	**
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	12.7	117
53836	WHITE HOLDING COMPANY, LLC	B01	1	Limerock Base	**	**
53836	WHITE HOLDING COMPANY, LLC	B01	2	Limerock Base	12.8	120
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	13.8	114
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL756	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	12.2	123
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	14.1	116

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
AL775	BROOKLYN LIMESTONE QUARRY	B01	3	Limerock Base	**	**
AL870	RANDALL JASON HYATT, INC.	B01	1	Limerock Base	**	**
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	145
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	145
TM528	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	145
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	8.9	131
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
TM833	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.8	137
TM839	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	145
TM842	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.8	137
TM857	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	8.9	131

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	**	**
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	**	**
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock Base	9.4	127
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	**	**
93366	STAR QUARRIES LLC	B01	1	Limerock Base	**	**
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	**	**
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	8.1	128
93721	MAYACA MATERIALS	B11	1	Shell Rock Base	8.3	126
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	14.7	114
93824	ALLSTAR AGGREGATES	B12	1	Recycled Concrete Base	**	**
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	7.6	127
94789	STEWART MATERIALS LLC	B03	1	Cemented Coquina Base	7.8	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock Base	12.0	120
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	12.8	115
18058	CEMEX	B01	1	Limerock Base	12.0	120
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.8	114
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	13.2	115
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	11.8	119
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	11.9	118
36826	SCI MATERIALS	B01	1	Limerock Base	13.4	115
70827	WAYNE'S AGGREGATE & MATERIALS LLC	B03	1	Cemented Coquina Base	**	**
70866	SUNSHINE MINE	B03	1	Cemented Coquina Base	7.5	132
70867	STAVOLA AGGREGATE SUPPLY	B03	1	Cemented Coquina Base	7.4	132
75819	ON SITE RECYCLED CONCRETE AGGREGATE FOR FDOT BASE, CODE B12 ON I-4 ULTIMATE ONLY.	B12	1	Recycled Concrete Base	12.6	115
92757	BUCK HAMMOCK	B02	1	Bank Run Shell Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock Base	12.8	115
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM447	CEMEX	B01	1	Limerock Base	8.0	130
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	8.2	132
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	9.4	128
87089	CEMEX	B01	1	Limerock Base	8.2	132
87090	CEMEX	B01	1	Limerock Base	8.0	130
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	8.0	128
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	7.8	132
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	8.4	131
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	**	**
87648	SDI AGGREGATES, INC.	B01	1	Limerock Base	7.4	131
87816	COMMUNITY ASPHALT CORPORATION	B01	1	Limerock Base	8.6	131

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter





# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock Base	11.9	118
02675	CEMEX	B01	1	Limerock Base	8.0	132
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	**	**
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	12.8	116
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock Base	**	**
15820	ANGELO'S AGGREGATE MATERIALS ST. PETE	B12	1	Recycled Concrete Base	**	**
15838	ANGELO'S RECYCLED MATERIALS LARGO	B12	1	Recycled Concrete Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 4/28/2020 4:32:29 PM

**Valid from 4/1/2020 to 6/30/2020**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 99

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	145
AL519	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.8	137
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
BA348	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	8.9	131
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate Base	6.7	144
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate Base	**	**
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 1/1/2020 to 3/31/2020 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter