



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock Base	**	**
01495	SOUTHWEST AGGREGATES	B11	2	Shell Rock Base	8.8	130
01730	FLORIDA SHELL	B11	1	Shell Rock Base	8.1	133
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell Base	8.8	127
01863	WILLIAMS FARMS SAND AND SHELL, INC.	B02	1	Bank Run Shell Base	9.2	126
01879	WRIGHT FARMS	B02	1	Bank Run Shell Base	10.4	123
03037	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
03616	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	8.6	127
03811	THE 846 MINE	B01	1	Limerock Base	**	**
03848	SOUTH GROVE MINE L.L.C.	B11	1	Shell Rock Base	**	**
05354	RIDGDILL & SONS INC.	B01	1	Limerock Base	9.4	128
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.3	127
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	8.9	128
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	9.2	127
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	**	**
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**
91821	SAND HILL ROCK LLC	B03	1	Cemented Coquina Base	7.9	131

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	12.8	117
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26098	LIMEROCK INDUSTRIES, INC.	B01	1	Limerock Base	12.4	119
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	12.8	118
33496	BLUE ROK INC.	B01	1	Limerock Base	12.3	118
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	11.8	121
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	13.0	115
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
38627	CONRAD YELVINGTON DISTRIBUTORS A MINING	B01	1	Limerock Base	11.3	121
72835	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
78697	SRM MATERIALS	B11	1	Shell Rock Base	**	**
TM445	CEMEX	B01	1	Limerock Base	8.0	131
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.5	132

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
50845	ANDERSON COLUMBIA, INC.	B12	1	Recycled Concrete Base	**	**
50846	ANDERSON COLUMBIA INC.	B12	1	Recycled Concrete Base	**	**
53271	DOLOMITE INC.	B01	1	Limerock Base	12.3	116
53357	NORTH FLORIDA ROCK LLC.	B01	1	Limerock Base	12.4	119
53357	NORTH FLORIDA ROCK LLC.	B01	3	Limerock Base	**	**
53575	MARIANNA HI-CAL LLC	B01	1	Limerock Base	14.4	113
53575	MARIANNA HI-CAL LLC	B01	2	Limerock Base	**	**
53670	MARIANNA LIME PRODUCTS INC.	B01	1	Limerock Base	**	**
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	13.3	120
53836	WHITE HOLDING COMPANY, LLC	B01	1	Limerock Base	**	**
53836	WHITE HOLDING COMPANY, LLC	B01	2	Limerock Base	12.2	123
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	12.9	119
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL756	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	10.3	129
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	12.0	118
AL775	BROOKLYN LIMESTONE QUARRY	B01	3	Limerock Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.2	144
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.2	144
TM528	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.2	144
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.5	129
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
TM833	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.4	140
TM839	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.2	144
TM842	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.4	140
TM857	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	9.5	129

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
86862	PORT EVERGLADES	B11	1	Shell Rock Base	8.6	129
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	8.3	131
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	**	**
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock Base	9.6	127
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	**	**
93366	STAR QUARRIES LLC	B01	1	Limerock Base	**	**
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	**	**
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	8.1	128
93721	MAYACA MATERIALS	B11	1	Shell Rock Base	8.5	125
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	14.0	113
93824	ALLSTAR AGGREGATES	B12	1	Recycled Concrete Base	**	**
93875		B12	1	Recycled Concrete Base	**	**
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	7.4	127
94789	STEWART MATERIALS LLC	B03	1	Cemented Coquina Base	8.3	129

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock Base	11.3	118
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	12.2	117
18058	CEMEX	B01	1	Limerock Base	11.7	118
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.4	116
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	12.8	115
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	11.3	121
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	**	**
36826	SCI MATERIALS	B01	1	Limerock Base	12.2	118
70866	SUNSHINE MINE	B03	1	Cemented Coquina Base	7.3	132
70867	STAVOLA AGGREGATE SUPPLY	B03	1	Cemented Coquina Base	7.6	131
75780	S&L MATERIALS, INC.	B12	1	Recycled Concrete Base	**	**
75819	ON SITE RECYCLED CONCRETE AGGREGATE FOR FDOT BASE, CODE B12 ON I-4 ULTIMATE ONLY.	B12	1	Recycled Concrete Base	12.3	115
92757	BUCK HAMMOCK	B02	1	Bank Run Shell Base	9.2	131
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B01	1	Limerock Base	12.2	117
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM447	CEMEX	B01	1	Limerock Base	8.0	131
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM664	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	10.0	127

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	8.5	129
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	7.8	132
87089	CEMEX	B01	1	Limerock Base	8.0	131
87090	CEMEX	B01	1	Limerock Base	8.0	131
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	8.9	127
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	7.7	129
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	7.8	133
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	**	**
87648	SDI AGGREGATES, INC.	B01	1	Limerock Base	7.2	133
87816	COMMUNITY ASPHALT CORPORATION	B01	1	Limerock Base	8.2	129
87874	HALLEY ENGINEERING CONTRACTORS, INC.	B01	1	Limerock Base	7.1	135

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock Base	**	**
02675	CEMEX	B01	1	Limerock Base	8.5	131
02834	HOLCIM US	B01	1	Limerock Base	**	**
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	**	**
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	12.6	117
14699	SUN WEST AQUISITION CORP.	B01	1	Limerock Base	10.1	121
15838	ANGELO'S RECYCLED MATERIALS LARGO	B12	1	Recycled Concrete Base	**	**
TM322	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.5	129

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/7/2021 8:03:46 AM

Valid from 1/1/2021 to 3/31/2021

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 99

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.2	144
AL519	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.4	140
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
BA348	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	9.5	129
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate Base	6.6	145
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate Base	**	**
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2020 to 12/31/2020 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 15 days from the start of the quarter