



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01495	SOUTHWEST AGGREGATES	B11	1	Shell Rock Base	8.1	132
01495	SOUTHWEST AGGREGATES	B11	2	Shell Rock Base	**	**
01730	FLORIDA SHELL	B11	1	Shell Rock Base	7.7	132
01794	BERMONT EXCAVATING	B02	1	Bank Run Shell Base	9.1	127
01794	BERMONT EXCAVATING	B11	1	Shell Rock Base	**	**
01863	WILLIAMS FARMS SAND AND SHELL, INC.	B02	1	Bank Run Shell Base	8.9	129
01879	CJC SHELL, LLC.	B02	1	Bank Run Shell Base	8.0	136
03616	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	**	**
03811	THE 846 MINE	B01	1	Limerock Base	**	**
05354	RIDGDILL & SONS INC.	B01	1	Limerock Base	8.9	128
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.2	126
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	8.5	128
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	9.1	126
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	8.7	127
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**
13844	WOODRUFF & SONS, INC.	B12	1	Recycled Concrete Base	**	**
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**
91821	SAND HILL ROCK LLC	B03	1	Cemented Coquina Base	8.2	131

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	12.6	120
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	13.4	115
26098	LIMEROCK INDUSTRIES, INC.	B01	1	Limerock Base	11.8	120
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	11.5	119
33496	BLUE ROK INC.	B01	1	Limerock Base	**	**
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	**	**
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	12.9	117
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
38627	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	10.5	122
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
50845	ANDERSON COLUMBIA, INC.	B12	1	Recycled Concrete Base	**	**
50846	ANDERSON COLUMBIA INC.	B12	1	Recycled Concrete Base	**	**
53271	DOLOMITE INC.	B01	1	Limerock Base	11.0	121
53357	NORTH FLORIDA ROCK LLC.	B01	1	Limerock Base	11.8	116
53575	ALTERNATIVE MATERIALS LLC	B01	1	Limerock Base	13.0	120
53575	ALTERNATIVE MATERIALS LLC	B01	2	Limerock Base	**	**
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	14.0	112
53836	WHITE HOLDING COMPANY, LLC	B01	1	Limerock Base	**	**
53836	WHITE HOLDING COMPANY, LLC	B01	2	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL756	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	**	**
AL887	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	12.6	121
AL887	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	13.6	117
AL896	MOHAWK VALLEY MINING, LLC	B01	1	Limerock Base	12.3	119

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
TM155	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	8.9	130
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM528	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
TM833	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM839	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM842	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	**	**
TM857	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
86900	SEMINOLE BIG CYPRESS MINE	B11	1	Shell Rock Base	**	**
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	**	**
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	8.2	130
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock Base	**	**
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	**	**
93366	STAR QUARRIES LLC	B01	1	Limerock Base	10.5	128
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	10.6	123
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	8.0	126
93721	STAVOLA AGGREGATE SUPPLY	B11	1	Shell Rock Base	8.8	126
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	14.1	114
93824	ALLSTAR AGGREGATES	B12	1	Recycled Concrete Base	**	**
93875	FLORIDA RECYCLING SERVICES	B12	1	Recycled Concrete Base	13.7	115
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	**	**
94789	STEWART MATERIALS LLC	B03	1	Cemented Coquina Base	8.1	131

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock Base	12.3	117
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	12.6	116
18058	CEMEX	B01	1	Limerock Base	11.7	119
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.9	114
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	13.0	115
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	10.8	123
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	12.2	118
36826	GEORGIA STONE PRODUCTS	B01	1	Limerock Base	11.9	118
70866	SUNSHINE MINE	B03	1	Cemented Coquina Base	7.9	131
70867	STAVOLA AGGREGATE SUPPLY	B03	1	Cemented Coquina Base	7.7	133
75780	S&L MATERIALS, INC.	B12	1	Recycled Concrete Base	**	**
75819	ON SITE RECYCLED CONCRETE AGGREGATE FOR FDOT BASE, CODE B12 ON I-4 ULTIMATE ONLY.	B12	1	Recycled Concrete Base	**	**
75886	J. MCKINNON INC.	B02	1	Bank Run Shell Base	**	**
92757	BUCK HAMMOCK	B02	1	Bank Run Shell Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM447	CEMEX	B01	1	Limerock Base	8.3	129
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM664	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	**	**
87089	CEMEX	B01	1	Limerock Base	8.2	130
87090	CEMEX	B01	1	Limerock Base	8.3	129
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	**	**
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	8.7	133
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	7.5	133
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	**	**
87648	SDI AGGREGATES, INC.	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES INC.	B01	2	Limerock Base	**	**
02675	CEMEX	B01	1	Limerock Base	8.3	130
02905	CRYSTAL RIVER QUARRIES, INC.	B01	1	Limerock Base	**	**
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	12.6	115
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	11.3	119
15838	ANGELO'S RECYCLED MATERIALS LARGO	B12	1	Recycled Concrete Base	**	**
TM322	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter





# Pit Proctor Quarterly Report

Generated: 10/9/2023 10:52:16 AM

**Valid from 10/1/2023 to 12/31/2023**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 99

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.9	145
AL519	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.5	136
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
BA348	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	**	**
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate Base	6.8	144
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate Base	**	**
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 7/1/2023 to 9/30/2023 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 10 days from the start of the quarter