



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01495	SOUTHWEST AGGREGATES - PUNTA GORDA, FL	B11	2	Shell Rock Base	**	**
01495	SOUTHWEST AGGREGATES - PUNTA GORDA, FL	B11	1	Shell Rock Base	**	**
01730	FLORIDA SHELL - PUNTA GORDA, FL	B11	1	Shell Rock Base	7.6	131
01791	WATERMELON PIT, LLC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	9.3	124
01794	BERMONT EXCAVATING, LLC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	8.9	121
01794	BERMONT EXCAVATING, LLC. - PUNTA GORDA, FL	B11	1	Shell Rock Base	**	**
01863	WILLIAMS FARMS SAND AND SHELL, INC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	9.1	126
01879	CJC SHELL, LLC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	9.5	132
03616	CONRAD YELVINGTON DISTRIBUTORS - NAPLES, FL	B01	1	Limerock Base	**	**
03811	THE 846 MINE - NAPLES, FL	B01	1	Limerock Base	**	**
05354	RIDGILL & SONS, INC. - MOORE HAVEN, FL	B01	1	Limerock Base	8.3	128
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	8.3	127
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.6	125
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	8.7	128
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	8.7	128
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**
13844	WOODRUFF & SONS, INC.	B12	1	Recycled Concrete Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**
91821	SAND HILL ROCK LLC	B03	1	Cemented Coquina Base	7.7	133

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	12.3	119
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	13.1	116
26098	NEWBERRY LIMESTONE, LLC	B01	1	Limerock Base	12.6	117
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS, INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	11.8	120
33496	BLUE ROK INC.	B01	1	Limerock Base	12.0	118
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	12.7	117
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	12.5	118
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
38627	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	10.4	122
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.1	132

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
50845	ANDERSON COLUMBIA, INC.	B12	1	Recycled Concrete Base	**	**
50846	ANDERSON COLUMBIA INC.	B12	1	Recycled Concrete Base	**	**
53271	DOLOMITE INC.	B01	1	Limerock Base	11.8	120
53357	NORTH FLORIDA ROCK LLC.	B01	1	Limerock Base	12.3	113
53575	ALTERNATIVE MATERIALS LLC	B01	2	Limerock Base	**	**
53575	ALTERNATIVE MATERIALS LLC	B01	1	Limerock Base	12.5	118
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	13.5	115
53836	WHITE HOLDING COMPANY, LLC	B01	2	Limerock Base	**	**
53836	WHITE HOLDING COMPANY, LLC	B01	1	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	2	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	**	**
AL756	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	**	**
AL887	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	14.1	117
AL887	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	12.9	122
AL896	MOHAWK VALLEY MINING, LLC	B01	1	Limerock Base	12.6	117

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
TM155	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	144
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	144
TM528	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	144
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.1	132
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	5.7	145
TM833	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.6	137
TM839	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	144
TM842	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.6	137
TM857	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	9.6	130

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
86900	SEMINOLE BIG CYPRESS MINE	B11	1	Shell Rock Base	**	**
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	**	**
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	8.0	130
89673	LAKE POINT RESTORATION, LLC	B11	1	Shell Rock Base	8.4	128
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	**	**
93366	STAR QUARRIES LLC	B01	1	Limerock Base	10.7	125
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	11.0	122
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	8.2	125
93721	STAVOLA AGGREGATE SUPPLY	B11	1	Shell Rock Base	8.5	127
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	14.3	114
93824	ALLSTAR AGGREGATES	B12	1	Recycled Concrete Base	**	**
93875	FLORIDA RECYCLING SERVICES	B12	1	Recycled Concrete Base	13.6	114
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	**	**
94789	STEWART MATERIALS LLC	B03	1	Cemented Coquina Base	8.2	129

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock Base	13.0	117
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	12.4	116
18058	CEMEX	B01	1	Limerock Base	12.0	118
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.5	115
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	12.7	115
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	11.3	123
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	12.3	117
36826	GEORGIA STONE PRODUCTS	B01	1	Limerock Base	11.7	120
70866	SUNSHINE MINE	B03	1	Cemented Coquina Base	7.9	129
70867	STAVOLA AGGREGATE SUPPLY	B03	1	Cemented Coquina Base	7.5	133
75780	S&L MATERIALS, INC.	B12	1	Recycled Concrete Base	**	**
75819	ON SITE RECYCLED CONCRETE AGGREGATE FOR FDOT BASE, CODE B12 ON I-4 ULTIMATE ONLY.	B12	1	Recycled Concrete Base	**	**
75886	J. MCKINNON INC.	B02	1	Bank Run Shell Base	10.1	122
92757	BUCK HAMMOCK	B02	1	Bank Run Shell Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM447	CEMEX	B01	1	Limerock Base	7.8	130
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM664	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.6	130

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	**	**
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
87089	CEMEX	B01	1	Limerock Base	7.6	132
87090	CEMEX	B01	1	Limerock Base	7.8	130
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	**	**
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	8.8	134
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	7.9	132
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	**	**
87648	SDI AGGREGATES, INC.	B01	1	Limerock Base	7.6	130

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES, INC. - LECANTO, FL	B01	2	Limerock Base	**	**
02675	CEMEX, INC. - INGLIS, FL	B01	1	Limerock Base	7.7	130
02905	CRYSTAL RIVER QUARRIES, INC.	B01	1	Limerock Base	11.5	118
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	12.6	116
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	11.6	118
15838	ANGELO'S RECYCLED MATERIALS - LARGO, FL	B12	1	Recycled Concrete Base	**	**
TM322	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.6	130

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter



Pit Proctor Quarterly Report

Generated: 1/29/2024 3:45:46 PM

Valid from 1/1/2024 to 3/31/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

District: 99

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.8	144
AL519	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	6.6	137
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	5.7	145
BA348	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	9.6	130
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate Base	**	**
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate Base	7.2	144
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate Base	**	**

* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 10/1/2023 to 12/31/2023 | Reference: Section 200

** Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 13 days from the start of the quarter