



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 01

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
01495	SOUTHWEST AGGREGATES - PUNTA GORDA, FL	B11	2	Shell Rock Base	**	**
01495	SOUTHWEST AGGREGATES - PUNTA GORDA, FL	B11	1	Shell Rock Base	**	**
01730	FLORIDA SHELL - PUNTA GORDA, FL	B11	1	Shell Rock Base	9.1	131
01791	WATERMELON PIT, LLC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	9.2	130
01794	BERMONT EXCAVATING, LLC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	8.6	127
01794	BERMONT EXCAVATING, LLC. - PUNTA GORDA, FL	B11	1	Shell Rock Base	**	**
01863	WILLIAMS FARMS SAND AND SHELL, INC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	9.8	127
01879	CJC SHELL, LLC. - PUNTA GORDA, FL	B02	1	Bank Run Shell Base	10.3	123
03616	CONRAD YELVINGTON DISTRIBUTORS - NAPLES, FL	B01	1	Limerock Base	**	**
03811	THE 846 MINE - NAPLES, FL	B01	1	Limerock Base	9.1	126
05354	RIDGDILL & SONS, INC. - MOORE HAVEN, FL	B01	1	Limerock Base	8.9	130
12260	VULCAN MATERIALS COMPANY	B01	3	Limerock Base	**	**
12260	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	8.7	130
12260	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	9.7	125
12521	BONITA GRANDE AGGREGATES	B01	2	Limerock Base	9.3	129
12521	BONITA GRANDE AGGREGATES	B01	1	Limerock Base	**	**
12599	YOUNGQUIST BROTHERS ROCK INC.	B01	1	Limerock Base	**	**
12920	EARTH TECH ENTERPRISES, INC	B01	1	Limerock Base	**	**
13700	WOODRUFF AND SONS, INC.	B12	1	Recycled Concrete Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
13844	WOODRUFF & SONS, INC.	B12	1	Recycled Concrete Base	**	**
17710	FREDERICK DERR & COMPANY, INC	B12	1	Recycled Concrete Base	**	**
91821	SAND HILL ROCK LLC	B03	1	Cemented Coquina Base	8.1	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine  
 The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200  
 \*\* Roadway Testing Required  
 Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 02

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
26001	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	12.4	120
26002	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	12.2	119
26098	NEWBERRY LIMESTONE, LLC	B01	1	Limerock Base	11.9	121
26099	LIMESTONE PRODUCTS INC.	B01	1	Limerock Base	**	**
26100	LIMESTONE PRODUCTS, INC.	B01	1	Limerock Base	**	**
26782	LIMESTONE MATERIALS	B01	1	Limerock Base	12.2	118
33496	BLUE ROK INC.	B01	1	Limerock Base	12.1	121
34104	V.E. WHITEHURST & SONS, INC.	B01	1	Limerock Base	**	**
37622	DENALI INVESTMENTS INC.	B01	1	Limerock Base	13.5	116
38228	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
38627	CONRAD YELVINGTON DISTRIBUTORS	B01	1	Limerock Base	10.3	121
TM579	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.6	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 03

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
50845	ANDERSON COLUMBIA, INC.	B12	1	Recycled Concrete Base	**	**
50846	ANDERSON COLUMBIA INC.	B12	1	Recycled Concrete Base	**	**
53271	DOLOMITE INC.	B01	1	Limerock Base	**	**
53357	NORTH FLORIDA ROCK LLC.	B01	1	Limerock Base	12.4	116
53575	ALTERNATIVE MATERIALS LLC	B01	2	Limerock Base	**	**
53575	ALTERNATIVE MATERIALS LLC	B01	1	Limerock Base	11.7	121
53706	ANDERSON COLUMBIA	B01	1	Limerock Base	13.4	115
53836	WHITE HOLDING COMPANY, LLC	B01	2	Limerock Base	11.9	126
53836	WHITE HOLDING COMPANY, LLC	B01	1	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	2	Limerock Base	**	**
61391	WHITE HOLDING COMPANY LLC.	B01	1	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	3	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	2	Limerock Base	**	**
AL585	SOUTHERN ROCK AND LIME	B01	1	Limerock Base	**	**
AL756	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	**	**
AL775	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	11.9	124
AL887	BROOKLYN LIMESTONE QUARRY	B01	2	Limerock Base	14.9	116
AL887	BROOKLYN LIMESTONE QUARRY	B01	1	Limerock Base	13.3	121
AL896	MOHAWK VALLEY MINING, LLC	B01	2	Limerock Base	12.8	118

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
AL896	MOHAWK VALLEY MINING, LLC	B01	1	Limerock Base	**	**
TM155	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.6	130
TM508	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.9	146
TM523	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.9	146
TM528	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.9	146
TM531	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	**	**
TM630	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
TM833	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	7.8	136
TM839	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.9	146
TM842	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	7.8	136
TM857	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	9.6	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

Valid from 7/1/2024 to 9/30/2024

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 04

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
86900	SEMINOLE BIG CYPRESS MINE	B11	1	Shell Rock Base	**	**
88749	WILD TURKEY ESTATES	B03	1	Cemented Coquina Base	8.0	127
88783	BLUE GOOSE MINE	B03	1	Cemented Coquina Base	8.1	130
89673	ARCOSA AGGREGATES	B11	1	Shell Rock Base	7.9	131
89797	BLUE GOOSE CONSTRUCTION LLC	B11	1	Shell Rock Base	**	**
93366	STAR QUARRIES LLC	B01	1	Limerock Base	10.7	125
93366	STAR QUARRIES LLC	B11	1	Shell Rock Base	10.4	125
93406	PALM BEACH AGGREGATES INC.	B11	2	Shell Rock Base	8.1	126
93721	STAVOLA AGGREGATE SUPPLY	B11	1	Shell Rock Base	8.6	127
93793	D.S. EAKINS CONSTRUCTION CO.	B12	1	Recycled Concrete Base	15.3	111
93824	ALLSTAR AGGREGATES	B12	1	Recycled Concrete Base	**	**
93875	FLORIDA RECYCLING SERVICES	B12	1	Recycled Concrete Base	14.0	113
94209	VULCAN MATERIALS COMPANY	B03	2	Cemented Coquina Base	7.9	125
94789	STEWART MATERIALS LLC	B03	1	Cemented Coquina Base	7.9	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 05

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
18020	CEMEX	B01	1	Limerock Base	12.0	119
18056	DIXIE LIME & STONE CO.	B01	1	Limerock Base	12.4	116
18058	CEMEX	B01	1	Limerock Base	11.8	120
18393	BEDROCK RESOURCES	B01	1	Limerock Base	12.5	116
18634	MID-COAST AGGREGATES, LLC	B01	1	Limerock Base	13.5	114
36246	M. J. STAVOLA INDUSTRIES	B01	2	Limerock Base	11.1	122
36654	COMMERCIAL INDUSTRIAL CORP.	B01	1	Limerock Base	**	**
36826	GEORGIA STONE PRODUCTS	B01	1	Limerock Base	12.0	118
70866	SUNSHINE MINE	B03	1	Cemented Coquina Base	7.5	133
70867	STAVOLA AGGREGATE SUPPLY	B03	1	Cemented Coquina Base	7.6	133
75780	S&L MATERIALS, INC.	B12	1	Recycled Concrete Base	**	**
75819	ON SITE RECYCLED CONCRETE AGGREGATE FOR FDOT BASE, CODE B12 ON I-4 ULTIMATE ONLY.	B12	1	Recycled Concrete Base	**	**
75886	J. MCKINNON INC.	B02	1	Bank Run Shell Base	**	**
92757	BUCK HAMMOCK	B02	1	Bank Run Shell Base	**	**
TM336	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM407	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM447	CEMEX	B01	1	Limerock Base	8.0	130
TM586	CONRAD YELVINGTON DISTRIBUTORS INC.	B10	1	Graded Aggregate Base	**	**
TM664	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.6	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 06

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
87049	VULCAN MATERIALS COMPANY	B01	2	Limerock Base	**	**
87049	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
87089	CEMEX	B01	1	Limerock Base	7.8	132
87090	CEMEX	B01	1	Limerock Base	8.0	130
87145	TITAN AMERICA, LLC.	B01	1	Limerock Base	**	**
87339	WHITE ROCK QUARRIES	B01	1	Limerock Base	8.2	131
87541	COMMUNITY ASPHALT CORP.	B01	1	Limerock Base	8.1	133
87633	WHITE ROCK QUARRIES	B01	1	Limerock Base	**	**
87648	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	8.0	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter





# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 07

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
02018	CRYSTAL RIVER QUARRIES, INC. - LECANTO, FL	B01	2	Limerock Base	**	**
02675	CEMEX, INC. - INGLIS, FL	B01	1	Limerock Base	7.8	131
02905	CRYSTAL RIVER QUARRIES, INC.	B01	1	Limerock Base	11.9	120
08050	WEST FLORIDA AGGREGATES	B01	1	Limerock Base	13.1	115
10645	VULCAN MATERIALS COMPANY	B01	1	Limerock Base	**	**
10679	TRANSCOR RECYCLING LLC	B12	1	Recycled Concrete Base	**	**
14262	CENTRAL STATE AGGREGATES, LLC	B01	2	Limerock Base	11.5	118
15838	ANGELO'S RECYCLED MATERIALS - LARGO, FL	B12	1	Recycled Concrete Base	**	**
TM322	MARTIN MARIETTA MATERIALS	B01	1	Limerock Base	9.6	130

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter



# Pit Proctor Quarterly Report

Generated: 7/2/2024 9:11:36 AM

**Valid from 7/1/2024 to 9/30/2024**

FDOT State Materials Office, 5007 N.E. 39th Avenue, Gainesville, FL 32609 (352) 955-6600

## District: 99

Facility ID	Facility Name	Product	Process	Material Description	* Est. Opt. Moisture (%)	Pit Proctor (pcf)
AL149	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	5.9	146
AL519	VULCAN MATERIALS COMPANY	B10	1	Graded Aggregate Base	7.8	136
AL526	MARTIN MARIETTA MATERIALS	B10	1	Graded Aggregate Base	**	**
BA348	MARTIN MARIETTA AGGREGATES	B01	1	Limerock Base	9.6	130
GA553	JUNCTION CITY MINING	B10	2	Graded Aggregate Base	**	**
GA553	JUNCTION CITY MINING	B10	1	Graded Aggregate Base	6.6	143
GA753	MIDSOUTH AGGREGATES	B10	1	Graded Aggregate Base	**	**

\* Est. Optimum Moisture = Department's estimate of optimum moisture based on data from the mine

The date range used for the mine data are from: 4/1/2024 to 6/30/2024 | Reference: Section 200

\*\* Roadway Testing Required

Note: Additional Pit Proctor Sources may be added to this list up to 2 days from the start of the quarter