

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: M. Cornwell, P. Zydek, R. Jordan

Dates Cored: 1/8/20 - 1/9/20

Page: 1 of 3

Typical Section No.: 1

W.P.I. No.:	Name: SR 35	Lanes: 4
Fin. Proj. ID: 441563-1	From: Washington Loop Road	Shoulder Type and Condition: Paved
F.A. Proj. No.:	To: Desoto County Line	Inside: N
County: Charlotte SR No.: 35	Beg MP: 1.753	End MP: 4.435 Lgth: 2.682
Outside: Y	Median Curbed (Y / N): N Paved	Lawn X
Vegetation	Curb and Gutter (Y/N): N	

Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)			Base					Subgrade Stabilized	Crack				Pvmt Cond	COMMENTS	
				FC5	SP1F	SP2F	Core Length (in.)	Limerock	ABC	Shell	Concrete		SAHM	Depth (in.)	Type	Class			Extent
1	2.090	OR	N	1.0	1.6	-	2.6	5.7	-	-	-	-	-	-	-	-	-	Fair	
2	2.090	R2	Y	0.8	-	3.1	3.9	10.1	-	-	-	-	-	-	-	-	-	Fair	
3	2.090	R1	N	1.0	0.9	2.6	4.5	9.2	-	-	-	-	-	-	-	-	-	Fair	
4	2.090	L1	N	0.9	1.1	3.0	5.0	11.5	-	-	-	-	-	-	-	-	-	Fair	
5	2.090	L2	Y	0.7	-	3.6	4.3	10.3	-	-	-	-	-	-	-	-	-	Fair	
6	2.090	OL	N	0.5	-	2.1	2.6	-	1.3	-	-	-	4.4	-	-	-	-	Fair	
7	2.592	OR	N	0.8	-	1.2	2.0	4.4	-	-	-	-	-	-	-	-	-	Fair	
8	2.592	R2	N	1.0	-	3.0	4.0	10.9	-	-	-	-	-	-	-	-	-	Fair	
9	2.592	R1	Y	0.9	-	3.2	4.1	10.7	-	-	-	-	-	-	-	-	-	Fair	
10	2.592	L1	Y	0.9	-	3.5	4.4	10.0	-	-	-	-	-	-	-	-	-	Fair	
11	2.592	L2	N	0.7	0.9	2.8	4.4	11.4	-	-	-	-	-	-	-	-	-	Fair	
12	2.592	OL	N	1.3	-	1.5	2.8	-	-	-	-	-	12.2	-	-	-	-	Fair	
13	3.066	OR	N	0.7	0.9	-	1.6	4.5	-	-	-	-	-	-	-	-	-	Fair	
14	3.066	R2	Y	1.0	0.7	2.5	4.2	10.4	-	-	-	-	-	2.1	C	III	M	Poor	
15	3.066	R1	N	0.8	-	3.1	3.9	9.5	-	-	-	-	14.5	-	-	-	-	Fair	
16	3.066	L1	N	0.9	1.0	2.6	4.5	10.0	-	-	-	-	-	-	-	-	-	Fair	
17	3.066	L2	Y	0.7	-	3.5	4.2	10.3	-	-	-	-	16.0	4.2	B	III	S	Poor	Full Depth Crack
18	3.066	OL	N	0.9	-	1.8	2.7	-	-	-	-	-	16.5	-	-	-	-	Fair	
19	3.647	OR	N	0.8	1.3	-	2.1	3.5	-	-	-	-	-	-	-	-	-	Fair	
20	3.647	R2	N	0.7	-	3.2	3.9	10.1	-	-	-	-	-	-	-	-	-	Fair	
21	3.647	R1	Y	1.0	-	3.8	4.8	10.4	-	-	-	-	18.8	-	-	-	-	Fair	
22	3.647	L1	N	0.8	0.9	2.3	4.0	11.5	-	-	-	-	-	-	-	-	-	Fair	
23	3.647	L2	Y	0.8	-	3.5	4.3	10.5	-	-	-	-	21.4	1.3	B	III	L	Poor	
24	3.647	OL	N	0.8	1.6	3.8	6.2	6.7	-	-	-	-	-	-	-	-	-	Fair	
25	4.243	OR	N	1.0	-	3.4	4.4	10.3	-	-	-	-	-	-	-	-	-	Fair	
26	4.243	R2	Y	0.8	-	4.4	5.2	12.6	-	-	-	-	-	-	-	-	-	Fair	
27	4.243	R1	N	0.9	-	5.0	5.9	12.8	-	-	-	-	12.2	-	-	-	-	Fair	

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: M. Cornwell, P. Zydek, R. Jordan

Dates Cored: 1/8/20 - 1/9/20

Page: 2 of 3

Typical Section No.: 1

W.P.I. No.:	Name: SR 35	Lanes: 4
Fin. Proj. ID: 441563-1	From: Washington Loop Road	Shoulder Type and Condition: Paved
F.A. Proj. No.:	To: Desoto County Line	Inside: N
County: Charlotte SR No.: 35	Beg MP: 1.753	End MP: 4.435 Lgth: 2.682
Outside: Y	Median Curbed (Y / N): N Paved	Lawn X
Vegetation	Curb and Gutter (Y/N): N	

Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)			Core Length (in.)	Base				Subgrade Stabilized	Crack				Pvmt Cond	COMMENTS	
				FC5	SP1F	SP2F		Limerock	ABC	Shell	Concrete		SAHM	Depth (in.)	Type	Class			Extent
28	4.243	L1	Y	0.8	-	4.0	4.8	12.6	-	-	-	-	-	-	-	-	-	Fair	
29	4.243	L2	N	1.2	-	4.6	5.8	13.4	-	-	-	-	16.7	-	-	-	-	Fair	
30	4.243	OL	N	1.2	-	3.8	5.0	8.3	-	-	-	-	-	-	-	-	-	Fair	
31	2.030	R1	N	1.0	3.1	-	4.1	11.5	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
32	2.468	L1	N	1.0	-	3.8	4.8	10.2	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
33	3.176	R1	Y	1.1	1.5	2.3	4.9	9.9	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
34	3.954	L1	N	0.9	1.0	2.4	4.3	9.9	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
35	4.396	R1	Y	1.0	-	5.0	6.0	13.0	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
36	2.056	L2	Y	1.5	-	3.9	5.4	10.6	-	-	-	-	-	-	-	-	-	Fair	Sam Way
37	2.299	L2	Y	0.9	-	3.9	4.8	18.1	-	-	-	-	-	-	-	-	-	Fair	Bryan Way
38	2.428	L2	Y	0.5	2.3	1.5	4.3	17.8	-	-	-	-	-	-	-	-	-	Fair	Palm Shores Blvd.
39	2.800	L2	N	0.8	-	3.0	3.8	17.1	-	-	-	-	-	-	-	-	-	Fair	Pine Villa Cir.
40	2.924	R2	N	-	-	2.4	2.4	-	6.6	-	-	-	-	-	-	-	-	Fair	Catalpa Ave.
41	3.050	L2	N	0.8	1.1	2.9	4.8	21.0	-	-	-	-	-	-	-	-	-	Fair	Pine Villa Cir.
42	3.209	L2	N	0.7	-	2.6	3.3	18.5	-	-	-	-	-	-	-	-	-	Fair	Turbak Dr.
43	3.700	L2	N	0.6	-	3.0	3.6	7.1	-	-	-	-	-	-	-	-	-	Fair	Lillis St.
44	3.927	L2	N	0.6	0.7	3.5	4.8	2.0	-	-	-	-	-	-	-	-	-	Fair	Peace River Shores Blvd.
45	4.184	L2	N	-	-	1.7	1.7	18.0	-	-	-	-	-	-	-	-	-	Fair	Fox Tail Ln.
46	4.422	L2	N	-	-	1.6	1.6	10.8	-	-	-	-	-	-	-	-	-	Fair	Nottingham Rd.
47	3.509	L2	N	-	-	2.7	2.7	4.0	-	-	-	-	-	-	-	-	-	Fair	Driveway onto empty lot
48	3.849	L2	N	-	-	1.3	1.3	4.8	-	-	-	-	-	-	-	-	-	Fair	Driveway of Green Fern View Apartments
49	3.892	L2	N	-	-	2.3	2.3	10.5	-	-	-	-	-	-	-	-	-	Fair	Driveway of "For Sale" lot
50	4.002	L2	Y	-	-	1.9	1.9	5.1	-	-	-	-	-	-	-	-	-	Fair	Driveway of Bivens Animal Hospital
51	4.044	L2	N	-	-	4.3	4.3	8.3	-	-	-	-	-	-	-	-	-	Fair	Driveway of Business Address 207 US 17
52	3.955	L2	N	0.8	-	3.5	4.3	14.0	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane
53	3.251	L2	Y	0.9	0.5	2.1	3.5	10.4	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane
54	2.451	L2	N	0.9	-	3.5	4.4	9.0	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: M. Cornwell, P. Zydek, R. Jordan

Dates Cored: 1/8/20 - 1/9/20

Page: 3 of 3

Typical Section No.: 1

W.P.I. No.:	Name: SR 35	Lanes: 4
Fin. Proj. ID: 441563-1	From: Washington Loop Road	Shoulder Type and Condition: Paved
F.A. Proj. No.:	To: Desoto County Line	Inside: N
County: Charlotte SR No.: 35	Beg MP: 1.753	End MP: 4.435 Lgth: 2.682
Outside: Y	Median Curbed (Y/N): N Paved	Lawn X
Vegetation	Curb and Gutter (Y/N): N	

Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)			Core Length (in.)	Base					Subgrade Stabilized	Crack				Pvmt Cond	COMMENTS
				FC5	SP1F	SP2F		Limerock	A B C	Shell	Concrete	S A H M		Depth (in.)	Type	Class	Extent		
55	3.251	L2	Y	1.0	-	3.5	4.5	12.0	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane
56	2.882	L1	Y	1.0	1.4	2.6	5.0	10.4	-	-	-	-	-	-	-	-	-	Fair	
57	2.430	R2	Y	0.6	-	2.9	3.5	10.0	-	-	-	-	-	-	-	-	-	Poor	
58	2.695	R2	Y	0.8	-	3.0	3.8	12.2	-	-	-	-	1.6	B	II	M	Fair		
59	3.952	L2	Y	0.9	-	3.4	4.3	11.1	-	-	-	-	1.9	C	II	M	Poor		
60	3.383	L2	Y	1.0	0.9	2.8	4.7	10.5	-	-	-	-	1.9	B	III	M	Fair		