

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: M. Cornwell, P. Zydek, R. Jordan

Dates Cored: 1/8/20 - 1/9/20

Page: 1 of 3

Typical Section No.: 1

W.P.I. No.:	Name: SR 35	Lanes: 4
Fin. Proj. ID: 441563-1	From: Washington Loop Road	Shoulder Type and Condition: Paved
F.A. Proj. No.:	To: Desoto County Line	Inside: N
County: Charlotte SR No.: 35	Beg MP: 1.753	End MP: 4.435 Lgth: 2.682
Median Curbed (Y / N): N Paved	Lawn X	Vegetation
		Curb and Gutter (Y/N): N

Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)			Base					Subgrade	Crack				Pvmt Cond	COMMENTS	
				FC5	SP1F	SP2F	Core Length (in.)	Limerock	A B C	Shell	Concrete		S A H M	Stabilized	Depth (in.)	Type			Class
1	2.090	OR	N	1.0	1.6	-	2.6	5.7	-	-	-	-	-	-	-	-	-	Fair	
2	2.090	R2	Y	0.8	-	3.1	3.9	10.1	-	-	-	-	-	-	-	-	-	Fair	
3	2.090	R1	N	1.0	0.9	2.6	4.5	9.2	-	-	-	-	-	-	-	-	-	Fair	
4	2.090	L1	N	0.9	1.1	3.0	5.0	11.5	-	-	-	-	-	-	-	-	-	Fair	
5	2.090	L2	Y	0.7	-	3.6	4.3	10.3	-	-	-	-	-	-	-	-	-	Fair	
6	2.090	OL	N	0.5	-	2.1	2.6	-	1.3	-	-	-	4.4	-	-	-	-	Fair	
7	2.592	OR	N	0.8	-	1.2	2.0	4.4	-	-	-	-	-	-	-	-	-	Fair	
8	2.592	R2	N	1.0	-	3.0	4.0	10.9	-	-	-	-	-	-	-	-	-	Fair	
9	2.592	R1	Y	0.9	-	3.2	4.1	10.7	-	-	-	-	-	-	-	-	-	Fair	
10	2.592	L1	Y	0.9	-	3.5	4.4	10.0	-	-	-	-	-	-	-	-	-	Fair	
11	2.592	L2	N	0.7	0.9	2.8	4.4	11.4	-	-	-	-	-	-	-	-	-	Fair	
12	2.592	OL	N	1.3	-	1.5	2.8	-	-	-	-	-	12.2	-	-	-	-	Fair	
13	3.066	OR	N	0.7	0.9	-	1.6	4.5	-	-	-	-	-	-	-	-	-	Fair	
14	3.066	R2	Y	1.0	0.7	2.5	4.2	10.4	-	-	-	-	-	2.1	C	III	M	Poor	
15	3.066	R1	N	0.8	-	3.1	3.9	9.5	-	-	-	-	14.5	-	-	-	-	Fair	
16	3.066	L1	N	0.9	1.0	2.6	4.5	10.0	-	-	-	-	-	-	-	-	-	Fair	
17	3.066	L2	Y	0.7	-	3.5	4.2	10.3	-	-	-	-	16.0	4.2	B	III	S	Poor	Full Depth Crack
18	3.066	OL	N	0.9	-	1.8	2.7	-	-	-	-	-	16.5	-	-	-	-	Fair	
19	3.647	OR	N	0.8	1.3	-	2.1	3.5	-	-	-	-	-	-	-	-	-	Fair	
20	3.647	R2	N	0.7	-	3.2	3.9	10.1	-	-	-	-	-	-	-	-	-	Fair	
21	3.647	R1	Y	1.0	-	3.8	4.8	10.4	-	-	-	-	18.8	-	-	-	-	Fair	
22	3.647	L1	N	0.8	0.9	2.3	4.0	11.5	-	-	-	-	-	-	-	-	-	Fair	
23	3.647	L2	Y	0.8	-	3.5	4.3	10.5	-	-	-	-	21.4	1.3	B	III	L	Poor	
24	3.647	OL	N	0.8	1.6	3.8	6.2	6.7	-	-	-	-	-	-	-	-	-	Fair	
25	4.243	OR	N	1.0	-	3.4	4.4	10.3	-	-	-	-	-	-	-	-	-	Fair	
26	4.243	R2	Y	0.8	-	4.4	5.2	12.6	-	-	-	-	-	-	-	-	-	Fair	
27	4.243	R1	N	0.9	-	5.0	5.9	12.8	-	-	-	-	12.2	-	-	-	-	Fair	

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: M. Cornwell, P. Zydek, R. Jordan

Dates Cored: 1/8/20 - 1/9/20

Page: 2 of 3

Typical Section No.: 1

W.P.I. No.:	Name: SR 35	Lanes: 4
Fin. Proj. ID: 441563-1	From: Washington Loop Road	Shoulder Type and Condition: Paved
F.A. Proj. No.:	To: Desoto County Line	Inside: N
County: Charlotte SR No.: 35	Beg MP: 1.753	End MP: 4.435 Lgth: 2.682
Outside: Y	Median Curbed (Y / N): N Paved	Lawn X
Vegetation	Curb and Gutter (Y/N): N	

Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)			Core Length (in.)	Base				Subgrade	Crack				Pvmt Cond	COMMENTS	
				FC5	SP1F	SP2F		Limerock	A B C	Shell	Concrete		S A H M	Stabilized	Depth (in.)	Type			Class
28	4.243	L1	Y	0.8	-	4.0	4.8	12.6	-	-	-	-	-	-	-	-	-	Fair	
29	4.243	L2	N	1.2	-	4.6	5.8	13.4	-	-	-	-	16.7	-	-	-	-	Fair	
30	4.243	OL	N	1.2	-	3.8	5.0	8.3	-	-	-	-	-	-	-	-	-	Fair	
31	2.030	R1	N	1.0	3.1	-	4.1	11.5	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
32	2.468	L1	N	1.0	-	3.8	4.8	10.2	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
33	3.176	R1	Y	1.1	1.5	2.3	4.9	9.9	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
34	3.954	L1	N	0.9	1.0	2.4	4.3	9.9	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
35	4.396	R1	Y	1.0	-	5.0	6.0	13.0	-	-	-	-	-	-	-	-	-	Fair	Left Turn Lane
36	2.056	L2	Y	1.5	-	3.9	5.4	10.6	-	-	-	-	-	-	-	-	-	Fair	Sam Way
37	2.299	L2	Y	0.9	-	3.9	4.8	18.1	-	-	-	-	-	-	-	-	-	Fair	Bryan Way
38	2.428	L2	Y	0.5	2.3	1.5	4.3	17.8	-	-	-	-	-	-	-	-	-	Fair	Palm Shores Blvd.
39	2.800	L2	N	0.8	-	3.0	3.8	17.1	-	-	-	-	-	-	-	-	-	Fair	Pine Villa Cir.
40	2.924	R2	N	-	-	2.4	2.4	-	6.6	-	-	-	-	-	-	-	-	Fair	Catalpa Ave.
41	3.050	L2	N	0.8	1.1	2.9	4.8	21.0	-	-	-	-	-	-	-	-	-	Fair	Pine Villa Cir.
42	3.209	L2	N	0.7	-	2.6	3.3	18.5	-	-	-	-	-	-	-	-	-	Fair	Turbak Dr.
43	3.700	L2	N	0.6	-	3.0	3.6	7.1	-	-	-	-	-	-	-	-	-	Fair	Lillis St.
44	3.927	L2	N	0.6	0.7	3.5	4.8	2.0	-	-	-	-	-	-	-	-	-	Fair	Peace River Shores Blvd.
45	4.184	L2	N	-	-	1.7	1.7	18.0	-	-	-	-	-	-	-	-	-	Fair	Fox Tail Ln.
46	4.422	L2	N	-	-	1.6	1.6	10.8	-	-	-	-	-	-	-	-	-	Fair	Nottingham Rd.
47	3.509	L2	N	-	-	2.7	2.7	4.0	-	-	-	-	-	-	-	-	-	Fair	Driveway onto empty lot
48	3.849	L2	N	-	-	1.3	1.3	4.8	-	-	-	-	-	-	-	-	-	Fair	Driveway of Green Fern View Apartments
49	3.892	L2	N	-	-	2.3	2.3	10.5	-	-	-	-	-	-	-	-	-	Fair	Driveway of "For Sale" lot
50	4.002	L2	Y	-	-	1.9	1.9	5.1	-	-	-	-	-	-	-	-	-	Fair	Driveway of Bivens Animal Hospital
51	4.044	L2	N	-	-	4.3	4.3	8.3	-	-	-	-	-	-	-	-	-	Fair	Driveway of Business Address 207 US 17
52	3.955	L2	N	0.8	-	3.5	4.3	14.0	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane
53	3.251	L2	Y	0.9	0.5	2.1	3.5	10.4	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane
54	2.451	L2	N	0.9	-	3.5	4.4	9.0	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: M. Cornwell, P. Zydek, R. JordanDates Cored: 1/8/20 - 1/9/20Page: 3 of 3Typical Section No.: 1

W.P.I. No.:	Name: SR 35	Lanes: 4
Fin. Proj. ID: 441563-1	From: Washington Loop Road	Shoulder Type and Condition: Paved
F.A. Proj. No.:	To: Desoto County Line	Inside: N
County: Charlotte SR No.: 35	Beg MP: 1.753	End MP: 4.435 Lgth: 2.682
Outside: Y	Median Curbed (Y/N): N Paved	Lawn X
Vegetation	Curb and Gutter (Y/N): N	

Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Pavement Layer (in.)			Core Length (in.)	Base				Subgrade	Crack				Pvmt Cond	COMMENTS	
				FC5	SP1F	SP2F		Limerock	A B C	Shell	Concrete		S A H M	Stabilized	Depth (in.)	Type			Class
55	3.251	L2	Y	1.0	-	3.5	4.5	12.0	-	-	-	-	-	-	-	-	-	Fair	Right Turn Lane
56	2.882	L1	Y	1.0	1.4	2.6	5.0	10.4	-	-	-	-	-	-	-	-	-	Fair	
57	2.430	R2	Y	0.6	-	2.9	3.5	10.0	-	-	-	-	-	-	-	-	-	Poor	
58	2.695	R2	Y	0.8	-	3.0	3.8	12.2	-	-	-	-	1.6	B	II	M	Fair		
59	3.952	L2	Y	0.9	-	3.4	4.3	11.1	-	-	-	-	1.9	C	II	M	Poor		
60	3.383	L2	Y	1.0	0.9	2.8	4.7	10.5	-	-	-	-	1.9	B	III	M	Fair		