

STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION
PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: Shannon Davidson Date: 10/28/19 Page of Typical Section No.: ---

W.P.I. No.:		Name: SR 33 Lakeland Hills Blvd at Carol Dr.				Lanes: 10	
Fin. Proj. ID: 440684-1-52-01		From: Lake Cargo Dr				Shoulder Type and Condition:	
F.A. Proj. No.:		To: Arbor Hills				Inside: Paved, Good	
County: Polk	SR No.: 33	Beg MP: 3.094	End MP: 3.598	Lgth: 0.504	Outside: Paved, Good		
Median Curbed (Y / N): N		Other:				Curb & Gutter (Y / N): N	

Core No.	MP	Lane	W h e e l	Pavement Layer (in.)						Base (in.)		Crack				P C v o m n t d	Comments
				FC125	S				Core Lgth (in.)	LIMEROCK	STAB	D e p t h (in.)	T y p e	C l a s s	E x t e n t		
3	3.42	L1	N	1.5	2.5	-	-	-	4.0	10.0	12.0	-	-	-	-	F	
1	3.28	R1	N	1.5	1.9	-	-	-	3.4	10.0	12.0	-	-	-	-	F	RITL Left Turn Lane
2	3.28	R1	N	1.5	2.0	-	-	-	3.5	10.0	12.0	-	-	-	-	F	