

State of Florida Department of Transportation
PAVEMENT EVALUATION CORING AND CONDITION DATA SHEET

675-030-09
Materials

Cored/Logged By: PR Young, Kevin Olds, Rhonda Hale Date: 6/7/2022 Page: 1 of 1 Typical Section No.: 1

| | | | | | | |
|--------------------------|---------------|-----------|--------------------------------------|---------|-------|--|
| Roadway Section: | 38040000 | Name: | SR 55 (US 221) (S Jefferson St) | | | Lanes: 4 |
| FIN Project ID: | 210899-3 | From: | From SR 30 (US 19) Byron Butler Pkwy | | | Shoulder Type and Condition: G / F / P |
| Federal Project No.: | N/A | To: | To Jones Street | | | Inside: |
| County: Taylor | SR No.: SR 55 | Begin MP: | 0.010 | End MP: | 0.352 | Length: 0.342 |
| Median Curbed (Y / N): Y | (X) Paved | () Lawn | Other: | | | Outside: |
| | | | | | | Curb & Gutter (Y / N): Y |

| CORE NO. | MILE POST | LANE | WHEEL PATH (Y or N) | PAVEMENT LAYER (in.) | | | | | | | BASE | | CRACK | | | PAVT. COND. | RUT DEPTH (in.) | CROSS SLOPE (%) | SLOPE DIRECTION (I=in / O=out) | COMMENTS | | |
|----------|-----------|-------|---------------------|----------------------|-----|-----|--|--|--|--|-------------------|------|-----------------|-------------|------|-------------|-----------------|-----------------|--------------------------------|----------|-------|------------------------------------|
| | | | | FC 12.5 | T-1 | T-S | | | | | CORE LENGTH (in.) | TYPE | THICKNESS (in.) | DEPTH (in.) | TYPE | | | | | | CLASS | EXTENT |
| 1 | 0.151 | R1 | N | 1.5 | | 1.7 | | | | | 3.2 | LR | 9.3 | 3.2 | B | II | M | P | | | | BASE CHECK, SPALLING |
| 2 | 0.254 | R1 | Y | 1.5 | | 2.4 | | | | | 3.9 | LR | - | 1.5 | B | II | M | P | | | | SPALLING |
| 3 | 0.364 | R1 | Y | 1.4 | | 3.0 | | | | | 4.4 | LR | - | 4.4 | B | III | M | P | | | | SPALLING |
| 4 | 0.065 | R2 | Y | 1.2 | 3.4 | | | | | | 4.6 | LR | - | 4.6 | B | III | M | P | | | | SPALLING |
| 5 | 0.208 | R2 | Y | 1.5 | | 2.5 | | | | | 4.0 | LR | - | 4.0 | B | III | M | P | | | | SPALLING |
| 6 | 0.300 | R2 | Y | 1.7 | | 2.5 | | | | | 4.2 | LR | 10.6 | - | - | - | - | F | | | | BASE CHECK |
| 7 | 0.137 | L2 | N | 1.3 | | 2.3 | | | | | 3.6 | LR | - | 2.1 | B | II | M | P | | | | MINOR CRACKING |
| 8 | 0.250 | L2 | Y | 1.5 | | 2.8 | | | | | 4.3 | LR | - | 2.3 | B | III | M | P | | | | SPALLING, SHOING |
| 9 | 0.353 | L2 | N | 1.2 | | 2.1 | | | | | 3.3 | LR | 12.2 | - | - | - | - | F | | | | BASE CHECK |
| 10 | 0.117 | L1 | Y | 1.2 | | 2.5 | | | | | 3.7 | LR | - | 3.7 | B | III | M | P | | | | SPALLING |
| 11 | 0.200 | L1 | Y | 1.3 | | 2.4 | | | | | 3.7 | LR | - | 3.7 | B | III | M | P | | | | SPALLING |
| 12 | 0.303 | L1 | Y | 1.4 | | 2.4 | | | | | 3.8 | LR | 9.4 | - | B | II | M | P | | | | BASE CHECK, SPALLING |
| 13 | 0.031 | RTO | - | | | | | | | | | | | | | | | | | | | AT E PARK ST, OMITTED IN THE FIELD |
| 14 | 0.125 | LLTTL | N | 2.2 | | 1.5 | | | | | 3.7 | LR | - | - | - | - | - | F | | | | AT ENTRANCE TO GOODWILL |
| 15 | 0.283 | LTO | N | 1.4 | 1.4 | | | | | | 2.8 | LR | - | - | - | - | - | F | | | | AT SIDE STREET WITH NO NAME |
| 16 | 0.272 | RLTTL | N | 1.7 | | 1.9 | | | | | 3.6 | LR | - | - | - | - | - | F | | | | AT SAXON ST |

REMARKS:
LR = LIME ROCK