

Pavement Evaluation Coring and Condition Data

Cored By: D2 Materials				Date: 05/14/24		Page 1 of 2											
Project No.: 208203-3				Name: SR 230						Lanes: 2							
State Road No.: SR230				From: Bradford C/L						Shoulders							
County: Clay				To: SR 16						Inside: N/A							
Section No: 7108000 / 71080001				Beg MP: 0.000		End MP: 3.518		Length: 3.518		Outside: 4' Paved							

Core Number	Mile Post	Lane	Wheel Path	<div style="display: flex; align-items: center;"> ← <div style="border: 1px solid black; padding: 2px 5px;">Top</div> <div style="margin-left: 5px;">Pavement Layer</div> </div>						Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:
				FC-4	S-1	T-1	ST	Depth	Type			Class	Extent							
1	0.010	R1	I	1.4	2.0		0.3		3.7	LR	2.5	B	II	M	P				Transverse Crack, Spalling, Shoving	
2	0.500	R1	O	1.3	1.4	3.0	0.5		6.2	LR=8.1"	0.6	B	IB	M	P				Shoving	
3	1.000	R1	N	1.2	1.4	2.0	0.5		5.1	LR	0.5	B	IB	M	P				Shoving, Spalling	
4	1.500	R1	O	1.5	2.0				3.5	LR	0.4	B	II	M	P				Shoving, Spalling, Curve	
5	2.000	R1	N	1.2	2.7				3.9	LR	1.2	B	II	M	P				Shoving, Spalling, Curve	
6	2.500	R1	O	1.3	2.0		0.1		3.4	LR=9.2"	3.4	B	II	M	P				Transverse Crack, Shoving	
7	3.000	R1	N	1.1	3.1		0.5		4.7	LR	1.0	B	IB	M	P				Shoving, Spalling	
8	3.500	R1	O	0.7	2.2				2.9	LR	2.9	B	II	M	P				SR	
9	0.330	L1	I	1.0	2.8	0.3			4.1	LR	1.8	B	II	M	P				SR	
10	0.700	L1	O	1.1	2.3		0.5		3.9	LR	3.9	B	II	M	P				Shoving, Spalling	
11	1.300	L1	O	1.7	1.3				3.0	LR	3.0	B	II	M	P				Shoving, Spalling	
12	1.700	L1	I	1.0	1.1	1.2			3.3	LR=7.7"	0.8	B	II	M	P				Shoving, Spalling, Curve	
13	2.300	L1	N	1.0	2.5	2.5	0.5		6.5	LR	2.2	B	II	M	P				Shoving, Spalling	
14	2.700	L1	I	1.1	2.0	2.0	0.4		5.5	LR	2.1	B	II	M	P				Shoving, Spalling	
15	3.244	L1	N	1.4	2.9		0.3		4.6	LR	2.0	B	IB	L	F					
16	0.500	OR	N	1.3					1.3	LR					F					
17	1.500	OR	N	1.5					1.5	LR=5.5"					F				Curve	
18	2.500	OR	N	1.3					1.3	LR=4.9"					F					
19	1.300	OL	N	0.9					0.9	LR=4.8"	0.9	S	IB	L	F					
20	2.300	OL	N	1.0					1.0	LR					F					

Remarks: SR= Slightly Ravel

Pavement Evaluation Coring and Condition Data																					
Cored By: D2 Materials									Date: 05/14/24				Page 2 of 2								
Project No.: 208203-3									Name: SR 230							Lanes: 2					
State Road No.: SR230									From: Bradford C/L							Shoulders					
County: Clay									To: SR 16							Inside: N/A					
Section No: 71080000 / 71080001									Beg MP: 0.000			End MP: 3.518			Length: 3.518			Outside: 4' Paved			
Core Number	Mile Post	Lane	Wheel Path	<div><div>← Top</div>Pavement Layer</div>						Core Length	Base Type	Crack				Pavement Condition	Rut Depth (inches)	Cross Slope (%)	Slope Direction (in / out)	Comments:	
				FC-3	T-1	ST						Depth	Type	Class	Extent						
21	3.244	OL	N	1.3					1.3	LR					F						
29	2.058	RTO	N	1.2	2.1				3.3	LR	1.1	B	II	M	P				Chemours Ent, Shoving		
30	2.806	RTO	N	1.0					1.0	LR	1.0	B	IB	L	P				Johnson Ave.		
SR 230 On Ramp SB fr. SR 16 (Measured from shoulder pvt change)																					
22	3.063	RP	O	1.9	2.9				4.8	LR=10.2"	0.2	S	IB	L	F						
24	3.063	OL	N	1.3					1.3	LR=4.8"					F						
71080001 SR230 On/Off Ramp																					
25	0.138	R1	O	1.1	1.3				2.4	LR=8.1"	2.4	B	II	M	P				Spalling		
26	0.098	L1	O	1.3	0.9	0.3			2.5	LR	2.5	S	IB	L	F				Transverse Crack, Curve		
27	0.138	OR	N	1.8					1.8	LR											
28	0.098	OL	N	1.0	1.3				2.3	LR											
Remarks: _____ _____																					